

Vehicle History Report #: 53482350 Report Date: May 21, 2024 | 6:12 PM EDT

Report Status: Complete

2015 NISSAN ROGUE S

Sport utility vehicle | 4 Cylinders | Gas 5N1AT2MV5FC825726 Country of Assembly: United States Last Reported Odometer: 151,767 KM

CARFAX





Last Registered In: 2 Service Records Found
Ontario (Normal)







Not Actively Declared Stolen




No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 21, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS	AMOUNT
9 2019 Feb 27	Ontario, Canada	
	Estimate Estimate Date: 2019 Feb 27	\$3,277.23
	Claim: Other Damage	\$3,277.00
0 2021 Mar 28	Ontario, Canada	
	Police Reported Accident: Accident reported: severe damage	
	Vehicle involved in a rear-end collision	
	with another motor vehicle	
	Damage to right rear	
	Vehicle towed	
	Estimate Estimate Date: 2021 Mar 28	\$7,244.59
	Claim: Other Damage	\$150.00
D 2023 Jul 18	North York, Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage	
	Involving front or side impact	
	with another motor vehicle	
	Damage to left front	
	Estimate: Not Available Estimate Date: 2023 Jul 28	\$9,447.56
	Estimate: Total Loss Estimate Date: 2023 Aug 17	\$18,989.39
	Claim: Other Damage	\$13,936.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
① 2019 Mar 5	n/a	
	Damage Event: Damage reported: minor damage Damage to front Damage to left front	



We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2015 Feb 27		MILTON NISSAN Milton, Ontario, Canada	Vehicle serviced Pre-delivery inspection completed	
2018 Dec 18	82,487 KM	Mike & The Mechanic	Vehicle serviced	
		Brampton, Ontario, Canada	 Rear brake pads replaced 	
			 Front brake pads replaced 	
			 Rear brake rotor(s) replaced 	
			 Front brake rotor(s) replaced 	
			 Drivability/performance checked 	
			Brakes checked	



Recall #: R21B9 | ROUGE WIRE HARNESS NTB22-076 Recall Date: 2022 Jan 25

Recall Description

IN AFFECTED VEHICLES, IF WATER AND SALT COLLECT IN THE DRIVER S SIDE FOOT WELL, IT MAY WICK UP THE DASH SIDE HARNESS TAPE AND ENTER THE CONNECTOR. IF THIS OCCURS, THE DASH SIDE HARNESS CONNECTOR MAY CORRODE AND POSSIBLY CAUSE ISSUES SUCH AS DRIVER S POWER WINDOW OR POWER SEAT INOPERATIVE, ALL-WHEEL DRIVE (AWD) WARNING LIGHT ON, BATTERY DISCHARGE, AND/OR THERMAL DAMAGE TO THE CONNECTOR. IN RARE CASES, THE CORROSION COULD POTENTIALLY LEAD TO A FIRE, WHICH MAY INCREASE RISK OF INJURY.

Remedy

YOUR NISSAN DEALER WILL INSPECT YOUR VEHICLE AND PERFORM THE APPROPRIATE REPAIR 1) IF CORROSION IS PRESENT ON EITHER THE MAIN HARNESS OR THE BODY HARNESS CONNECTORS, THE DEALER WILL REMOVE THE HARNESS TAPE AND HARNESS COVERING, REPLACE BOTH CONNECTORS AND APPLY WHITE LITHIUM GREASE TO THE CONNECTORS 2) IF CORROSION IS NOT PRESENT ON EITHER OF THE CONNECTORS, THE DEALER WILL REMOVE THE HARNESS TAPE AND HARNESS COVERING AND APPLY WHITE LITHIUM GREASE TO THE CONNECTORS. THIS SERVICE WILL BE CONDUCTED AT NO CHARGE TO YOU FOR PARTS AND LABOR, AND MAY TAKE UP TO TWO (2) HOURS TO COMPLETE IF YOUR HARNESS CONNECTORS REQUIRE REPLACEMENT. HOWEVER, YOUR NISSAN DEALER MAY REQUIRE YOUR VEHICLE FOR A LONGER PERIOD OF TIME BASED UPON THEIR WORK SCHEDULE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website.

Recall #: R22C9 | ROGUE MCH KEY SPCR NTB23-068 Recall Date: 2023 Aug 24

Recall Description

CERTAIN 2014-2020 ROGUE AND 2017-2022 ROGUE SPORT VEHICLES ARE EQUIPPED WITH A JACKKNIFE KEY THAT MAY NOT HOLD THE KEY BLADE IN THE EXTENDED OPEN POSITION. OVER TIME THE INTERNAL PIVOT OF THE JACKKNIFE KEY MAY WEAKEN AND THE KEY COULD UNLOCK AND ROTATE DOWNWARDS.

Remedy

THE FINAL REMEDY IS NOW AVAILABLE. THE DEALER WILL INSERT A SPACER INTO THE KEY BLADE STORAGE SLOT OF THE FOB SO THE KEY BLADE IS IN THE EXTENDED OPEN POSITION AND CANNOT BE FOLDED DOWN. OWNERS SHOULD BRING ALL KEYS AND FOBS FOR THE AFFECTED VEHICLE WITH THEM TO THE DEALERSHIP WHEN HAVING THE REMEDY PERFORMED, AS THE REMEDY WILL RESULT IN DEACTIVATION OF ANY KEYS AND FOBS THAT ARE NOT REGISTERED AT THE TIME OF REPAIR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Feb 27		MILTON NISSAN Milton, Ontario, Canada	Service Record	Vehicle serviced
2015 May 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as silver
2016 Jan 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Jan 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Jan 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Dec 18	82,487 KM	Mike & The Mechanic Brampton, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Feb 27		Insurance Records Ontario, Canada		
2019 Feb 27	87,757 KM	Insurance Records	Estimate Repair	Estimate Date: 2019-02-27
2019 Mar 5			Damage Event	Damage reported: minor damage Damage to front Damage to left front
2020 Jan 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Jan 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Mar 28		Police Reported Accident Ontario, Canada	Police Report	Accident Reported:
2021 Mar 28		Insurance Records Ontario, Canada		
2021 Mar 28	139,844 KM	Insurance Records	Estimate Repair	Estimate Date: 2021-03-28
2021 May 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as silver
2022 Jan 25		NISSAN	Recall	Manufacturer Recall Issued Recall # R21B9
2023 Mar 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as silver
2023 Jul 18		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: minor damage Involving front or side impact with another motor vehicle Damage to left front
2023 Jul 18		Insurance Records Ontario, Canada		
2023 Jul 18		Insurance Records North York, Ontario, Canada	Estimate Repair	Estimate Date: 2023-07-28 Not Available
2023 Jul 18	151,767 KM	Insurance Records London, Ontario, Canada	Estimate Repair	Estimate Date: 2023-08-17 Total Loss
2023 Aug 24		NISSAN	Recall	Manufacturer Recall Issued Recall # R22C9
2023 Aug 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as silver
2024 Jan 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as silver



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information there discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

