

2016 VOLKSWAGEN GOLF S/SE

Hatchback | 4 Cylinders | Gas 3VW217AUXGM058234 Country of Assembly: Mexico Last Reported Odometer: 128,712 KM

Low Kilometres™ >





Last Registered In: Ontario (Normal)



14 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at ${\it support.carfax.ca}$



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 24, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS	AMOUNT
9 2024 Jul 4	Jerseyville, Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage	
	with another motor vehicle	
	Damage to left front	
	Vehicle towed	
	Estimate: Total Loss Estimate Date: 2024 Jul 12	\$16,595.50



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 May 3		Roseland Volkswagen	Vehicle serviced
		Burlington, Ontario, Canada	Pre-delivery inspection completed
2016 Aug 30		Maple Volkswagen	Vehicle serviced
		Maple, Ontario, Canada	Pre-delivery inspection completedVehicle washed/detailed
2017 May 5	7,211 KM	Maple Volkswagen	Vehicle serviced
		Maple, Ontario, Canada	Maintenance inspection completed
		• , , ,	 Vehicle washed/detailed
			 Fluids checked
			Oil and filter changed
			Tire condition and pressure checked
2017 Jun 8 7,300 KM		Maple Volkswagen	Vehicle serviced
		Maple, Ontario, Canada	 Vehicle washed/detailed
			Tire(s) replaced
2018 Jun 19	24,409 KM	Maple Volkswagen	Vehicle serviced
		Maple, Ontario, Canada	Maintenance inspection completed
		, -,,	Vehicle washed/detailed
			 Fluids checked
			Oil and filter changed
			 Tire condition and pressure checked
			 Wiper(s) replaced
			 Cabin air filter replaced/cleaned

	ODOMETER	SOURCE	DETAILS
2019 Jan 18	33,190 KM	Maple Volkswagen Maple, Ontario, Canada	Vehicle serviced Maintenance inspection completed Fluids checked Oil and filter changed Tire condition and pressure checked Vehicle washed/detailed Drive belt(s) replaced Cooling system checked Drivability/performance checked Thermostat replaced
2019 Mar 25		Pfaff Volkswagen Newmarket, Ontario, Canada	Vehicle serviced Pre-delivery inspection completed Maintenance inspection completed Oil and filter changed Fluids checked Safety inspection performed Vehicle washed/detailed
2019 Nov 16	41,296 KM	Volkswagen Downtown Toronto Toronto, Ontario, Canada	Vehicle serviced
2020 Jul 23		Pfaff Volkswagen Newmarket, Ontario, Canada	Vehicle serviced Pre-delivery inspection completed Maintenance inspection completed Oil and filter changed Fluids checked Safety inspection performed Vehicle washed/detailed Four tires balanced
2020 Jul 31		Pfaff Volkswagen Newmarket, Ontario, Canada	Vehicle serviced • Vehicle washed/detailed
2021 Sep 3	76,270 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced • Fluids checked • Oil and filter changed • Tire condition and pressure checked • Exterior lights checked
2023 Jan 6	103,101 KM	Westown Auto Signature Hamilton, Ontario, Canada	Vehicle serviced
2023 Jun 26	110,377 KM	Locke Street Tire & Automotive Hamilton, Ontario, Canada	Vehicle serviced • Tire repaired
2023 Jul 8	111,499 KM	Active Green & Ross Hamilton, Ontario, Canada	Vehicle serviced • Battery replaced



Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

REPAIR NOT YET AVAILABLE

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website. (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 May 3		Roseland Volkswagen Burlington, Ontario, Canada	Service Record	Vehicle serviced
2016 Aug 30		Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2016 Sep 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black
2017 Mar 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 May 5	7,211 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2017 Jun 8	7,300 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2018 Mar 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Jun 19	24,409 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 18	33,190 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 22	35,135 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2019 Mar 25		Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 Apr 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2019 Nov 16	41,296 KM	Volkswagen Downtown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Jul 21	46,268 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2020 Jul 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2020 Jul 23		Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2020 Jul 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2020 Jul 31		Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2021 Sep 3	76,270 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Sep 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2022 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2023 Jan 6	103,101 KM	Westown Auto Signature Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 26	110,377 KM	Locke Street Tire & Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2023 Jul 8	111,499 KM	Active Green & Ross Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Jul 4		Police Reported Accident Ontario, Canada	Police Report	Accident Reported:
2024 Jul 12	128,712 KM	Insurance Records Jerseyville, Ontario, Canada	Estimate Repair	Incident Date: 2024-07-04 Total Loss



CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres[™] badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres[™] badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablity, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

