



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70155

Station Name: Pro Certified Auto Service Inc

Technician #: 89835

Technician Name: Colton Lavoie

Signing Officer #: 91708

Signing Officer Name: Sharon Silzer

Customer Details:

Name: 3J Motors Inc

Address: 703 Winnipeg Street, Regina, Saskatchewan, S4R1H9

Vehicle Details:

VIN: JNKBV61F18M256229

Odometer Reading: 212929 km

Year: 2008

Vehicle Make/Model: INFINITI G35X 4DR AWD

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (5&8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (5)	
x				Windshield Defroster/Heater (5)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Floor/Step Well Covering (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (4)	

x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	
		x		Doors (8)	both front outside door handles loose

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	left headlight assembly, plate light assembly not secure
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Hybrid Vehicle Drive Systems (1)	
		x		Unitized Body Elements (8)	front cradel support rusted through

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Hood Safety Catches (8)	
		x		Power Steering System (4)	rack leaking
x				Fuel System (1)	
x				Alternator/Battery/Wiring (7)	
x				Drive Belts (1)	
x				Fluid Levels (3&4)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3)	
x				Wheel Bearings (9)	
		x		King Pins/Ball Joints (4)	both lower ball joints
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	left front axle
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	
x				Computer Control Suspension (2)	
x				Shock Absorbers & Strut Assemblies (2)	

x				Wheel Seal Leaks (3&9)	
x				Disc Brake Components (3)	
x				Drum Brake Components (3)	
x				Anti-Lock Brakes (3)	

Pass	Rejected	Corrected	Req Attn	WHEEL ALIGNMENT	Comments
		x		Front Wheel Alignment (4)	parts required
		x		Rear Wheel Alignment (4)	parts required

Brake/Tire Measurements

**Axle 1-Pass**

Wheel1-Off : Tire Tread Depth: 8 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 10 in • Brake Drum/Rotor: 1.107 in

Wheel2-Off : Tire Tread Depth: 8 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 10 in • Brake Drum/Rotor: 1.108 in

**Axle 2-Pass**

Wheel1-Off : Tire Tread Depth: 8 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 8 in • Brake Drum/Rotor: .651 in

Wheel2-Off : Tire Tread Depth: 8 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 8 in • Brake Drum/Rotor: .653 in

PASS - vehicle passes inspection	Decal # A115166	Inspection Completed Date: 24Jul2024
----------------------------------	-----------------	--------------------------------------

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.