SO# B204530

Visual 40 Point Inspection

Contact	3j Motors
VIN	WVGLE67L77D001378

TechTyler JesseVehicle2007 VOLKSWAGEN TOUAREG

Completed Date Odom 09/25/2024 239467

Visual Inspection

Inspect Horn Operation	
Works: No	
Inspect Heat/Defrost Inspection	
Inspect Instrument Cluster/Interior Lights	
Inspect Seatbelt Operation and Condition	
Inspect Mirrors	
Inspect Windshield	
Inspect Wipers and Operation	
Inspect Floor Mat Condition at Accelerator	
Inspect Vehicle for Spare Tools	
: No	
Inspect all Doors and Latches for Operation	
Inspect all Exterior Lights	
Inspect Seat Operation	
DF: No	
RF: No	
Rear: No	
Inspect Block Heater and Cord, Check for	
Operation	
Inspect Alternator	
Output:	
Volts:	
Amps:	
Inspect all Engine Wiring and Connectors	
Inspect Spark Plug Condition/Pull 1 Plug	
Inspect Cooling System and Coolant Strength	
Strength:	
Inspect all Hoses	
Inspect Rad Condition	
Inspect Water Pump abd Thermostat for Leaks	
Inspect Air filter	
Inspect PCV Operation	
Inspect Hood Latch Operation	
Inspect All Fluid Levels and Condition	
Inspect Belts, Tensioner and Idler	
Inspect Tires	
LF: 8	
RF: 8	
LR: 8	
RR: 8	
Inspect Rims	
Inspect Wheel Bearings for Adjustment/Noise	
Inspect Brakes and Measure Pads	
LF: 7	
RF: 7	
LR: 8	
RR: 8	
Inspect Brake Hoses	
Visual Inspection of Steering Linkage	
Inspect CV Axle Boots	
Inspect Exhaust System	
Inspect Engine oil and Power Steering Leaks	
Visual Inspection of Fuel Tank and Lines for	
Leaks	
Inspect Engine/Trans Mounts	
Inspect Body Condition	