

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71973

Station Name: Extra Mile Auto Repair Ltd.

Technician #: 91729

Technician Name: Gurwinder Singh Saggu

Signing Officer #: 91913

Signing Officer Name: Jatinder Singh

**Customer Details:**

Name: 3J MOTORS

Address: 703 WINNIPEG STREET, REGINA, Saskatchewan, S4R 1H9

**Vehicle Details:**

VIN: JA32U2FU0CU610477

Odometer Reading: 177221 km

Year: 2012

Vehicle Make/Model: MITSUBISHI LANCER ES

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (5&8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (5)	
x				Windshield Defroster/Heater (5)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Floor/Step Well Covering (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
		x		Speedometer/Odometer (5)	FIXED ABS SIGN AND TRACTION LIGHT ISSUE
x				Steering Lash/Travel (4)	

x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	
x				Doors (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	REPLACED ALL MARKER BULBS
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
		x		Body/Bumpers (8)	FIXED REAR BUMPER
x				Trailer Hitch (10)	
x				Cargo Bodies/Vessels (8)	
		x		Mud Flaps/Fenders (8)	REPLACED FRONT LHS INNER FENDER LINER
x				Trailer Power Cord (7)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Hood Safety Catches (8)	
x				Power Steering System (4)	
		x		Fuel System (1)	REPLACED GAS TANK
x				Alternator/Battery/Wiring (7)	
x				Drive Belts (1)	
x				Fluid Levels (3&4)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
		x		Tires/Wheels (9)	REPLACED FRONT LHS TIRE AND REAR RHS TIRE
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	

x			Wheel Seal Leaks (3&9)	
		x	Disc Brake Components (3)	
x			Drum Brake Components (3)	
x			Anti-Lock Brakes (3)	

Pass	Rejected	Corrected	Req Attn	WHEEL ALIGNMENT	Comments
		x		Front Wheel Alignment (4)	DONE WHEEL ALIGNMENT
		x		Rear Wheel Alignment (4)	DONE WHEEL ALIGNMENT

Brake/Tire Measurements

**xle 1-Pass**

/heel1-Off : Tire Tread Depth: 6 mm

Brake(1): Disc Brake

Min Brake Lining/Pad: 5 mm • Brake Drum/Rotor: 25.8 mm

/heel2-Off : Tire Tread Depth: 5 mm

Brake(1): Disc Brake

Min Brake Lining/Pad: 5 mm • Brake Drum/Rotor: 25.8 mm

**xle 2-Pass**

/heel1-Off : Tire Tread Depth: 5 mm

Brake(1): Disc Brake

Min Brake Lining/Pad: 8 mm • Brake Drum/Rotor: 10 mm

/heel2-Off : Tire Tread Depth: 6 mm

Brake(1): Disc Brake

Min Brake Lining/Pad: 8 mm • Brake Drum/Rotor: 9.9 mm

PASS - vehicle passes inspection	Decal # A133256	Inspection Completed Date: 01Oct2024
----------------------------------	-----------------	--------------------------------------

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be RE-TORQUED within 100-150 km. Failure to do so may result in damage or serious injury.



Vehicle Standards and Inspection

# Light Vehicle Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A133256

Station #: 71973

Station Name: Extra Mile Auto Repair Ltd.

Technician #: 91729

Technician Name: Gurwinder Singh Saggu

Signing Officer #: 91913

Signing Officer Name: Jatinder Singh

### Customer Details:

Name: 3J MOTORS

Address: 703 WINNIPEG STREET, REGINA, Saskatchewan, S4R 1H9

Inspection Completed Date: 01Oct2024

Inspection Expiry Date: N/A

### Vehicle Details:

VIN: JA32U2FU0CU610477

Odometer Reading: 177221 km

Year: 2012

Vehicle Make/Model: MITSUBISHI/LANCER ES

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This inspection is valid for registration purposes outside Saskatchewan for 35 days from the inspection completion date, if acceptable to the registering jurisdiction.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.