



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71973

Station Name: Extra Mile Auto Repair Ltd.

Technician #: 91729

Technician Name: Gurwinder Singh Saggu

Signing Officer #: 91913

Signing Officer Name: Jatinder Singh

Customer Details:

Name: 3J MOTORS

Address: 703 WINNIPEG STREET, REGINA, Saskatchewan, S4R 1H9

Vehicle Details:

VIN: 3GYFK628X7G228999

Odometer Reading: 267149 km

Year: 2007

Vehicle Make/Model: CADILLAC ESCALADE EXT AWD

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (5&8)	
x				Horn Operation (5)	
		x		Mirrors (8)	REPLACED RHS MIRROR
		x		Windshield Wipers/Washers (5)	REPLACED BOTH FRONT WIPER BLADE
x				Windshield Defroster/Heater (5)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Floor/Step Well Covering (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (4)	

x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	
x				Doors (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Alternator/Battery/Wiring (7)	
x				Drive Belts (1)	
		x		Fluid Levels (3&4)	REPLACED OIL PAN GASKET AND FIXED OIL LEAKAGE

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	REPLACED FRONT RHS CV AXLE OUTER BOOT, REPLACED FRONT LHS SWAY BAR LINK, REPLACED REAR SWAY BAR BUSHING
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	
x				Computer Control Suspension (2)	

		x		Shock Absorbers & Strut Assemblies (2)	REPLACED BOTH REAR SHOCK
x				Wheel Seal Leaks (3&9)	
x				Disc Brake Components (3)	
x				Drum Brake Components (3)	
x				Anti-Lock Brakes (3)	

Pass	Rejected	Corrected	Req Attn	WHEEL ALIGNMENT	Comments
		x		Front Wheel Alignment (4)	DONE WHEEL ALIGNMENT
		x		Rear Wheel Alignment (4)	DONE WHEEL ALIGNMENT

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off : Tire Tread Depth: 10 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 10 mm • Brake Drum/Rotor: 30.20 mm

Wheel2-Off : Tire Tread Depth: 10 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 10 mm • Brake Drum/Rotor: 30.37 mm

Axle 2-Pass

Wheel1-Off : Tire Tread Depth: 10 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 6 mm • Brake Drum/Rotor: 20.91 mm

Wheel2-Off : Tire Tread Depth: 10 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 6 mm • Brake Drum/Rotor: 20.16 mm

PASS - vehicle passes inspection	Decal # A138746	Inspection Completed Date: 17Oct2024
----------------------------------	-----------------	--------------------------------------

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.