

Light Vehicle Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A154308

Station #: 71937

Station Name: Punjab Auto Repair Inc.

Technician #: 91504

Technician Name: Balwinder Sandhu

Signing Officer #: 91910

Signing Officer Name: Anand Pandya

Customer Details:

Name: 3J MOTORS

Address: 703 Winnipeg St, Regina, Saskatchewan, S4R1H9

Inspection Completed Date: 19Nov2024

Inspection Expiry Date: N/A

Vehicle Details:

VIN: 3FA6P0T95FR308179

Odometer Reading: 178967 km

Year: 2015

Vehicle Make/Model: FORD/FUSION SE AWD

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This inspection is valid for registration purposes outside Saskatchewan for 35 days from the inspection completion ate, if acceptable to the registering jurisdiction.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Light Vehicle Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71937 Station Name: Punjab Auto Repair Inc.

Technician #: 91504 Technician Name: Balwinder Sandhu

Signing Officer #: 91910 Signing Officer Name: Anand Pandya

Customer Details:

Name: 3J MOTORS Address: 703 Winnipeg St, Regina, Saskatchewan, S4R1H9

Vehicle Details:

VIN: 3FA6P0T95FR308179 Odometer Reading: 178967 km

Year: 2015 Vehicle Make/Model: FORD FUSION SE AWD

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (5&8)	A BY WALL SEEDING
x			EWSTE (Horn Operation (5)	
х		Land Marie	B.	Mirrors (8)	
		x		Windshield Wipers/Washers (5)	Replaced wiper blade
x				Windshield Defroster/Heater (5)	
Χ.				Windshield/Other Glass (8)	
х				Gear Position Indicator & Neutral Switch (1)	
x			-	Instrument Lamps (6)	
х				Floor/Step Well Covering (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
х	STORY SETTING			Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	
х				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
х				Auxiliary Controls/Equip (5)	
х				Speedometer/Odometer (5)	
х				Steering Lash/Travel (4)	

x	Accelerator Pedal/Actuator (1)	
x	Engine Shut Down Control (1)	
x	Engine Start Feature (1)	
x	Body Interior/Fixtures (8)	
x	Doors (8)	The state of the state of

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
×				Lamps (6)	
x		100.00		Headlamp Aim (6)	
×	Pro 1912 975 975 9	G. Landard		Reflex Reflectors (6)	
x				Body/Bumpers (8)	The Survey of th
x			en de la companya de	Trailer Hitch (10)	
x				Cargo Bodies/Vessels (8)	
x	a side of the side			Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Hybrid Vehicle Drive Systems (1)	
х				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x	Bank	200000		Hood Safety Catches (8)	- 10 (8 m c) 10 m c)
x	Maria Livid			Power Steering System (4)	
x		e e v basil	ter access (a)	Fuel System (1)	
x				Alternator/Battery/Wiring (7)	
x				Drive Belts (1)	
×				Fluid Levels (3&4)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3)	
x			1	Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x			****	Steering Linkage (4)	
		×		Tires/Wheels (9)	Replaced four tyre
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
×				Suspension/Axles (2)	
х				Drive Shaft/Universal Joints (1)	
×				Exhaust/Emission System (1)	
×				Computer Control Suspension (2)	
×				Shock Absorbers & Strut Assemblies (2)	
x				Wheel Seal Leaks (3&9)	

v	Disc Brake Components (3)	
	Drum Brake Components (3)	
^	Anti-Lock Brakes (3)	
X		

Pass	Rejected	Corrected	Req Alln	WHEEL ALIGNMENT	Comments
		х		Front Wheel Alignment (4)	Done alignment
		x		Rear Wheel Alignment (4)	Done alignment

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off: Tire Tread Depth: 5 mm

Brake(1): Disc Brake

Wheel2-Off: Tire Tread Depth: 5 mm

Brake(1): Disc Brake

Axle 2-Pass

Wheel1-Off: Tire Tread Depth: 5 mm

Brake(1): Disc Brake

Wheel2-Off: Tire Tread Depth: 5 mm

Brake(1): Disc Brake

PASS - vehicle passes inspection

Decal # A154308

Inspection Completed Date: 19Nov2024

One or more wheels were removed for inspection. Warning: Wheel nuts MUST be RE-TORQUED within 100-150 km. Failure to do so may result in damage or serious injury.