

Contact 3 J Motors
VIN JM1BK343181169694

Tech Fisher Hauglum
Vehicle 2008 MAZDA MAZDA3

Completed Date 11/26/2024
Odom 176864

Visual Inspection

Inspect Horn Operation	<div><div></div><div></div><div></div></div>
Works: No	
Inspect Heat/Defrost Inspection	<div><div></div><div></div><div></div></div>
Inspect Instrument Cluster/Interior Lights	<div><div></div><div></div><div></div></div>
Inspect Seatbelt Operation and Condition	<div><div></div><div></div><div></div></div>
Inspect Mirrors	<div><div></div><div></div><div></div></div>
Inspect Windshield	<div><div></div><div></div><div></div></div>
Inspect Wipers and Operation	<div><div></div><div></div><div></div></div>
Inspect Floor Mat Condition at Accelerator	<div><div></div><div></div><div></div></div>
Inspect Vehicle for Spare Tools	
: No	
Inspect all Doors and Latches for Operation	<div><div></div><div></div><div></div></div>
Inspect all Exterior Lights	<div><div></div><div></div><div></div></div>
Inspect Seat Operation	<div><div></div><div></div><div></div></div>
DF: Yes	
RF: Yes	
Rear: Yes	
Inspect Block Heater and Cord, Check for Operation	<div><div></div><div></div><div></div></div>
Inspect Alternator	<div><div></div><div></div><div></div></div>
Output:	
Volts:	
Amps:	
Inspect all Engine Wiring and Connectors	<div><div></div><div></div><div></div></div>
Inspect Spark Plug Condition/Pull 1 Plug	<div><div></div><div></div><div></div></div>
Inspect Cooling System and Coolant Strength	<div><div></div><div></div><div></div></div>
Strength:	
Inspect all Hoses	<div><div></div><div></div><div></div></div>
Inspect Rad Condition	<div><div></div><div></div><div></div></div>
Inspect Water Pump abd Thermostat for Leaks	<div><div></div><div></div><div></div></div>
Inspect Air filter	<div><div></div><div></div><div></div></div>
Inspect PCV Operation	<div><div></div><div></div><div></div></div>
Inspect Hood Latch Operation	<div><div></div><div></div><div></div></div>
Inspect All Fluid Levels and Condition	<div><div></div><div></div><div></div></div>
Inspect Belts, Tensioner and Idler	<div><div></div><div></div><div></div></div>
Inspect Tires	<div><div></div><div></div><div></div></div>
LF: 8	
RF: 8	
LR: 7	
RR: 7	
Inspect Rims	<div><div></div><div></div><div></div></div>
Inspect Wheel Bearings for Adjustment/Noise	<div><div></div><div></div><div></div></div>
Inspect Brakes and Measure Pads	<div><div></div><div></div><div></div></div>
LF: 6	
RF: 6	
LR: 6	
RR: 6	
Inspect Brake Hoses	<div><div></div><div></div><div></div></div>
Visual Inspection of Steering Linkage	<div><div></div><div></div><div></div></div>
Inspect CV Axle Boots	<div><div></div><div></div><div></div></div>
Inspect Exhaust System	<div><div></div><div></div><div></div></div>
Inspect Engine oil and Power Steering Leaks	<div><div></div><div></div><div></div></div>
Visual Inspection of Fuel Tank and Lines for Leaks	<div><div></div><div></div><div></div></div>
Inspect Engine/Trans Mounts	<div><div></div><div></div><div></div></div>
Inspect Body Condition	<div><div></div><div></div><div></div></div>