Vehicle Standards and Inspection

Light Vehicle Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71937

Station Name: Punjab Auto Repair Inc.

Technician #: 91504

Technician Name: Balwinder Sandhu

Signing Officer #: 91910

Signing Officer Name: Anand Pandya

Customer Details:

Name: 3J MOTORS

Address: 703 Winnipeg St, Regina, Saskatchewan, S4R1H9

Vehicle Details:

VIN: 1FTFW1R68DFC29857

Odometer Reading: 265318 km

Year: 2013

Vehicle Make/Model: FORD F150 RAPTOR

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (5&8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (5)	
x				Windshield Defroster/Heater (5)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Floor/Step Well Covering (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (4)	

x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	
x				Doors (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Alternator/Battery/Wiring (7)	
x				Drive Belts (1)	
x				Fluid Levels (3&4)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
		x		Tires/Wheels (9)	Install new lug nuts
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	
x				Computer Control Suspension (2)	
x				Shock Absorbers & Strut Assemblies (2)	
x				Wheel Seal Leaks (3&9)	

		x		Disc Brake Components (3)	Replaced rear brake pad
x				Drum Brake Components (3)	
x				Anti-Lock Brakes (3)	

Pass	Rejected	Corrected	Req Attn	WHEEL ALIGNMENT	Comments
x				Front Wheel Alignment (4)	
x				Rear Wheel Alignment (4)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off : Tire Tread Depth: 7 mm
Brake(1): Disc Brake
• Min Brake Lining/Pad: 4 mm • Brake Drum/Rotor: 34 mm
Wheel2-Off : Tire Tread Depth: 7 mm
Brake(1): Disc Brake
• Min Brake Lining/Pad: 6 mm • Brake Drum/Rotor: 34 mm

Axle 2-Pass

Wheel1-Off : Tire Tread Depth: 9 mm
Brake(1): Disc Brake
• Min Brake Lining/Pad: 12 mm • Brake Drum/Rotor: 26 mm
Wheel2-Off : Tire Tread Depth: 9 mm
Brake(1): Disc Brake
• Min Brake Lining/Pad: 12 mm • Brake Drum/Rotor: 26 mm

PASS - vehicle passes inspection	Decal # A192333	Inspection Completed Date: 27Jan2025

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.