SO# B213607

Visual 40 Point Inspection

Contact	3j Motors	**Tech**	Alexander Woidyla	**Completed Date**	12/27/2024
VIN	WBA5B3C59ED292351	**Vehicle**	2014 BMW 5 SERIES	**Odom**	168705

Visual Inspection

Inspect Horn Operation	✓		
Works: No			
Inspect Heat/Defrost Inspection	✓		
Inspect Instrument Cluster/Interior Lights	✓		
Inspect Seatbelt Operation and Condition	✓		
Inspect Mirrors	✓		
Inspect Windshield	✓		
Inspect Wipers and Operation	✓		
Inspect Floor Mat Condition at Accelerator	✓		
Inspect Vehicle for Spare Tools			
: No			
Inspect all Doors and Latches for Operation	✓		
Inspect all Exterior Lights	✓		
Inspect Seat Operation	✓		
DF: Yes			
RF: Yes			
Rear: Yes			
Inspect Block Heater and Cord, Check for Operation			
Inspect Alternator			
Output:			
Volts:			
Amps:			
Inspect all Engine Wiring and Connectors	✓		
Inspect Spark Plug Condition/Pull 1 Plug			
Inspect Cooling System and Coolant Strength	✓		
Strength: 45			
Inspect all Hoses	✓		
Inspect Rad Condition	✓		
Inspect Water Pump abd Thermostat for Leaks	✓		
Inspect Air filter	✓		
Inspect PCV Operation	✓		
Inspect Hood Latch Operation	✓		
Inspect All Fluid Levels and Condition	✓		
Inspect Belts, Tensioner and Idler	✓		
Inspect Tires		✓	
LF: 6			
RF: 6			
LR: 4			
RR: 4			
Inspect Rims	✓		
Inspect Wheel Bearings for Adjustment/Noise	✓		
Inspect Brakes and Measure Pads	✓		
LF: 10			
RF: 10			
LR: 8			
RR: 8			
Inspect Brake Hoses	✓		
Visual Inspection of Steering Linkage		✓	
Inspect CV Axle Boots	✓		
Inspect Exhaust System	✓		
Inspect Engine oil and Power Steering Leaks	✓		
Visual Inspection of Fuel Tank and Lines for Leaks	✓		
Inspect Engine/Trans Mounts	✓		
Inspect Body Condition	✓		