ehicle Standards and Inspection

Light Vehicle Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70251

Station Name: Frame & Wheel Alignment Co

Technician #: 80522

Technician Name: Chris Magnusson

Signing Officer #: 91056

Signing Officer Name: Jorlen Jose

Customer Details:

Name: G7 auto-group inc.

Address: 4514 padwick cres, regina, Saskatchewan, s4w0c5

Vehicle Details:

VIN: 5XYZGDAG1CG117459

Odometer Reading: 233392 km

Year: 2012

Vehicle Make/Model: HYUNDAI SANTA FE V6 AWD

ıspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (5&8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (5)	
x				Windshield Defroster/Heater (5)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Floor/Step Well Covering (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (4)	

x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	
x				Doors (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	both rear side marker lights out. license light out.
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Alternator/Battery/Wiring (7)	
x				Drive Belts (1)	
x				Fluid Levels (3&4)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3)	
x				Wheel Bearings (9)	
		x		King Pins/Ball Joints (4)	play in both REAR upper ball joints
x				Steering Linkage (4)	
		x		Tires/Wheels (9)	tread low both rear tires.
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

x				Wheel Seal Leaks (3&9)	
x				Disc Brake Components (3)	
x				Drum Brake Components (3)	
x				Anti-Lock Brakes (3)	

Pass	Rejected	Corrected	Req Attn	WHEEL ALIGNMENT	Comments
		x		Front Wheel Alignment (4)	
		x		Rear Wheel Alignment (4)	

rake/Tire Measurements

xle 1-Pass

/heel1-Off : Tire Tread Depth: 9/32 in
rake(1): Disc Brake
Min Brake Lining/Pad: 8/32 in • Brake Drum/Rotor: 27.52 mm
/heel2-Off : Tire Tread Depth: 9/32 in
rake(1): Disc Brake
Min Brake Lining/Pad: 9/32 in • Brake Drum/Rotor: 27.51 mm

xle 2-Pass

/heel1-Off : Tire Tread Depth: 8/32 in
rake(1): Disc Brake
Min Brake Lining/Pad: 6/32 in • Brake Drum/Rotor: 10.65 mm
/heel2-Off : Tire Tread Depth: 8/32 in
rake(1): Disc Brake
Min Brake Lining/Pad: 7/32 in • Brake Drum/Rotor: 10.44 mm

PASS - vehicle passes inspection	Decal # A159152	Inspection Completed Date: 24Dec2024

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.