



Vehicle Standards and Inspection

Light Vehicle Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71937

Station Name: Punjab Auto Repair Inc.

Technician #: 91504

Technician Name: Balwinder Sandhu

Signing Officer #: 91910

Signing Officer Name: Anand Pandya

Customer Details:

Name: 3J MOTORS

Address: 703 Winnipeg St, Regina, Saskatchewan, S4R1H9

Vehicle Details:

VIN: 5UXFE83519L171321

Odometer Reading: 183214 km

Year: 2009

Vehicle Make/Model: BMW X5 4.8i AWD

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (5&8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (5)	
x				Windshield Defroster/Heater (5)	
		x		Windshield/Other Glass (8)	Fix door regulator
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Floor/Step Well Covering (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (4)	

x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	
x				Doors (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Alternator/Battery/Wiring (7)	
x				Drive Belts (1)	
		x		Fluid Levels (3&4)	Replaced Engine oil seal and differential seal

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
		x		Steering Linkage (4)	Install new front left bellow boot
		x		Tires/Wheels (9)	Replaced front both tyre
		x		Engine/Transmission Mounts (1)	Replaced transfer case support bar Rust
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	Replaced front both control arm
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	
x				Computer Control Suspension (2)	
x				Shock Absorbers & Strut Assemblies (2)	

x				Wheel Seal Leaks (3&9)	
x				Disc Brake Components (3)	
x				Drum Brake Components (3)	
x				Anti-Lock Brakes (3)	

Pass	Rejected	Corrected	Req Attn	WHEEL ALIGNMENT	Comments
x				Front Wheel Alignment (4)	
x				Rear Wheel Alignment (4)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off : Tire Tread Depth: 7 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 10 mm • Brake Drum/Rotor: 29 mm

Wheel2-Off : Tire Tread Depth: 7 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 10 mm • Brake Drum/Rotor: 28.90 mm

Axle 2-Pass

Wheel1-Off : Tire Tread Depth: 7 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 6 mm • Brake Drum/Rotor: 22.50 mm

Wheel2-Off : Tire Tread Depth: 7 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 6 mm • Brake Drum/Rotor: 22.48 mm

PASS - vehicle passes inspection

Decal # A192340

Inspection Completed Date: 30Jan2025

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.



Vehicle Standards and Inspection

Light Vehicle Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A192340

Station #: 71937

Station Name: Punjab Auto Repair Inc.

Technician #: 91504

Technician Name: Balwinder Sandhu

Signing Officer #: 91910

Signing Officer Name: Anand Pandya

Customer Details:

Name: 3J MOTORS

Address: 703 Winnipeg St, Regina, Saskatchewan, S4R1H9

Inspection Completed Date: 30Jan2025

Inspection Expiry Date: N/A

Vehicle Details:

VIN: 5UXFE83519L171321

Odometer Reading: 183214 km

Year: 2009

Vehicle Make/Model: BMW/X5 4.8i AWD

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This inspection is valid for registration purposes outside Saskatchewan for 35 days from the inspection completion date, if acceptable to the registering jurisdiction.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.