



Vehicle History Report #: 46159084
Report Date: May 23, 2023 | 1:35 PM EDT
Report Status: Complete
Reference:

2019 VOLKSWAGEN JETTA S

Sedan | 4 Cylinders | Gas
3VWC57BU0KM080842
Country of Assembly: Mexico
Last Reported Odometer: 183,994 KM



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



2 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 23, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

3VWC57BU0KM080842

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2018 Sep 7		Maple Volkswagen Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Vehicle washed/detailed
2018 Dec 31		Maple Volkswagen Maple, Ontario, Canada	Vehicle serviced



Open Recalls

Recall #: 42J5 | COIL SPRINGS Recall Date: 2019 Mar 28

Recall Description

The rear axle coil springs in affected vehicles may not have met factory specifications due to a defect in materials or because of problems in the spring production process. These issues can impact the long-term durability of the rear axle coil springs. Affected coil springs can break. A broken coil spring can damage a rear tire, become a hazard on the roadway and lead to a loss of vehicle control without warning, putting people at risk and possibly causing damage to other vehicles on the road.

Remedy

Replace the rear axle coil springs.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](#).



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Sep 7		Maple Volkswagen	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Maple, Ontario, Canada		
2018 Dec 31		Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2019 Mar 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Commercial
2019 Mar 28		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 42J5
2021 Dec 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2022 Apr 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2022 May 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2022 Nov 16	183,994 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.



3VWC57BU0KM080842