



Vehicle History Report #: 47489612
Report Date: July 28, 2023 | 11:35 AM EDT
Report Status: Complete
Reference:

2018 NISSAN ROGUE S

Sport utility vehicle | 4 Cylinders | Gas
5N1AT2MT0JC826273
Country of Assembly: United States
Last Reported Odometer: 94,328 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



11 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca




This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 28, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
 2019 Mar 24	Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage with another motor vehicle Damage to left front Claim: Other Damage	\$5,458.00



Registration

 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2018 Jul 31		Airport Nissan Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed VIN glass etching vin etched Wheel locks installed
2018 Aug 31		Airport Nissan Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
2018 Dec 19	9,777 KM	Great Canadian Oil Change Concord, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2019 Apr 17	22,756 KM	Great Canadian Oil Change Concord, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2019 Aug 13	32,984 KM	Great Canadian Oil Change Concord, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2019 Nov 3	41,025 KM	Great Canadian Oil Change Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Air filter checked
2020 Feb 23	50,086 KM	Great Canadian Oil Change Scarborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2020 Jul 12	58,018 KM	Jiffy Lube #2871 Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Fluids checked Windshield washer checked

	ODOMETER	SOURCE	DETAILS
2021 Mar 7	68,111 KM	Valvoline Express Care Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Antifreeze/coolant checked • Fluids checked • Windshield washer checked
2021 Oct 23	84,233 KM	Valvoline Express Care Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Air filter checked • Fluids checked • Windshield washer checked
2022 May 8	94,328 KM	Valvoline Express Care Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Fluids checked • Windshield washer checked



Open Recalls

Recall #: R1911 | NIS AV CONT UNIT MULTI TSB Recall Date: 2019 May 15

Recall Description

ON AFFECTED VEHICLES, A DRIVER MAY POTENTIALLY ADJUST THE REARVIEW CAMERA AND DISPLAY SETTINGS TO A DEGREE THAT THE IMAGE IS NO LONGER VISIBLE, AND THE SYSTEM WILL RETAIN THOSE SETTINGS AT THE NEXT BACKING EVENT. THIS CONDITION DOES NOT MEET THE REQUIREMENTS FOR DEFAULT VIEW REQUIRED FOR FMVSS NO. 111.

Remedy

DEALERS WILL REPROGRAM THE VEHICLE INFOTAINMENT SYSTEM WITH COUNTERMEASURE SOFTWARE DELIVERED VIA USB OR SD CARD. THIS FREE SERVICE VARIES BY MODEL, BUT COULD TAKE UP TO ONE (1) HOUR. YOUR NISSAN DEALER MAY REQUIRE YOUR VEHICLE FOR A LONGER PERIOD OF TIME BASED UPON THEIR WORK SCHEDULE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).

Recall #: P9327 | ROGUE AEB NTB19-064 Recall Date: 2019 Aug 27

Recall Description

In rare instances and unique roadway environments such as certain types of railroad crossings and metal overpasses, the Automatic Emergency Braking (AEB) system in some vehicles may activate braking when it is not needed. The driver can always override the Automatic Emergency Braking (AEB) system by pressing the accelerator.

Remedy

Dealers will reprogram the Radar and Advanced Driver Assistance System (ADAS) components of the Automatic Emergency Braking (AEB) system with updated software to prevent false Automatic Emergency Braking (AEB) activation in previously specified driving environments.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Jul 31		Airport Nissan Brampton, Ontario, Canada	Service Record	Vehicle serviced
2018 Aug 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2018 Aug 31		Airport Nissan Brampton, Ontario, Canada	Service Record	Vehicle serviced
2018 Dec 19	9,777 KM	Great Canadian Oil Change Concord, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 24		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • moderate damage • with another motor vehicle • Damage to left front
2019 Mar 24		Insurance Records Ontario, Canada		
2019 Apr 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Apr 17	22,756 KM	Great Canadian Oil Change Concord, Ontario, Canada	Service Record	Vehicle serviced
2019 May 15		NISSAN	Recall	Manufacturer Recall Issued Recall # R1911
2019 Aug 13	32,984 KM	Great Canadian Oil Change Concord, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 27		NISSAN	Recall	Manufacturer Recall Issued Recall # P9327
2019 Nov 3	41,025 KM	Great Canadian Oil Change Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 23	50,086 KM	Great Canadian Oil Change Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2020 Jul 12	58,018 KM	Jiffy Lube #2871 Markham, Ontario, Canada	Service Record	Vehicle serviced
2021 Mar 7	68,111 KM	Valvoline Express Care Brampton, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Apr 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Oct 23	84,233 KM	Valvoline Express Care Brampton, Ontario, Canada	Service Record	Vehicle serviced
2022 May 8	94,328 KM	Valvoline Express Care Brampton, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.

