


Vehicle History Report #: 48933110 Report Date: October 5, 2023 | 5:21 PM EDT Report Status: Complete Reference:


# 2013 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas 3VW2K7AJ1DM446371 Country of Assembly: Mexico Last Reported Odometer: 133,370 KM



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 05, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

## **Vehicle History Report**



INCIDENT DATE	DETAILS	AMOUNT
9 2021 Nov 1	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage	
	Vehicle involved in a rear-end collision	
	with another motor vehicle	
	Damage to rear	

### Registration

🕑 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

### Service Records

DATE	ODOMETER	SOURCE	DETAILS
2020 Aug 21	88,432 KM	Confederation Lube & Tire Express	Vehicle serviced
		Sarnia, Ontario, Canada	Recommended maintenance performed
			Oil and filter changed
2020 Oct 29	98,217 KM	Confederation Lube & Tire Express	Vehicle serviced
		Sarnia, Ontario, Canada	Recommended maintenance performed
			Oil and filter changed
2021 Jul 5	133,370 KM	Confederation Lube & Tire Express	Vehicle serviced
		Sarnia, Ontario, Canada	Oil and filter changed
2023 May 19		Speedy Lube 2002	Vehicle serviced
		Timmins, Ontario, Canada	Maintenance inspection completed
			Oil and filter changed

## 🔰 Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

#### **Recall Description**

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

#### Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed,

please contact VOLKSWAGEN or visit Volkswagen's website.

#### **Stolen Vehicle Check –** =

This vehicle is not actively declared stolen.

### **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Jul 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2014 Jun 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Jun 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jun 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jun 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jun 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jun 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Aug 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2020 Jun 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Jul 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2020 Aug 21	88,432 KM	Confederation Lube & Tire Express Sarnia, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 29	98,217 KM	Confederation Lube & Tire Express Sarnia, Ontario, Canada	Service Record	Vehicle serviced
2021 Mar 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported

#### CARFAX Canada Vehicle History Reports

	ODOMETER	SOURCE	RECORD TYPE	PETAILS Use: Personal
2021 Jul 5	133,370 KM	Confederation Lube & Tire Express Sarnia, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2021 Nov 1		Police Reported Accident Ontario, Canada	Police Report	<ul> <li>Accident Reported:</li> <li>minor damage</li> <li>Vehicle involved in a rear-end collision</li> <li>with another motor vehicle</li> <li>Damage to rear</li> </ul>
2022 Sep 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2023 May 19		Speedy Lube 2002 Timmins, Ontario, Canada	Service Record	Vehicle serviced
2023 Sep 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and Its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an asis where is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantabile quality or filtness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada and any CARFAX Canada and US CARFAX Canada and US CARFAX Canada and use there acets may be atterned from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.

