


Vehicle History Report #: 45467049 Report Date: April 18, 2023 | 4:15 PM EDT Report Status: Complete

2012 DODGE RAM 2500

3C6UD5CL5CG194895 Country of Assembly: n/a Last Reported Odometer: 283,269 KM



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 18, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



(i)

INCIDENT DATE	DETAILS	AMOUNT
\rm 9 2012 Jul 13	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage	
	with another motor vehicle	
	Damage to left rear	

Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2012 Jun 6	7,467 KM	Service Facility	Vehicle serviced
			Brakes checked
2012 Jul 3	12,122 KM	Service Facility	Vehicle serviced
			Oil and filter changed
2012 Aug 24	20,384 KM	Service Facility	Vehicle serviced
			Lights checked
			Oil and filter changed
2012 Nov 2	29,060 KM	Service Facility	Vehicle serviced
			Oil and filter changed
			Tire condition and pressure checked
2012 Dec 19	34,300 KM	Service Facility	Vehicle serviced
			Oil and filter changed
2013 Feb 15	40,214 KM	Service Facility	Vehicle serviced
		2	Oil and filter changed
2013 Apr 12	49,560 KM	Service Facility	Vehicle serviced
			AIR system checked
			Axles checked
			Oil and filter changed
2013 May 24	58,579 KM	Service Facility	Vehicle serviced
			Oil and filter changed
2013 Jul 12	66,643 KM	Service Facility	Vehicle serviced
			Fuel system checked
			Oil and filter changed
2013 Aug 23	71,288 KM	Service Facility	Vehicle serviced
			AIR system checked
2013 Sep 13	73,665 KM	Service Facility	Vehicle serviced
		-	Axles checked
			Oil and filter changed

	ODOMETER	SOURCE	DETAILS
2013 Nov 15	81,401 KM	Service Facility	Vehicle serviced
	·	5	Fuel system checked
			Oil and filter changed
			Steering/suspension checked
			Tire condition and pressure checked
2014 Jan 18	87,159 KM	Service Facility	Vehicle serviced
	,		Oil and filter changed
2014 Mar 23	93,675 KM	Service Facility	Vehicle serviced
		-	Oil and filter changed
2014 14 2	00.020 //14		
2014 May 2	99,939 KM	Service Facility	Vehicle serviced
			Oil and filter changed
			Transmission checked
2014 May 14	101,900 KM	Service Facility	Vehicle serviced
2014 Jun 13	106,971 KM	Service Facility	Vehicle serviced
			Oil and filter changed
20141 22	100 057 101	Comitor Fo 111	Valida annual d
2014 Jun 30	109,357 KM	Service Facility	Vehicle serviced
			AIR system checked
			Wheel bearing(s)/hub(s) replaced
			Exhaust system checked
2014 Jul 4	109,938 KM	Service Facility	Vehicle serviced
		Belleville, Ontario, Canada	
2014 Aug 23	117,555 KM	Service Facility	Vehicle serviced
			Oil and filter changed
2014 Sep 2	118,560 KM	Service Facility	Vehicle serviced
2014 Oct 9	129,328 KM	Service Facility	Vehicle serviced
			Oil and filter changed
2014 Nov 21	130,859 KM	Service Facility	Vehicle serviced
		-	Oil and filter changed
	400.007.00		V 1 · 1 · · ·
2015 Feb 20	138,827 KM	Service Facility	Vehicle serviced
2015 Feb 20	138,827 KM	Service Facility	Oil and filter changed
2015 Feb 20	138,827 KM	Service Facility	Oil and filter changedSteering/suspension checked
2015 Feb 20	138,827 KM	Service Facility	Oil and filter changed
2015 Feb 20 2015 Apr 10	138,827 KM 144,585 KM	Service Facility Service Facility	Oil and filter changedSteering/suspension checked
			 Oil and filter changed Steering/suspension checked Tire condition and pressure checked
			 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced
2015 Apr 10		Service Facility	 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced AIR system checked Oil and filter changed
2015 Apr 10			 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced AIR system checked Oil and filter changed Vehicle serviced
2015 Apr 10		Service Facility	 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced Oil and filter changed Vehicle serviced Oil and filter changed
2015 Apr 10		Service Facility	 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced Oil and filter changed Vehicle serviced Oil and filter changed Oil and filter changed Cooling system checked
		Service Facility	 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced AIR system checked Oil and filter changed Vehicle serviced Oil and filter changed Oil and filter changed Cooling system checked
2015 Apr 10 2015 Jun 11		Service Facility Service Facility	 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced AIR system checked Oil and filter changed Vehicle serviced Oil and filter changed Cooling system checked Exhaust system checked Fuel system checked
2015 Apr 10 2015 Jun 11		Service Facility	 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced AIR system checked Oil and filter changed Vehicle serviced Oil and filter changed Cooling system checked Exhaust system checked Fuel system checked Vehicle serviced Weise serviced
2015 Apr 10		Service Facility Service Facility	 Oil and filter changed Steering/suspension checked Tire condition and pressure checked Vehicle serviced AIR system checked Oil and filter changed Vehicle serviced Oil and filter changed Cooling system checked Exhaust system checked Fuel system checked

3C6UD5CL5CG194895

	ODOMETER	SOURCE	DETAILS	
2015 Jul 23	155,714 KM	Elegant Motoring Etobicoke, Ontario, Canada	Vehicle serviced Mirror(s) checked Brake pads replaced Light bulb(s) replaced Rear brake pads replaced Front brake pads replaced Tie rod end(s) replaced Turn signal bulb(s) replaced Brake light bulb(s) replaced	
2015 Sep 15	161,185 KM	Service Facility Belleville, Ontario, Canada	 Vehicle serviced Maintenance inspection completed Oil and filter changed Exterior lights checked 	
2015 Nov 27	173,614 KM	Bayview Chrysler Dodge Ltd Sarnia, Ontario, Canada	 Vehicle serviced Engine/powertrain computer/module checked AIR system checked Electrical system checked Oil and filter changed 	
2016 Jan 12	175,475 KM	Raceway Chrysler Etobicoke, Ontario, Canada	 Vehicle serviced Engine/powertrain computer/module checked Exhaust system checked 	
2016 Apr 8	181,766 KM	Service Facility	 Vehicle serviced AIR system checked Axles checked Oil and filter changed Transmission checked 	
2016 May 27	184,972 KM	Service Facility	Vehicle serviced Driveshaft checked 	
2016 Aug 12	189,615 KM	Service Facility	 Vehicle serviced Oil and filter changed Tire condition and pressure checked 	
2016 Sep 6	192,466 KM	Butterworth's Service Centre Inc. Ingersoll, Ontario, Canada	Vehicle servicedCooling system checkedExhaust system checked	
2016 Sep 7		Glassford Chrysler Ingersoll, Ontario, Canada	 Vehicle serviced PCM reprogrammed Serpentine belt replaced 	
2016 Dec 7	200,136 KM	Service Facility	Vehicle servicedAIR system checkedOil and filter changed	
2017 Apr 7	206,302 KM	Speedy Auto Service Mississauga, Ontario, Canada	Vehicle servicedExhaust system checkedOil and filter changed	
2017 May 29	209,049 KM	Speedy Auto Service Mississauga, Ontario, Canada	 Vehicle serviced Tire repaired Tire condition and pressure checked 	
2017 Aug 11	213,611 KM	Service Facility	Vehicle serviced Brakes checked Lights checked Steering/suspension checked 	

 Brakes checked Oil and filter changed Tire condition and pressure checked 229,631 KM Service Facility Vehicle serviced Ignition system checked 2018 Jul 10 Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada Vehicle serviced AIR system checked Oil and filter changed Tire condition and pressure checked Oil and filter changed Tire condition and pressure checked Oil and filter changed Tire condition and pressure checked Service Facility Vehicle serviced AIR system checked Oil and filter changed Tire condition and pressure checked Sterring/suspension checked Sterring/suspension checked Sterring/suspension checked Sterring/suspension checked Sterring/suspension checked Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Wehicle serviced Wheel bearing(s)/hub(s) replaced 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada Vehicle serviced Active Green & Ross Vehicle serviced 		ODOMETER	SOURCE	DETAILS
 Oil and filter changed Fuel system checked Fuel system checked Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Ignition system checked Ignition system checked Ignition system checked Service Facility Vehicle serviced Ignition system checked Oil and filter changed Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Oil and filter changed Tree condition and pressure checked Steering/subject facility Vehicle serviced Steering/subject facility Vehicle serviced Steering/subject facility Vehicle serviced Wheel bearing(s)/hub(s) replaced Wheel bearing(s)/hub(s) replaced Wheel bearing(s)/hub(s) replaced Wheel serviced Wheel serviced Steering/subject facility Vehicle serviced Wheel serviced Wheel serviced Wheel serviced Tree condition and pressure checked Wheel serviced Wheel serviced Wheel serviced Wheel serviced Wheel serviced Wheel serviced Steering Subject facility 	2017 Nov 8	218,411 KM	Speedy Auto Service	Vehicle serviced
Fuel system checked Tire condition and pressure checked2018 May 24227,498 KMService FacilityVehicle serviced • Dil and filter changed • Tire condition and pressure checked2018 Jul 9229,631 KMService FacilityVehicle serviced 			Mississauga, Ontario, Canada	Maintenance inspection completed
Tre condition and pressure checked2018 May 24227,498 KMService FacilityVehicle serviced · Brakes checked · Oil and filter changed · Tire condition and pressure checked2018 Jul 9229,631 KMService FacilityVehicle serviced · Ignition system checked2018 Jul 10Taylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced · Ignition and pressure checked2019 Jan 31234,620 KMService FacilityVehicle serviced · Oil and filter changed · Tire condition and pressure checked · Oil and filter changed · Tire condition and pressure checked · Oil and filter changed · Tire condition and pressure checked · Oil and filter changed · Tire condition and pressure checked · Wheel bearing(s)/hub(s) replaced2020 Jan 14244,076 KMService Facility Mississauga, Ontario, CanadaVehicle serviced · Wheile serviced2021 Mar 29253,324 KMMechaniq Oakville 1 Oakville, Ontario, CanadaVehicle serviced2021 Jul 19258,750 KMTaylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced2022 Nov 2283,269 KM<			-	Oil and filter changed
2018 May 24227,498 KMService FacilityVehicle serviced Brakes checked Oil and filter changed Tre condition and pressure checked2018 Jul 9229,631 KMService FacilityVehicle serviced • Ignition system checked2018 Jul 9229,631 KMService FacilityVehicle serviced • Ignition system checked2018 Jul 10Taylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced • Ignition system checked2019 Jan 31234,620 KMService FacilityVehicle serviced • AIR system checked • Oil and filter changed • Tire condition and pressure checked2019 May 7238,534 KMService FacilityVehicle serviced • Electrical system checked • Steering/suspension checked • Tire condition and pressure checked • Wheel bearing(s)/hub(s) replaced2020 Jan 14244,076 KMService Facility Mississauga, Ontario, CanadaVehicle serviced • Wheel bearing(s)/hub(s) replaced2021 Jul 19258,750 KMTaylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced • Vehicle serviced2022 Nov 2283,269 KMActive Green & RossVehicle serviced				Fuel system checked
 Brakes checked Oil and filter changed Tire condition and pressure checked 229,631 KM Service Facility Vehicle serviced Ignition system checked 2018 Jul 10 Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada Vehicle serviced AIR system checked Oil and filter changed Tire condition and pressure checked Oil and filter changed Tire condition system checked Oil and filter changed Tire condition and pressure checked Oil and filter changed Tire condition and pressure checked Service Facility Vehicle serviced Electrical system checked Sterring/suspension checked Sterring/suspension checked Sterring/suspension checked Sterring/suspension checked Sterring/suspension checked Wheel bearing(s)/hub(s) replaced Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Wehicle serviced Wheel bearing(s)/hub(s) replaced Wheel bearing(s)/hub(s) replaced 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada Vehicle serviced Vehicle serviced Stering State checked Wehicle serviced 				Tire condition and pressure checked
 Oil and filter changed Tire condition and pressure checked Ignition system checked Oil and filter changed Add the serviced Oil and filter changed Ignition system checked Oil and filter changed Oil and filter changed Oil and filter changed Oil and filter changed Tire condition and pressure checked Oil and filter changed Tire condition and pressure checked Steering/suspension checked Steering/suspensichecked Stee	2018 May 24	227,498 KM	Service Facility	Vehicle serviced
 Oil and filter changed Tire condition and pressure checked Ignition system checked Oil and filter changed Add the serviced Oil and filter changed Ignition system checked Oil and filter changed Oil and filter changed Oil and filter changed Oil and filter changed Tire condition and pressure checked Oil and filter changed Tire condition and pressure checked Steering/suspension checked Steering/suspensichecked Stee			2	Brakes checked
- Tire condition and pressure checked2018 Jul 9229,631 KMService FacilityVehicle serviced · Ignition system checked2018 Jul 10Taylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced2019 Jan 31234,620 KMService FacilityVehicle serviced 2019 May 7238,534 KMService FacilityVehicle serviced · Steering/suspension checked 				
1Taylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced2019 Jan 31234,620 KMService FacilityVehicle serviced • AlR system checked • Oil and filter changed • Tire condition and pressure checked • Oil and filter changed • Tire condition and pressure checked • Steering/suspension checked • Tire condition and pressure checked • Wheel bearing(s)/hub(s) replaced2020 Jan 14244,076 KMService Facility Mississauga, Ontario, CanadaVehicle serviced2021 Mar 29253,324 KMMechaniq Oakville 1 Oakville, Ontario, CanadaVehicle serviced2021 Jul 19258,750 KMTaylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced2022 Nov 2283,269 KMActive Green & RossVehicle serviced				-
1Taylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced2019 Jan 31234,620 KMService FacilityVehicle serviced • AlR system checked • Oil and filter changed • Tire condition and pressure checked2019 May 7238,534 KMService FacilityVehicle serviced • Oil and filter changed • Tire condition and pressure checked • Steering/suspension checked • Tire condition and pressure checked • Wheel bearing(s)/hub(s) replaced2020 Jan 14244,076 KMService Facility Mississauga, Ontario, CanadaVehicle serviced2021 Mar 29253,324 KMMechaniq Oakville 1 Oakville, Ontario, CanadaVehicle serviced2021 Jul 19258,750 KMTaylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced2022 Nov 2283,269 KMActive Green & RossVehicle serviced	2018 Jul 9	229.631 KM	Service Facility	Vehicle serviced
Hamilton, Ontario, Canada2019 Jan 31234,620 KMService FacilityVehicle serviced • AIR system checked • Oil and filter changed • Tire condition and pressure checked • Oil and filter changed • Tire condition and pressure checked • Steering/suspension checked • Steering/suspension checked • Steering(s)/hub(s) replaced2019 May 7238,534 KMService Facility Mississauga, Ontario, CanadaVehicle serviced • Electrical system checked • Steering(s)/hub(s) replaced2020 Jan 14244,076 KMService Facility Mississauga, Ontario, CanadaVehicle serviced2021 Mar 29253,324 KMMechaniq Oakville 1 Oakville, Ontario, CanadaVehicle serviced2021 Jul 19258,750 KMTaylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced2022 Nov 2283,269 KMActive Green & RossVehicle serviced			y	
Hamilton, Ontario, Canada2019 Jan 31234,620 KMService FacilityVehicle serviced • AIR system checked • Oil and filter changed • Tire condition and pressure checked • Oil and filter changed • Tire condition and pressure checked • Steering/suspension checked • Steering/suspension checked • Steering(s)/hub(s) replaced2019 May 7238,534 KMService Facility Mississauga, Ontario, CanadaVehicle serviced • Electrical system checked • Steering(s)/hub(s) replaced2020 Jan 14244,076 KMService Facility Mississauga, Ontario, CanadaVehicle serviced2021 Mar 29253,324 KMMechaniq Oakville 1 Oakville, Ontario, CanadaVehicle serviced2021 Jul 19258,750 KMTaylor Chrysler Dodge Ltd Hamilton, Ontario, CanadaVehicle serviced2022 Nov 2283,269 KMActive Green & RossVehicle serviced	2019 101 10		Taylor Chrycler Dodgo Ltd	Vehicle conviced
2019 Jan 31234,620 KMService FacilityVehicle serviced 	2018 Jul 10			venicle serviced
 AIR system checked Oil and filter changed Tire condition and pressure checked Electrical system checked Steering/suspension checked Steering/suspension checked Tire condition and pressure checked Steering/suspension checked Wheel bearing(s)/hub(s) replaced Weile serviced Weile serviced Weile serviced Weile serviced Weile serviced Weile serviced 			Hamilton, Ontario, Canada	
 Oil and filter changed Tire condition and pressure checked Tire condition and pressure checked Electrical system checked Steering/suspension checked Steering/suspension checked Tire condition and pressure checked Steering/suspension checked Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Mississauga, Ontario, Canada Vehicle serviced Wheel bearing(s)/hub(s) replaced Vehicle serviced Wheel bearing(s)/hub(s) replaced 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada Vehicle serviced Vehicle serviced Vehicle serviced Active Green & Ross Vehicle serviced 	2019 Jan 31	234,620 KM	Service Facility	Vehicle serviced
 Oil and filter changed Tire condition and pressure checked Tire condition and pressure checked Electrical system checked Steering/suspension checked Steering/suspension checked Tire condition and pressure checked Steering/suspension checked Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Mississauga, Ontario, Canada Vehicle serviced Wheel bearing(s)/hub(s) replaced Vehicle serviced Wheel bearing(s)/hub(s) replaced 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada Vehicle serviced Vehicle serviced Vehicle serviced Active Green & Ross Vehicle serviced 				AIR system checked
2019 May 7238,534 KMService FacilityVehicle serviced 				Oil and filter changed
 Electrical system checked Steering/suspension checked Tire condition and pressure checked Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Mississauga, Ontario, Canada 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced				Tire condition and pressure checked
 Electrical system checked Steering/suspension checked Tire condition and pressure checked Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Mississauga, Ontario, Canada 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada Vehicle serviced 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced	2019 May 7	238,534 KM	Service Facility	Vehicle serviced
 Steering/suspension checked Tire condition and pressure checked Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Mississauga, Ontario, Canada Vehicle serviced Vehicle serviced Vehicle serviced 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada Vehicle serviced Vehicle serviced Vehicle serviced Active Green & Ross Vehicle serviced 	,		, ,	Electrical system checked
 Tire condition and pressure checked Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Mississauga, Ontario, Canada 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced Vehicle serviced 				
 Wheel bearing(s)/hub(s) replaced 2020 Jan 14 244,076 KM Service Facility Mississauga, Ontario, Canada 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced 				
Mississauga, Ontario, Canada 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada Vehicle serviced 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada Vehicle serviced 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced				
Mississauga, Ontario, Canada 2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada Vehicle serviced 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada Vehicle serviced 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced	2020 lan 14	244.076 KM	Service Facility	Vehicle serviced
2021 Mar 29 253,324 KM Mechaniq Oakville 1 Oakville, Ontario, Canada Vehicle serviced 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada Vehicle serviced 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced		2,0,0.0	•	
Oakville, Ontario, Canada 2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Vehicle serviced Hamilton, Ontario, Canada Vehicle serviced 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced			Mississauga, Ontario, Canada	
2021 Jul 19 258,750 KM Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada Vehicle serviced 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced	2021 Mar 29	253,324 KM	Mechaniq Oakville 1	Vehicle serviced
Hamilton, Ontario, Canada 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced			Oakville, Ontario, Canada	
Hamilton, Ontario, Canada 2022 Nov 2 283,269 KM Active Green & Ross Vehicle serviced	2021 Jul 19	258,750 KM	Taylor Chrysler Dodge Ltd	Vehicle serviced
	-			
	2022 Nov 2	283 260 KM	Active Green & Poss	Vahicle serviced
Ministration Court Court Court Cohin air tiltor replaced / despect	LUZZ INUV Z	203,203 NIVI		Cabin air filter replaced/cleaned
Mississauga, Ontario, Canada • Cabin air filter replaced/cleaned • Air filter replaced			wiississauga, Ontario, Canada	•
Air Inter replaced Oil and filter changed				•

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact DODGE or visit Dodge's website.



This vehicle is not actively declared stolen.

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Apr 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial
2012 Jun 6	7,467 KM	Service Facility	Service Record	Vehicle serviced
2012 Jul 3	12,122 KM	Service Facility	Service Record	Vehicle serviced
2012 Jul 13		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: minor damage with another motor vehicle Damage to left rear
2012 Aug 24	20,384 KM	Service Facility	Service Record	Vehicle serviced
2012 Nov 2	29,060 KM	Service Facility	Service Record	Vehicle serviced
2012 Dec 19	34,300 KM	Service Facility	Service Record	Vehicle serviced
2013 Feb 15	40,214 KM	Service Facility	Service Record	Vehicle serviced
2013 Apr 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2013 Apr 12	49,560 KM	Service Facility	Service Record	Vehicle serviced
2013 May 24	58,579 KM	Service Facility	Service Record	Vehicle serviced
2013 Jul 12	66,643 KM	Service Facility	Service Record	Vehicle serviced
2013 Aug 23	71,288 KM	Service Facility	Service Record	Vehicle serviced
2013 Sep 13	73,665 KM	Service Facility	Service Record	Vehicle serviced
2013 Nov 15	81,401 KM	Service Facility	Service Record	Vehicle serviced
2014 Jan 18	87,159 KM	Service Facility	Service Record	Vehicle serviced
2014 Mar 23	93,675 KM	Service Facility	Service Record	Vehicle serviced
2014 Apr 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2014 May 2	99,939 KM	Service Facility	Service Record	Vehicle serviced
2014 May 14	101,900 KM	Service Facility	Service Record	Vehicle serviced
2014 Jun 13	106,971 KM	Service Facility	Service Record	Vehicle serviced
2014 Jun 30	109,357 KM	Service Facility	Service Record	Vehicle serviced
2014 Jul 4	109,938 KM	Service Facility Belleville, Ontario, Canada	Service Record	Vehicle serviced
2014 Aug 23	117,555 KM	Service Facility	Service Record	Vehicle serviced
2014 Sep 2	118,560 KM	Service Facility	Service Record	Vehicle serviced

5/26/23, 5:24 PM

CARFAX Canada Vehicle History Reports

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Oct 9	129,328 KM	Service Facility	Service Record	Vehicle serviced
2014 Nov 21	130,859 KM	Service Facility	Service Record	Vehicle serviced
2015 Feb 20	138,827 KM	Service Facility	Service Record	Vehicle serviced
2015 Apr 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2015 Apr 10	144,585 KM	Service Facility	Service Record	Vehicle serviced
2015 Jun 11		Service Facility	Service Record	Vehicle serviced
2015 Jul 17		Service Facility	Service Record	Vehicle serviced
2015 Jul 23	155,714 KM	Elegant Motoring Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2015 Sep 15	161,185 KM	Service Facility Belleville, Ontario, Canada	Service Record	Vehicle serviced
2015 Nov 27	173,614 KM	Bayview Chrysler Dodge Ltd Sarnia, Ontario, Canada	Service Record	Vehicle serviced
2016 Jan 12	175,475 KM	Raceway Chrysler Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2016 Apr 8	181,766 KM	Service Facility	Service Record	Vehicle serviced
2016 May 27	184,972 KM	Service Facility	Service Record	Vehicle serviced
2016 Jun 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2016 Aug 12	189,615 KM	Service Facility	Service Record	Vehicle serviced
2016 Sep 6	192,466 KM	Butterworth's Service Centre Inc. Ingersoll, Ontario, Canada	Service Record	Vehicle serviced
2016 Sep 7		Glassford Chrysler Ingersoll, Ontario, Canada	Service Record	Vehicle serviced
2016 Dec 7	200,136 KM	Service Facility	Service Record	Vehicle serviced
2017 Apr 7	206,302 KM	Speedy Auto Service Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2017 May 29	209,049 KM	Speedy Auto Service Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2017 Jun 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial

5/26/23, 5:24 PM

CARFAX Canada Vehicle History Reports

		er frei / frei euna	da venicie mistory reports	,
	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Aug 11	213,611 KM	Service Facility	Service Record	Vehicle serviced
2017 Nov 8	218,411 KM	Speedy Auto Service Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2018 May 24	227,498 KM	Service Facility	Service Record	Vehicle serviced
2018 Jun 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2018 Jul 9	229,631 KM	Service Facility	Service Record	Vehicle serviced
2018 Jul 10		Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 31	234,620 KM	Service Facility	Service Record	Vehicle serviced
2019 May 7	238,534 KM	Service Facility	Service Record	Vehicle serviced
2020 Jan 14	244,076 KM	Service Facility Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2020 Sep 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2021 Mar 29	253,324 KM	Mechaniq Oakville 1 Oakville, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2021 Jul 19	258,750 KM	Taylor Chrysler Dodge Ltd Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 2	283,269 KM	Active Green & Ross Mississauga, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantabile quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this which history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.