

Vehicle History Report #: 49588163 Report Date: November 7, 2023 | 3:52 PM EST Report Status: Complete Reference: 3082

2020 FORD TRANSIT CONNECT XL

Van passenger | 4 Cylinders | Gas NM0GS9E20L1440206 Country of Assembly: Spain Last Reported Odometer: 140,616 KM



Accident/Damage Records Found



Last Registered In: Ontario (Normal)



21 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

(i)

Questions? We're here to help. Visit us at support.carfax.ca

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 07, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS	AMOUNT
2021 Nov 29	Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage	
	Claim amount was CAD\$6,407	
	Vehicle involved in a rear-end collision	
	with another motor vehicle	
	Damage to rear	
	Estimate Estimate Date: 2021 Nov 29	\$7,239.92
	Claim: Collision	\$0.00
	Claim: Other Damage	\$6,407.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
() 2022 Jan 13	n/a	
	Damage Event: Damage repairs performed	
	Repairs to rear end	
() 2023 May 4	Kitchener, Ontario, Canada	
	Auction Announcement: AUCTION ANNOUNCED AS ACCIDENT REPAIR	
🌗 2023 Jun 1	Kitchener, Ontario, Canada	
	Auction Announcement: AUCTION ANNOUNCED AS ACCIDENT REPAIR	
() 2023 Sep 14	Kitchener, Ontario, Canada	
	Auction Announcement: AUCTION ANNOUNCED AS ACCIDENT REPAIR	



🤣 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Oct 1		Meadowvale Ford Mississauga, Ontario, Canada	Vehicle serviced
2019 Oct 25	2,400 KM	Service Facility	 Vehicle serviced Tire(s) changed Tire valve stem(s)/core(s) replaced Tire(s) replaced
2019 Oct 28		Active Green & Ross Ontario, Canada	 Vehicle serviced Maintenance inspection completed Tire(s) replaced
2020 Jan 3	11,338 KM	Active Green & Ross Ontario, Canada	 Vehicle serviced Maintenance inspection completed Oil and filter changed
2020 May 25	21,885 KM	Active Green & Ross Ontario, Canada	 Vehicle serviced Maintenance inspection completed Oil and filter changed Four tires balanced Four tires mounted Tire repaired Tire(s) mounted
2020 Aug 22	31,477 KM	Active Green & Ross Ontario, Canada	 Vehicle serviced Maintenance inspection completed Oil and filter changed
2020 Nov 9	37,665 KM	Active Green & Ross Ontario, Canada	 Vehicle serviced Maintenance inspection completed Brakes serviced Cabin air filter replaced/cleaned Air filter replaced Tire(s) changed Tire pressure sensor checked Oil and filter changed Front brakes serviced Brake rotor(s) resurfaced Rear brakes serviced/adjusted Air filter checked A/C system checked Tire repaired Tire(s) mounted
2021 Feb 5		Service Facility	 Vehicle serviced Oil and filter changed Tire valve stem(s)/core(s) replaced Tire(s) replaced

2021 Apr 12	51,280 KM	Active Green & Ross	Vehicle serviced
	51,200 100		Maintenance inspection completed
		Ontario, Canada	Tire(s) changed
			Oil and filter changed
			Tire valve stem(s)/core(s) replaced
2021 May 26	54,747 KM	Service Facility	Vehicle serviced
			Window replaced
			Windshield calibrated
2021 San 4	66 040 KM	Active Green & Ross	Vehicle serviced
2021 Sep 4	66,949 KM		
		Ontario, Canada	Maintenance inspection completed
			Brakes serviced
			Tire pressure sensor checked
			Tire repaired
			Cabin air filter replaced/cleaned
			Air filter replaced Oil and filter shares al
			Oil and filter changed
			Brake rotor(s) resurfaced
			Brake drum(s) resurfaced
			A/C system checked
			Air filter checked
2021 Nov 8	76,193 KM	Active Green & Ross	Vehicle serviced
202110000	70,155100		Maintenance inspection completed
		Ontario, Canada	Antifreeze/coolant flushed/changed
			Oil and filter changed
			Tire pressure sensor checked
			Wiper(s) replaced
			Cooling system checked
			Wipers/washers checked
			Tire valve stem(s)/core(s) replaced
2022 Jan 13		Service Facility	Vehicle serviced
2022 Mar 4	87,901 KM	Active Green & Ross	Vehicle serviced
		Ontario, Canada	Maintenance inspection completed
			Air filter replaced
			Oil and filter changed
2022 May 14	95,507 KM	Active Green & Ross	Vehicle serviced
	,	Ontario, Canada	Maintenance inspection completed
		Untario, Callaua	Brakes serviced
			Rear brake rotor(s) replaced
			Rear brake pads replaced
			Oil and filter changed
			 Off and filter changed Tire condition and pressure checked
			Brakes checked
			Brake rotor(s) replaced
			Tire repairedTire(s) mounted
2022 Sep 2	107,495 KM	Service Facility	Vehicle serviced
			Radiator cap replaced
			 Cabin air filter replaced/cleaned A/C system checked

			Wiper(s) replacedTires rotatedOil and filter changed
2022 Oct 31	114,867 KM	Service Facility	 Vehicle serviced Tire valve stem(s)/core(s) replaced Tire(s) replaced Transmission fluid changed Oil and filter changed
2023 Jan 7	126,052 KM	Service Facility	 Vehicle serviced Cabin air filter replaced/cleaned A/C system checked Air filter replaced Air filter checked Oil and filter changed
2023 Feb 17	133,098 KM	Service Facility	 Vehicle serviced Transmission fluid changed Wiper(s) replaced Wipers/washers checked Tires rotated Oil and filter changed
2023 Apr 29	135,174 KM	Mcalpine Ford Lincoln Aurora, Ontario, Canada	 Vehicle serviced Transmission checked Transmission fluid changed Transmission replaced
2023 Sep 27	140,616 KM	Dixie Ford Sales Ltd Mississauga, Ontario, Canada	Vehicle serviced

) Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit Ford's website.

Stolen Vehicle Check

🤣 This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed

First Owner Reported Previous Use: Commercial Vehicle colour noted as white

2019 Oct 1		Meadowvale Ford Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Oct 25	2,400 KM	Service Facility	Service Record	Vehicle serviced
2019 Oct 28		Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2020 Jan 3	11,338 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2020 May 25	21,885 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2020 Aug 22	31,477 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 9	37,665 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2021 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as wh
2021 Feb 5		Service Facility	Service Record	Vehicle serviced
2021 Apr 12	51,280 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2021 May 26	54,747 KM	Service Facility	Service Record	Vehicle serviced
2021 Sep 4	66,949 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 8	76,193 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 29	79,423 KM	Police Reported Accident Ontario, Canada	Police Report	 Accident Reported: moderate damage Claim amount was CAD\$6,407 Vehicle involved in a rea end collision with another motor veh Damage to rear
2021 Nov 29		Insurance Records Ontario, Canada		

2021 Nov 29		Insurance Records Ontario, Canada		
2021 Nov 29	81,626 KM	Insurance Records	Estimate Repair	Estimate Date: 2021-11-29
2022 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2022 Jan 13			Damage Event	Damage repairs performed Repairs to rear end
2022 Jan 13		Service Facility	Service Record	Vehicle serviced
2022 Mar 4	87,901 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2022 May 14	95,507 KM	Active Green & Ross Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 2	107,495 KM	Service Facility	Service Record	Vehicle serviced
2022 Oct 31	114,867 KM	Service Facility	Service Record	Vehicle serviced
2023 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2023 Jan 7	126,052 KM	Service Facility	Service Record	Vehicle serviced
2023 Feb 17	133,098 KM	Service Facility	Service Record	Vehicle serviced
2023 Apr 29	135,174 KM	Mcalpine Ford Lincoln Aurora, Ontario, Canada	Service Record	Vehicle serviced
2023 May 4	140,316 KM	Auto Auction Kitchener, Ontario, Canada	Auction Announcement	AUCTION ANNOUNCED AS ACCIDENT REPAIR
2023 Jun 1	225,817 KM	Auto Auction	Auction Announcement	Vehicle sold
2023 Jun 1		Auto Auction Kitchener, Ontario, Canada	Auction Announcement	AUCTION ANNOUNCED AS ACCIDENT REPAIR
2023 Sep 14		Auto Auction Kitchener, Ontario, Canada	Auction Announcement	AUCTION ANNOUNCED AS ACCIDENT REPAIR
2023 Sep 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2023 Sep 27	140,616 KM	Dixie Ford Sales Ltd	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information, service records, recall information, accurace believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly discional all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantabile quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.

