

Vehicle History Report #: 52493316 Report Date: April 8, 2024 | 10:20 AM EDT Report Status: Complete

2016 FORD F250 SUPER DUTY

Pickup | 8 Cylinders | Gas 1FT7W2A61GEC91844 Country of Assembly: United States Last Reported Odometer: 274,063 KM



No Accident/Damage Records Found



Last Registered In: **Ontario (Normal)**



32 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 08, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage



There are no accidents/damage reported on this vehicle.



Registration

 ${\color{red} oldsymbol{\oslash}}$ This vehicle has been registered in the province of ${\color{red} oldsymbol{Ontario}}$ in ${\color{red} oldsymbol{Canada}}$ with ${\color{red} oldsymbol{Normal}}$ branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE ODOMETEI		SOURCE	DETAILS	
2016 Sep 27	17,748 KM	Master Mechanic - Oshawa	Vehicle serviced	
		Oshawa, Ontario, Canada	 Maintenance inspection completed 	
			Brakes checked	
			 Tire condition and pressure checked 	
			Oil and filter changed	
2016 Oct 19	21,737 KM	Master Mechanic - Oshawa	Vehicle serviced	
	•	Oshawa, Ontario, Canada	Maintenance inspection completed	
		Oshawa, Ohtano, Canada	Oil and filter changed	
			Tire condition and pressure checked	
2016 Nov 30	30,362 KM	Master Mechanic - Oshawa	Vehicle serviced	
	30,302 1111		Maintenance inspection completed	
		Oshawa, Ontario, Canada	Oil and filter changed	
			Tire condition and pressure checked	
			Tire pressure monitoring system reset	
			Tire pressure monitoring system checked	
			The pressure monitoring system enected	
2017 Jan 4	35,776 KM	Master Mechanic - Oshawa	Vehicle serviced	
		Oshawa, Ontario, Canada	 Maintenance inspection completed 	
			Oil and filter changed	
			Tire condition and pressure checked	
2017 Feb 1	41,000 KM	Master Mechanic - Oshawa	Vehicle serviced	
		Oshawa, Ontario, Canada	Maintenance inspection completed	
		oonana, omano, canaaa	Oil and filter changed	
			Tire condition and pressure checked	
2017 Mar 27	50,794 KM	Master Mechanic - Oshawa	Vehicle serviced	
		Oshawa, Ontario, Canada	Maintenance inspection completed	
		Oshawa, Ontario, Canada	Oil and filter changed	
			Tire condition and pressure checked	
2017 May 25	62,172 KM	Master Mechanic - Oshawa	Vehicle serviced	
-517 May 25	02,172 KW		Maintenance inspection completed	
		Oshawa, Ontario, Canada	Oil and filter changed	
			Tire condition and pressure checked	
			Drivability/performance checked	
			Brakes checked	
2017 Jun 27	68,524 KM	Master Mechanic - Oshawa	Vehicle serviced	
2017 Juil 27	UU,JZ4 KIVI			
		Oshawa, Ontario, Canada	o o o piaco a	
			Front brake pads replacedEmissions or safety inspection performed	
2017.6	00 6 15 1			
2017 Sep 20	82,942 KM	Master Mechanic - Oshawa	Vehicle serviced	
		Oshawa, Ontario, Canada	Maintenance inspection completedOil and filter changed	
			Tire condition and pressure checked	
			- The condition and pressure checked	

	ODOMETER	SOURCE	DETAILS	
2017 Dec 8	98,588 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	 Vehicle serviced Maintenance inspection completed Oil and filter changed Tire condition and pressure checked Tie rod end(s) replaced Lights checked 	
2018 Feb 22		Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Tire(s) balanced • Tire(s) mounted • Oil and filter changed • Tire condition and pressure checked • Oxygen sensor replaced • Drivability/performance checked • Tire pressure monitoring system reset • Brakes checked	
2018 Apr 30	112,409 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced • Headlight bulb(s) replaced	
2018 Jun 4	123,623 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed Tire condition and pressure checked License plate light bulb(s) replaced Wheel bearings repacked Brakes serviced Rear brake rotor(s) replaced Rear brake pads replaced Rear brakes replaced Rear brakes replaced Front brake pads replaced Front brake rotor(s) replaced Front brake rotor(s) replaced Front brake rotor(s) replaced Front brakes replaced Brakes checked	
2018 Aug 2	132,694 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	 Vehicle serviced Maintenance inspection completed Air filter replaced Oil and filter changed Tire condition and pressure checked Emissions or safety inspection performed 	
2018 Aug 22	135,642 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced	
2018 Sep 25	136,112 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced • Ignition lock cylinder replaced	
2018 Oct 18	144,283 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed • Tire condition and pressure checked • Washer nozzle(s) replaced	
2018 Nov 27		Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced	
2019 Feb 4	160,407 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed • Tire condition and pressure checked • Steering angle sensor replaced • Power steering checked • Steering/suspension checked	

	ODOMETER	SOURCE	Drivability/performance checked	
2019 Apr 3	168,915 KM	Master Mechanic - Oshawa	Vehicle serviced	
		Oshawa, Ontario, Canada	Reverse warning alarm installed	
			 Headlight bulb(s) replaced 	
			Lights checked	
2019 May 16	175,594 KM	Master Mechanic - Oshawa	Vehicle serviced	
,		Oshawa, Ontario, Canada	Maintenance inspection completed	
		Oshawa, Ontario, Canada	Fluids checked	
			Transmission fluid changed	
			Transmission filter replaced	
			Oil and filter changed	
			Tire condition and pressure checked	
2019 Oct 11	198,569 KM	Great Canadian Oil Change	Vehicle serviced	
		Oshawa, Ontario, Canada	Air filter checked	
			Oil and filter changed	
			Fluids checked	
2019 Oct 31	201,897 KM	Attersley Tire Service Inc Oshawa	Vehicle serviced	
		Oshawa, Ontario, Canada	Tire(s) balanced	
2040 5	040 545 :::: :			
2019 Dec 20	212,012 KM	Master Mechanic - Oshawa	Vehicle serviced	
		Oshawa, Ontario, Canada	 Maintenance inspection completed 	
		•	Electrical system checked	
			Wheel bearings repacked	
			Brakes serviced	
			Rear brakes serviced/adjusted	
			Battery/charging system checked	
			Front brake pads replaced	
			Front brakes replaced	
			Light bulb(s) replaced	
			Brakes checked	
			Oil and filter changed	
			Tire condition and pressure checked	
			Alternator repairedAlternator checked	
	219,761 KM	Great Canadian Oil Change	Vehicle serviced	
2020 Feb 20			 Maintenance inspection completed 	
2020 Feb 20		Oshawa, Ontario, Canada		
2020 Feb 20		Osnawa, Ontario, Canada	Oil and filter changed	
	228,807 KM			
	228,807 KM	Master Mechanic - Oshawa	Vehicle serviced	
	228,807 KM			
2020 Feb 20 2020 Apr 20	228,807 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced Tire condition and pressure checked Tire(s) changed	
	228,807 KM	Master Mechanic - Oshawa	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced	
2020 Apr 20	228,807 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed	
2020 Apr 20	228,807 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced	
2020 Apr 20	228,807 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed	
2020 Apr 20 2020 Apr 22	228,807 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed	
2020 Apr 20 2020 Apr 22 2020 May 6		Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced	
2020 Apr 20 2020 Apr 22	228,807 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced	
2020 Apr 20 2020 Apr 22 2020 May 6		Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced	
2020 Apr 20 2020 Apr 22 2020 May 6 2020 Jul 10	244,162 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change North York, Ontario, Canada	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed	
2020 Apr 20 2020 Apr 22 2020 May 6		Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change North York, Ontario, Canada Master Mechanic Barrie West	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed	
2020 Apr 20 2020 Apr 22 2020 May 6 2020 Jul 10	244,162 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change North York, Ontario, Canada	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Maintenance inspection completed Maintenance inspection completed	
2020 Apr 20 2020 Apr 22 2020 May 6 2020 Jul 10	244,162 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change North York, Ontario, Canada Master Mechanic Barrie West	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Maintenance inspection completed Starter replaced	
2020 Apr 20 2020 Apr 22 2020 May 6 2020 Jul 10	244,162 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change North York, Ontario, Canada Master Mechanic Barrie West	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Reverse light bulb(s) replaced	
2020 Apr 20 2020 Apr 22 2020 May 6 2020 Jul 10	244,162 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change North York, Ontario, Canada Master Mechanic Barrie West	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Raintenance inspection completed Maintenance inspection completed Reverse light bulb(s) replaced Light bulb(s) replaced	
2020 Apr 20 2020 Apr 22 2020 May 6 2020 Jul 10	244,162 KM	Master Mechanic - Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change Oshawa, Ontario, Canada Attersley Tire Service Inc Oshawa Oshawa, Ontario, Canada Great Canadian Oil Change North York, Ontario, Canada Master Mechanic Barrie West	Vehicle serviced Tire condition and pressure checked Tire(s) changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle serviced Reverse light bulb(s) replaced	

	ODOMETER	SOURCE	DETAILS	
			Brakes checked	
2022 May 9		John's Quality Auto Service Lindsay, Ontario, Canada	Vehicle serviced • Safety inspection performed	
2022 Oct 13	274,063 KM	John's Quality Auto Service Lindsay, Ontario, Canada	Vehicle serviced • Safety inspection performed	



Open Recalls

Recall #: 22S35 | CLOCKSPRING CONTAMINATION Recall Date: 2022 May 16

Recall Description

ON YOUR VEHICLE, DUST CONTAMINATION MAY LEAD TO A LOSS OF ELECTRICAL CIRCUIT CONNECTION WITH YOUR STEERING WHEEL AND AIRBAG AND WILL ILLUMINATE YOUR AIRBAG WARNING LIGHT IN YOUR VEHICLES INSTRUMENT CLUSTER SHOWN ON THE LEFT.

Remedy

PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPLACE YOUR STEERING WHEELS CLOCK SPRING FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 May 31		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		First Owner Reported
				Previous Use: Fleet
				Vehicle colour noted as white
2016 Sep 27	17,748 KM	Master Mechanic - Oshawa	Service Record	Vehicle serviced
		Oshawa, Ontario, Canada		
2016 Oct 19	21,737 KM	Master Mechanic - Oshawa	Service Record	Vehicle serviced
		Oshawa, Ontario, Canada		
2016 Nov 1		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Fleet
2016 Nov 30	30,362 KM	Master Mechanic - Oshawa	Service Record	Vehicle serviced
		Oshawa, Ontario, Canada		

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including provider a report or or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX.

Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

