

2018 JEEP GRAND CHEROKEE

QUEST AUTOMOTIVE LEASING SERVICES (SECONDARY) | 1C4RJFAG5JC417679 | 162,352 kilometers

Automatic Transmission | 3.6L 6CYL GASOLINE FUEL | 4 Wheel Drive | Ext: BLACK | Int: black

AutoGrade 3.3



21 32
Damages Overview

Photos

Tires Matched

7	6	4	2
32nds	32nds	32nds	32nds

High Value Options

Nav	3d Row	Sunroof	Leather
-----	--------	---------	---------

- Damages **21**
- OBD2 Codes **2**
- CARFAX [View Full Report](#)
- Inspection Type **Standard**
- Inventory Type **Not Provided**
- Odors **Must (Extreme)**

ANNOUNCEMENTS

Pre-Sale: Frame Pass engine has excessive top end noise - repairs over \$750
 engine light on - repairs over \$750
 Additional Disclosure- Jurisdictions Registered:ON
 Additional Disclosure- 10/28/2019- PoliceReportedAccident
 Additional Disclosure- 10/28/2019-11,808.00- HistoryReport, 2019-10-28, CLAIM, 11808.00

MVDA
 No MVDA disclosures have been reported for this vehicle.

Notes

Click to add notes

Purchase Date: May 1, 2024

Final Price:

[Bid History](#)



This vehicle has been sold. If you have questions, please [Contact Us](#) or [Chat With Us](#).

Vehicle Location
BRAMPTON, ON

[Go to My Purchases](#)

DealerBlock Inventory

INSPECTION SUMMARY

Salvage	No	Structural Damage	No
Prior Paint	Not Reported	Keys / Remotes	Emergency (2), Smart (2)
Inspection Type	Standard	Inspected By	ADESA
Manuals	Not Reported	Inspection Date	April 29, 2024
Odors	Must (Extreme)	Odometer Condition	Functions Properly
Driveable	Yes		






















VEHICLE HISTORY



[View Full Report](#)

Important: CARFAX Canada report may contain additional disclosure information NOT included in the condition report OR vehicle detail page. Please carefully review all information before bidding. Disclosed matters are NOT subject to arbitration.

DAMAGES

	Region/Area	Type	Severity
	FRONT Bumper Cover - Front	misaligned	Repair Required
	FRONT Bumper Cover Partial - RF	scratch heavy	3" to 4"
	FRONT Roof Panel - Front	rust	1/8" to 1/2"
	INTERIOR Seat Cushion - LF	worn	Acceptable
	INTERIOR Seat Cushion - LR	stained	Permanent
	INTERIOR Seat Cushion - RR	stained	Permanent
	INTERIOR Warning - Engine	on	Further Diagnosis
	LEFT FENDER Fender - LF	mult scratches/light	4
	LEFT FRONT DOOR Door Edge - LF	scratch heavy	1" to 2"
	LEFT QUARTER/SIDE Qtr Panel - L	scratch light	1/2" to 1"
	LEFT QUARTER/SIDE Wheel Opening Mldg - LR	scratch light	9" to 10"
	LEFT REAR DOOR Door - LR	dent/paint dmg	1/8" to 1/2"
	MECHANICAL "C" Pillar - L	mult dents/no paint dmg	3
	MECHANICAL "C" Pillar - L	scratch heavy	< 1/8"
	REAR Bumper Cvr Partial - LR	scratch light	9" to 10"
	REAR Bumper Cvr Partial - RR	scratch light	1/2" to 1"
	RIGHT FENDER Fender - RF	prev repair	Substd Fish Eyes
	RIGHT FRONT DOOR Door - RF	chipped	5
	RIGHT QUARTER/SIDE Tire - RR	worn	Replacement Required
	RIGHT REAR DOOR Door - RR	chipped	4
	front windshield	cracked	9" to 10"

The above item(s) were noted in an inspection. Be sure to review the pictures of the vehicle, as there may be further information about the damage there. Items noted above will not be eligible for arbitration.

TIRES

	Position	Wheel Type	Wheel Size	Tread	Brand	Tire Size
7	front left tire	Alloy	265/50/20V	7/32"	NEXEN	20"

6	front right tire	Alloy	265/50/20V	6/32"	NEXEN	20"
4	rear left tire	Alloy	265/50/20V	4/32"	NEXEN	20"
2	rear right tire	Alloy	265/50/20V	2/32"	NEXEN	20"
-	spare tire	Not Reported	Not Reported		Not Reported	Full Size Spare

OBD2 CODES

[Learn About Diagnostic Codes](#)

Scanned: April 29, 2024 | 9:14am EDT Codes Last Cleared: 40,722 miles ago

Code	Type	Category	System	Code Description
P0171	Generic	Powertrain	Emissions	System Too Lean Bank 1
P0300	Generic	Powertrain	Emissions	Random/Multiple Cylinder Misfire Detected

We performed a Check Engine Light (CEL) scan. This scan only checks vehicles for standard OBD2 emissions codes. The announcement of the presence of warning lights or OBD2 codes does not exempt a Seller from arbitration responsibilities as defined by the

NAAA. The issue/defect found to be the cause of the light or OBD2 code may be arbitrated policy within the stated time period and dollar amount threshold according to Appendix 1.

VEHICLE DATA

[Original Data](#) Enriched Data

Default View

Vehicle Information

Body Style	4X4	Doors	4	Engine	3.6L 6CYL GASOLINE FUEL
Fuel Type	Gasoline	Transmission	Automatic Transmission	Drivetrain	4 Wheel Drive
Odometer Digits	Not Reported	Exterior Color	BLACK	Interior Color	black
Inventory Type	not provided	Title State	Not Reported	Registration Province	ON

Additional Vehicle Information

Tire Pressure Monitoring System TPMS - Yes

High Value Options

Equipment

back-up camera	parking distance control (pdc)	4WD	AM/FM	POWER DRIVER SEAT	REAR DEFOGGER
heated seats - driver and passenger	satellite radio sirius	5 PASSENGER	CARGO COVER	POWER LIFTGATE	SEAT TYPE - BUCKET
navigation system	sunroof/moonroof	ABS	CLOTH SEATS	POWER LOCKS	SIDE FRONT AIR BAGS
onstar	wood trim	ADJUSTABLE STEERING WHEEL	CRUISE CONTROL	POWER MIRRORS	SPOILER
		AIR BAG	ELECTRIC MIRRORS	POWER STEERING	TRACTION CONTROL
		AIR CONDITIONING	FOG LIGHTS	POWER WINDOWS	

APPRAISAL



Price Analysis

[Open this VIN in Market guide](#)

Based on last 90 days of historical sales data for similar vehicles.

Average Price	\$17,687
Highest Price	\$28,000
Lowest Price	\$7,200

STATEMENTS

No statements are available for this vehicle.

AutoGrade AUTOGRADE is a registered trademark of Cox Automotive, Inc. used with permission.[About AutoGrade](#)