

2018 FORD F-150

ENTERPRISE FLEET MANAGEMENT | [1FTMF1EB5JKF10463](#) | 175,061 kilometers

Automatic Transmission

3.3L 6CYL FLEX FUEL CAPABILITY | 4 Wheel Drive | Ext: white | Int: gray

AutoGrade 2.8




24 26
Damages Overview

Photos

Tires Matched



High Value Options



Damages **24**

CARFAX [View Full Report](#)

Inspection Type **Standard**

Inventory Type **Not Provided**

Odors **No**

ANNOUNCEMENTS

Red: Vehicle Sold As-Is
Additional Disclosure-
Jurisdictions Registered:ON

MVDA
No MVDA disclosures have
been reported for this vehicle.

Notes

Click to add notes

[Watching](#)

Simulcast



Sale Date: June 5, 2024|9:30 am EDT



Sale Ended

Vehicle Location
BRAMPTON, ON

INSPECTION SUMMARY

























Salvage	No	Structural Damage	No
Prior Paint	Not Reported	Keys / Remotes	Combo (3)
Inspection Type	Standard	Inspected By	ADESA
Manuals	Not Reported	Inspection Date	May 21, 2024
Odors	No	Odometer Condition	Functions Properly
Driveable	Yes		

VEHICLE HISTORY



[View Full Report](#)

Important: CARFAX Canada report may contain additional disclosure information NOT included in the condition report OR vehicle detail page. Please carefully review all information before bidding. Disclosed matters are NOT subject to arbitration.

DAMAGES			
	Region/Area	Type	Severity
	FRONT Bumper Cover Upper - Front	chipped	5
	FRONT Overall Vehicle	De-Identify	Removal Required
	INTERIOR Seat Cushion - RF	stained	Permanent
	INTERIOR Steering Wheel	worn	Acceptable
	LEFT FENDER Mud Guard - LF	cracked	4" to 5"
	LEFT FRONT DOOR Door - LF	chipped	10 or more
	LEFT QUARTER/SIDE Bed Side - L	mult scratches/heavy	4
	MECHANICAL "C" Pillar - L	mult dents/paint dmg	10 or more
	MECHANICAL "C" Pillar - L	mult scratches/heavy	10 or more
	MECHANICAL "C" Pillar - R	dent/paint dmg	1/8" to 1/2"
	MECHANICAL Rocker Panel Outer - L	scraped	GR 12"
	REAR Chrome Metal Bumper - Rear	mult dents/no paint dmg	2
	REAR Tail Lamp - LR	cracked	Replacement Required
	REAR Tail Lamp - RR	chipped	Replacement Required
	REAR Tail Lamp - RR	water damage	Replacement Required
	REAR Trailer Hitch	after market	Acceptable
	RIGHT QUARTER/SIDE Bed Side - R	dent/paint dmg	1" to 2"
	RIGHT QUARTER/SIDE Bed Side - R	mult scratches/heavy	10 or more
	front hood	chipped	6
	front hood	dent/no paint dmg	1/8" to 1/2"
	rear tailgate	mult dents/paint dmg	3
	rear tailgate	mult scratches/heavy	10 or more
	rear tailgate protector	hole	Replacement Required
	rear tailgate protector	mult scratches/heavy	Replacement Required

The above item(s) were noted in an inspection. Be sure to review the pictures of the vehicle, as there may be further information about the damage there. Items

noted above will not be eligible for arbitration.

TIRES

	Position	Wheel Type	Wheel Size	Tread	Brand	Tire Size	
9	front left tire	Steel	265/70/17T	9/32"	Hankook	17"	☼
7	front right tire	Steel	265/70/17T	7/32"	Hankook	17"	☼
8	rear left tire	Steel	265/70/17T	8/32"	Hankook	17"	☼
8	rear right tire	Steel	265/70/17T	8/32"	Hankook	17"	☼
-	spare tire	Steel	Not Reported		Not Reported	Full Size Spare	

VEHICLE DATA

[Original Data](#)

[Enriched Data](#)

Default View

Vehicle Information

Body Style	4WD REG CAB 8' BOX	Doors	2	Engine	3.3L 6CYL FLEX FUEL CAPABILITY
Fuel Type	Flex Fuel	Transmission	Automatic Transmission	Drivetrain	4 Wheel Drive
Odometer Digits	Not Reported	Exterior Color	white	Interior Color	gray
Inventory Type	not provided	Title State	Not Reported	Registration Province	ON

Additional Vehicle Information

Tire Pressure Monitoring System TPMS - Yes

High Value Options

Equipment

back-up camera	satellite radio sirius	3 PASSENGER	AIR CONDITIONING	FOG LIGHTS	POWER STEERING
onstar		4WD	AM/FM	HARD TOP	POWER WINDOWS
		ABS	BACK-UP CAMERA	POWER LOCKS	RUNNING BOARDS
		ADJUSTABLE STEERING WHEEL	CLOTH SEATS	POWER MIRRORS	SIDE FRONT AIR BAGS
		AIR BAG	CRUISE CONTROL	POWER MIRRORS YES	TRACTION CONTROL

APPRAISAL



Price Analysis

[Open this VIN in Market guide](#)

Based on last 90 days of historical sales data for similar vehicles.

Average Price	\$26,400
Highest Price	\$26,400
Lowest Price	\$26,400

STATEMENTS

No statements are available for this vehicle.

