

2014 GMC SIERRA 3500HD

JIM PEPLINSKI LEASING | 1GT422CG3EF181504 | 175,088 kilometers | Automatic Transmission
6.0L 8CYL FLEX FUEL CAPABILITY | 4 Wheel Drive | Ext: white | Int: brown

AutoGrade 1.3



41 33
Damages Overview
Photos

ANNOUNCEMENTS

Structural Damage as is
Additional Disclosure- Jurisdictions Registered:ON

MVDA
No MVDA disclosures have been reported for this vehicle.

Notes

Click to add notes

Purchase Date: May 22, 2024 Final Price: \$10,800

[Bid History](#)



This vehicle has been sold. If you have questions, please [Contact Us](#) or [Chat With Us](#).

Vehicle Location
BRAMPTON, ON

[Go to My Purchases](#)

Tires Matched

16	13	11	10
32nds	32nds	32nds	32nds

High Value Options

Nav	3d Row	Sunroof	Leather
-----	--------	---------	---------

Damages 41

CARFAX [View Full Report](#)

Inspection Type [Standard](#)

Inventory Type **Not Provided**

Odors Must (Mild)

INSPECTION SUMMARY






















Salvage	No	Structural Damage	No
Prior Paint	Not Reported	Keys / Remotes	Remote (2), Standard (2)
Inspection Type	Standard	Inspected By	ADESA
Manuals	Not Reported	Inspection Date	May 3, 2024
Odors	Must (Mild)	Odometer Condition	Functions Properly
Driveable	Yes		

VEHICLE HISTORY



[View Full Report](#)

Important: CARFAX Canada report may contain additional disclosure information NOT included in the condition report OR vehicle detail page. Please carefully review all information before bidding. Disclosed matters are NOT subject to arbitration.

DAMAGES			
	Region/Area	Type	Severity
	FRONT Bumper - Front	dent/no paint dmg	GR 12"
	FRONT Bumper - Front	mult scratches/heavy	3
	FRONT Headlight - L	faded	Acceptable
	FRONT Headlight - R	faded	Acceptable
	FRONT Overall Interior	Excessively Dirty	Unacceptable
	INTERIOR Door Panel - LF	mult scratches/heavy	2
	INTERIOR Door Panel - RR	mult scratches/heavy	2
	INTERIOR Headliner	stained	Permanent
	INTERIOR Seat - LF	torn	GR 12"
	INTERIOR Seat - RF	torn	GR 12"
	INTERIOR Seat Adjustment Handle - RF	broken	Replacement Required
	INTERIOR Steering Wheel	worn	Acceptable
	LEFT FENDER Fender - LF	mult dents/no paint dmg	3
	LEFT FENDER Fender - LF	rust	3" to 4"
	LEFT FRONT DOOR Door - LF	mult dents/paint dmg	2
	LEFT FRONT DOOR Door Lower - LF	scratch heavy	GR 12"
	LEFT QUARTER/SIDE Bed Side - L	mult dents/paint dmg	10 or more
	LEFT QUARTER/SIDE Bed Side - L	prev repair	Substd Repair
	LEFT QUARTER/SIDE Bed Side - L	rust	GR 12"
	LEFT QUARTER/SIDE Cab Corner Panel - L	mult scratches/heavy	3
	LEFT REAR DOOR Door - LR	prev repair	Substd Repair
	MECHANICAL Rocker Panel Inner - L	Hole (Structure)	1" to 2"
	MECHANICAL Rocker Panel Inner - R	Hole (Structure)	1" to 2"
	MECHANICAL Rocker Panel Outer - L	hole	1" to 2"
	MECHANICAL Rocker Panel Outer - L	scratch heavy	GR 12"

	MECHANICAL Rocker Panel Outer - L	scratch heavy	GR 12"
	MECHANICAL Rocker Panel Outer - R	hole	1" to 2"
	MECHANICAL Rocker Panel Outer - R	scratch heavy	GR 12"
	REAR Brake Light - Center	cracked	Replacement Required
	REAR Bumper Cover - Rear	mult dents/no paint dmg	3
	REAR Inside Bed	mult dents/paint dmg	10 or more
	REAR Tail Lamp - LR	scratch heavy	Replacement Required
	RIGHT FRONT DOOR Door - RF	mult dents/paint dmg	3
	RIGHT FRONT DOOR Door Lower - RF	rust	GR 12"
	RIGHT QUARTER/SIDE Bed Side - R	mult dents/no paint dmg	10 or more
	RIGHT QUARTER/SIDE Bed Side - R	rust	GR 12"
	RIGHT REAR DOOR Door Upper - RR	hole	1/2" to 1"
	front hood	mult scratches/heavy	10 or more
	front roof panel	dent/no paint dmg	GR 12"
	front windshield	cracked	1/2" to 1"
	rear tailgate	mult dents/paint dmg	4
	rear tailgate	prev repair	Substd Repair

The above item(s) were noted in an inspection. Be sure to review the pictures of the vehicle, as there may be further information about the damage there. Items noted above will not be eligible for arbitration.

TIRES

	Position	Wheel Type	Wheel Size	Tread	Brand	Tire Size
16	front left tire	Alloy	265/70/18R	16/32"	Firestone	18"
13	front right tire	Alloy	265/70/18R	13/32"	Firestone	18"
11	rear left tire	Alloy	265/70/18R	11/32"	Firestone	18"
10	rear right tire	Alloy	265/70/18R	10/32"	Firestone	18"
4	spare tire	Not Reported	Not Reported	4/32"	Not Reported	Full Size Spare

VEHICLE DATA

[Original Data](#)

Enriched Data

Default View

Vehicle Information

Body Style	4WD CREW CAB 167"	Doors	4	Engine	6.0L 8CYL FLEX FUEL CAPABILITY
Fuel Type	Flex Fuel	Transmission	Automatic Transmission	Drivetrain	4 Wheel Drive
Odometer Digits	Not Reported	Exterior Color	white	Interior Color	brown
Inventory Type	not provided	Title State	Not Reported	Registration Province	ON

Additional Vehicle Information

Tire Pressure Monitoring System TPMS - Yes

High Value Options

Equipment

onstar	4WD	ADJUSTABLE STEERING WHEEL	AM/FM	FOG LIGHTS
	6 PASSENGER	AIR BAG	CLOTH SEATS	HARD TOP
	ABS	AIR CONDITIONING	CRUISE CONTROL	POWER LOCKS
	POWER STEERING	POWER WINDOWS		

APPRAISAL



Price Analysis

[Open this VIN in Market guide](#)

Based on last 90 days of historical sales data for similar vehicles.

Average Price	\$9,700
Highest Price	\$10,800
Lowest Price	\$8,600

STATEMENTS

No statements are available for this vehicle.

AutoGrade AUTOGRADE is a registered trademark of Cox Automotive, Inc. used with permission.[About AutoGrade](#)