

Vehicle History Report #: 54013821
Report Date: June 13, 2024 | 4:08 PM EDT
Report Status: Complete

2018 FORD EXPLORER

Sport utility vehicle | 6 Cylinders | Gas 1FM5K7B8XJGB60967 Country of Assembly: United States Last Reported Odometer: 163,791 KM



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



22 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 13, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS Vehicle serviced		
2018 May 5		Formula Ford			
		Pickering, Ontario, Canada	 Pre-delivery inspection completed 		
		3, ,	Recommended maintenance performed		
			VIN glass etching vin etched		
2018 Sep 14		Formula Ford	Vehicle serviced		
		Pickering, Ontario, Canada	Vehicle washed/detailed		
2018 Nov 22	8,900 KM	Shanahan Ford Lincoln	Vehicle serviced		
		Newmarket, Ontario, Canada	Oil and filter changed		
		, ,	Four tires balanced		
			Four tires mounted		
2019 Mar 18	24,736 KM	Jiffy Lube	Vehicle serviced		
		Newmarket, Ontario, Canada	Maintenance inspection completed		
		, ,	Oil and filter changed		
			 Antifreeze/coolant checked 		
			 Fluids checked 		
			Windshield washer checked		
2019 May 28	34,866 KM	Midas Auto Service Experts	Vehicle serviced		
		Newmarket, Ontario, Canada	Oil and filter changed		
			 Tire(s) mounted 		
			Tire(s) balanced		
2019 Aug 29	49,378 KM	Jiffy Lube	Vehicle serviced		
		Newmarket, Ontario, Canada	 Maintenance inspection completed 		
			Oil and filter changed		
			Air filter checked		
			 Fluids checked 		
			Windshield washer checked		
			Cabin air filter replaced/cleaned		
2019 Nov 11	58,723 KM	Midas Auto Service Experts	Vehicle serviced		
		Newmarket, Ontario, Canada	Oil and filter changed		
			 Tire(s) mounted 		
			Tire(s) balanced		

	ODOMETER	SOURCE	DETAILS
2020 Mar 20	77,715 KM	Midas Auto Service Experts	Vehicle serviced
		Newmarket, Ontario, Canada	Brakes checked
			Rear brake pads replaced
			 Rear brake rotor(s) replaced
			Brakes serviced
2020 May 5	80,715 KM	Midas Auto Service Experts	Vehicle serviced
•		Newmarket, Ontario, Canada	Oil and filter changed
		,	Tire(s) mounted
			Tire(s) balanced
2020 Oct 17		Jiffy Lube	Vehicle serviced
		Newmarket, Ontario, Canada	Maintenance inspection completed
		Newmarket, Omano, Canada	Oil and filter changed
			Fluids checked
			Windshield washer checked
2020 Nov 27		Mides Auto Comiles Experts	Vakiala asmisad
2020 Nov 27		Midas Auto Service Experts	Vehicle serviced
		Newmarket, Ontario, Canada	• Tire(s) mounted
			Tire(s) balanced
			Wiper(s) replaced
2021 Mar 3	107,190 KM	Jiffy Lube	Vehicle serviced
		Newmarket, Ontario, Canada	Maintenance inspection completed
		, ,	Oil and filter changed
			Fluids checked
			Windshield washer checked
2021 Jun 7	114,346 KM	Midas Auto Service Experts	Vehicle serviced
2021 juil 7	111,510100	•	Oil and filter changed
		Newmarket, Ontario, Canada	Tire(s) mounted
			Tire(s) balanced
2021 Oct 7	126,136 KM	Jiffy Lube	Vehicle serviced
2021 Oct 7	120,130 KW		
		Newmarket, Ontario, Canada	Maintenance inspection completedOil and filter changed
			Fluids checked
			Windshield washer checked
2024 0 -+ 20	120 000 1/14	NA: des Aute Comites Françoite	Vahiala associated
2021 Oct 28	129,800 KM	Midas Auto Service Experts	Vehicle serviced
		Newmarket, Ontario, Canada	Air filter replaced
2021 Nov 25	133,559 KM	Midas Auto Service Experts	Vehicle serviced
		Newmarket, Ontario, Canada	Tire(s) mounted
		, ,	Tire(s) balanced
2021 Dec 1	134,115 KM	Jiffy Lube	Vehicle serviced
		Newmarket, Ontario, Canada	Maintenance inspection completed
		. termanici, ontario, canada	Oil and filter changed
			Fluids checked
			Windshield washer checked
2023 Feb 15	149,265 KM	Jiffy Lube	Vehicle serviced
2025 1 CD 15	177,200 KIVI	· •	Oil and filter changed
		Whitby, Ontario, Canada	Air filter replaced
2022 1 0	1EE 2E0 1/8 #	CTE Auto Contro	Vahiela sawiisad
2023 Jun 9	155,250 KM	STE Auto Centre	Vehicle serviced
		Whitby, Ontario, Canada	Brake fluid flushed/changed
			Brakes serviced
			Brake rotor(s) replaced
			Brake pads replaced
			Brake caliper(s) replaced Brake replaced
			Rear brake pads replaced
			Prakes shocked
			Brakes checkedFront brake pads replaced



Open Recalls

Recall #: 21S22 | ROOF RACK TRIM DETACHMENT Recall Date: 2021 May 10

Recall Description

THE ROOF RAIL COVERS MAY BECOME DETACHED FROM YOUR VEHICLE.

Remedy

PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND SECURE THE ROOF RAIL COVER FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website. (https://www.ford.com/support/recalls/)

Recall #: 24S02 | EXTERIOR A PILLAR APPLIQUE INSPECTION Recall Date: 2024 Jan 23

Recall Description

IN SOME OF THE AFFECTED VEHICLES IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.

Remedy

FORD MOTOR COMPANY IS WORKING CLOSELY WITH ITS SUPPLIERS TO PRODUCE PARTS FOR THIS REPAIR. WHEN PARTS BECOME AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE PARTS AND LABOR. PARTS ARE ANTICIPATED TO BE AVAILABLE TOWARD THE LATTER HALF OF 2024.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed,



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 May 5		Formula Ford Pickering, Ontario, Canada	Service Record	Vehicle serviced
2018 Sep 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black
2018 Sep 14		Formula Ford Pickering, Ontario, Canada	Service Record	Vehicle serviced
2018 Nov 22	8,900 KM	Shanahan Ford Lincoln Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 18	24,736 KM	Jiffy Lube Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 May 28	34,866 KM	Midas Auto Service Experts Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 29	49,378 KM	Jiffy Lube Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 11	58,723 KM	Midas Auto Service Experts Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2020 Mar 20	77,715 KM	Midas Auto Service Experts Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2020 May 5	80,715 KM	Midas Auto Service Experts Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 17		Jiffy Lube Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 27		Midas Auto Service Experts Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2021 Mar 3	107,190 KM	Jiffy Lube Newmarket, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 May 10		FORD	Recall	Manufacturer Recall Issued Recall # 21S22
2021 Jun 7	114,346 KM	Midas Auto Service Experts Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 7	126,136 KM	Jiffy Lube Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 28	129,800 KM	Midas Auto Service Experts Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 25	133,559 KM	Midas Auto Service Experts Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2021 Dec 1	134,115 KM	Jiffy Lube Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2022 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2023 Feb 15	149,265 KM	Jiffy Lube Whitby, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 9	155,250 KM	STE Auto Centre Whitby, Ontario, Canada	Service Record	Vehicle serviced
2023 Jul 14	155,701 KM	STE Auto Centre Whitby, Ontario, Canada	Service Record	Vehicle serviced
2023 Sep 5	158,649 KM	STE Auto Centre Whitby, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2023 Dec 4	163,791 KM	STE Auto Centre Whitby, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 23		FORD	Recall	Manufacturer Recall Issued Recall # 24S02

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

