

2018 JAGUAR F-PACE 20D PRESTIGE

OPENLANE CANADA INC.- OPEN FLEET '&' LEASE CONSIGNORS | [SADCK2FN5JA281718](#)

166,629 kilometers | Automatic Transmission | 2.0L 4CYL DIESEL FUEL | All Wheel Drive

Ext: BLACK Int: tan



25 32
Damages Overview

Photos

ANNOUNCEMENTS

Timing chain Issue - repair over \$ 750

Additional Disclosure-Jurisdictions Registered:ON

MVDA
No MVDA disclosures have been reported for this vehicle.

Purchase Date: October 9, 2024 Purchase Price: \$9,100

[Bid History](#)



This vehicle has been sold. If you have questions, please [Contact Us](#) or [Chat With Us](#).

Vehicle Location
BRAMPTON, ON

Tires Matched

4	3	4	3
32nds	32nds	32nds	32nds

Damages **25**

OBD2 Codes **0**

CARFAX [View Full Report](#)

High Value Options

Nav	3d Row	Sunroof	Leather

Inspection Type **Standard** ⓘ

Inventory Type **Not Provided**

Odors **No**

INSPECTION SUMMARY


























Salvage	No	Structural Damage	No
Prior Paint	Not Reported	Keys / Remotes	Emergency (1), Smart (1)
Inspection Type	Standard ⓘ	Inspected By	ADESA
Manuals	Not Reported	Inspection Date	September 23, 2024
Odors	No	Odometer Condition	Functions Properly
Driveable	Yes		

VEHICLE HISTORY



[View Full Report](#)

Important: CARFAX Canada report may contain additional disclosure information NOT included in the condition report OR vehicle detail page. Please carefully review all information before bidding. Disclosed matters are NOT subject to arbitration.

DAMAGES			
	Region/Area	Type	Severity
	FRONT Bumper Cover - Front	chipped	10 or more
	FRONT Bumper Cover - Front	scratch heavy	3" to 4"
	FRONT Headlight - L	chipped	Replacement Required
	FRONT Headlight - R	chipped	Replacement Required
	INTERIOR Seat Back - LF	worn	Acceptable
	INTERIOR Steering Wheel	worn	Acceptable
	LEFT FENDER Fender - LF	chipped	4
	LEFT FRONT DOOR Door - LF	chipped	4
	LEFT REAR DOOR Door - LR	mult scratches/heavy	8
	MECHANICAL Camshaft Seal	leak	Repair Required
	MECHANICAL Rear Main Seal	leak	Repair Required
	REAR Bumper Cover - Rear	mult scratches/heavy	7
	REAR Liftgate Trim Panel	mult scratches/heavy	6
	RIGHT FENDER Fender - RF	dent/paint dmg	1/2" to 1"
	RIGHT FENDER Tire - RF	worn	Replacement Required
	RIGHT FRONT DOOR Door - RF	chipped	2
	RIGHT FRONT DOOR Door - RF	mult scratches/heavy	3
	RIGHT FRONT DOOR Door - RF	scuffed	1" to 2"
	RIGHT QUARTER/SIDE Qtr Panel - R	scratch heavy	2" to 3"
	RIGHT QUARTER/SIDE Tire - RR	worn	Replacement Required
	RIGHT REAR DOOR Door - RR	dent/no paint dmg	1/2" to 1"
	RIGHT REAR DOOR Door - RR	dent/paint dmg	1/8" to 1/2"
	RIGHT REAR DOOR Door - RR	scuffed	1/8" to 1/2"
	front hood	chipped	8
	front windshield	star in glass	1" to 2"



front windshield

star in glass

F 0 2

The above item(s) were noted in an inspection. Be sure to review the pictures of the vehicle, as there may be further information about the damage there. Items noted above will not be eligible for arbitration.

TIRES

4	front left tire	255/55/19W Alloy	4/32"	19"	Goodyear
3	front right tire	255/55/19W Alloy	3/32"	19"	Goodyear
4	rear left tire	255/55/19W Alloy	4/32"	19"	Goodyear
3	rear right tire	255/55/19W Alloy	3/32"	19"	Goodyear
4	spare tire	Wheel Not Reported	4/32"	Compact Spare	Brand Not Reported

OBD2 CODES

[Learn About Diagnostic Codes](#)

Scanned: September 23, 2024 | 12:29pm EDT Codes Last Cleared: 322 miles ago

No diagnostic codes have been reported for this vehicle.

We performed a Check Engine Light (CEL) scan. This scan only checks vehicles for standard OBD2 emissions codes. The announcement of the presence of warning lights or OBD2 codes does not exempt a Seller from arbitration responsibilities as defined by the NAAA policy. The issue/defect found to be the cause of the light or OBD2 code may be arbitrated within the stated time period and dollar amount threshold according to Appendix 1.

VEHICLE DATA

[Original Data](#)

Enriched Data

Default View

Vehicle Information

Body Style	AWD	Doors	4
Engine	2.0L 4CYL DIESEL FUEL	Fuel Type	Diesel
Transmission	Automatic Transmission	Drivetrain	All Wheel Drive
Odometer Digits	Not Reported	Exterior Color	BLACK
Interior Color	tan	Inventory Type	not provided
Title State	Not Reported	Registration Province	ON

Additional Vehicle Information

Active Parking Assist Yes
Tire Pressure Monitoring System TPMS - Yes

High Value Options

back-up camera	onstar
drive train - all wheel	panorama roof
hd radio	parking distance control (pdc)
heated seats - driver and passenger	rain sensor front windshield
leather	satellite radio sirius
memory seat	sunroof
navigation system	

Equipment

- 5 PASSENGER
- ADJUSTABLE STEERING WHEEL
- AIR BAG
- AIR CONDITIONING
- AM/FM
- CARGO COVER
- CRUISE CONTROL
- POWER DRIVER SEAT
- POWER FOLDING MIRRORS
- POWER LIFTGATE
- POWER LOCKS
- POWER MIRRORS
- POWER MIRRORS YES
- POWER STEERING
- POWER WINDOWS
- REAR DEFOGGER
- REMOTE START
- TRACTION CONTROL

APPRAISAL



Price Analysis

[Open this VIN in Market guide](#)

Based on last 90 days of historical sales data for similar vehicles.

Average Price	\$14,669
Highest Price	\$18,700
Lowest Price	\$9,100

STATEMENTS

No statements are available for this vehicle.