



1C4AJWBG7FL517916 [2024-11-28 - BY DARRIN B.]



VEHICLE CATEGORY: SUV/VAN
VIN: 1C4AJWBG7FL517916
YEAR: 2015
MAKE: JEEP
MODEL: WRANGLER
TRIM: SAHARA 4WD
BODY STYLE: SPORT UTILITY 2-DR
DISTANCE TRAVELLED: 177762
MILEAGE UNIT: KILOMETERS



3.3

Vehicle Details

GENERAL

VEHICLE CATEGORY:	SUV/Van	VIN:	1C4AJWBG7FL517916	YEAR:	2015
MAKE:	Jeep	MODEL:	Wrangler	TRIM:	Sahara 4WD
BODY STYLE:	SPORT UTILITY 2-DR	DISTANCE TRAVELLED:	177762	MILEAGE UNIT:	Kilometers

VEHICLE DETAILS

TRANSMISSION-LONG:	5-Speed Automatic 6-Speed Manual	DRIVELINE:	4WD	ANTI-BRAKE SYSTEM:	4-Wheel ABS
STEERING TYPE:	Recirc	OPTIONAL SEATING:	No	POWER DOOR LOCKS:	Std.
VEHICLE ANTI-THEFT:	Std.	4WD/AWD:	Std.	ABS BRAKES:	Std.
ELECTRONIC BRAKE ASSISTANCE:	Std.	TRACTION CONTROL:	Std.	DRIVER AIRBAG:	Std.

FRONT SIDE AIRBAG:	No	FRONT SIDE AIRBAG WITH HEAD PROTECTION:	No	PASSENGER AIRBAG:	Std.
SIDE HEAD CURTAIN AIRBAG:	No	SECOND ROW SIDE AIRBAG:	No	SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION:	No
ELECTRONIC PARKING AID:	Yes	KEYLESS ENTRY:	Std.	REMOTE IGNITION:	No
CRUISE CONTROL:	Std.	POWER WINDOWS:	Std.	TOW HITCH RECEIVER:	Yes
TOWING PREPARATION PACKAGE:	No	VEHICLE LOCATION:	North Toronto Auction.	STOCK NUMBER:	271081
EXTERIOR COLOUR:	Gray	PAINT:	Fair	DOORS NUMBER:	2
PASSENGERS:	2	VEHICLE ADDITIONAL INFORMATION:	None.	ROOF:	Convertible

INTERIOR DETAILS

STANDARD SEATING:	4	AIR CONDITIONING:	Yes and the AC bliws cold in this Jeep.	SEPARATE DRIVER/FRONT PASSENGER CLIMATE CONTROLS:	No
TILT STEERING:	Std.	TILT STEERING COLUMN:	Std.	HEATED STEERING WHEEL:	No
LEATHER STEERING WHEEL:	Yes	STEERING WHEEL MOUNTED CONTROLS:	Std.	TIRE PRESSURE MONITOR:	Std.
TRIP COMPUTER:	Std.	AM/FM RADIO:	Yes	CASSETTE PLAYER:	No
CD PLAYER:	Std.	CD CHANGER:	No	DVD PLAYER:	No
VOICE ACTIVATED TELEPHONE:	No	NAVIGATION AID:	No	FRONT COOLED SEAT:	No
FRONT HEATED SEAT:	No	IS THERE A REVERSE CAMERA?:	Yes	INTERIOR COLOUR:	Gray
SAFETY DETECTION:	N/A	UPHOLSTERY:	Cloth	ODOMETER DISPLAY:	Digital

FULL-VIEW CAMERA: No

MECHANICAL

CYLINDERS: 6 **ENGINE SIZE:** 3.6L V6 DOHC 24V FFV **BRAKE CONDITION:** Average

FUEL LEVEL: Empty **ENGINE TUNE:** Good **TRANSMISSION CONDITION:** Good

STEERING CONDITION: Good **SUSPENSION CONDITION:** Average **EXHAUST:** Good

FUEL TYPE: Gas **DRIVABLE:** Yes **MECHANICAL ADDITIONAL INFORMATION:** The engine warning light is on. Transmission (limp mode) and power train problems (4x4 problems). The oil pan is also seeping oil.

TIRES

SPARE TIRE: Full Size,Yes **TIRE CONDITION:** Good **TIRE SIZE:** 255 70 18

WINTER TIRES: No **WHEEL COVERS:** Alloys **EXTRA TIRE INCLUDED:** No

TIRES ADDITIONAL INFORMATION: Tires are all terrain.

DOCUMENTATION

KEYS PRESENT: Yes **NUMBER OF KEYS:** 2 **KEY FOBS PRESENT:** No

NUMBER OF KEY FOBS: 0 **LICENCE PLATES ON VEHICLE:** No **CIGARETTE SMOKE ODOUR:** No


DECALS ON VEHICLE: No **PET ODOUR/HAIR PRESENT :** No **OWNERSHIP PRESENT:** No

OWNERSHIP REGION: Unknown **MANUALS PRESENT:** No **NAV SOFTWARE:** N/A

PERSONAL EFFECTS: Yes. I cooler and an empty blue Makita case. **DOCUMENTATION ADDITIONAL INFORMATION:** The two rear seats are missing invthis jeep. They were not in it when it arrived.

Map


Route distance:




Condition Map





PLEASE CLICK ON MAP TO VIEW THE DAMAGES.

Enviro Paint Damage
Tread Depth
Heavy Scratch
Chipped



DAMAGE LIST

Part	Damage	Description	Images
Hood	<ul style="list-style-type: none"> enviro paint damage 	<ul style="list-style-type: none"> 12 inches 	 <p>Nov 1 2024</p>
Left Front Tire	<ul style="list-style-type: none"> tread depth 	<ul style="list-style-type: none"> 2 mm 	
Left Qtr Panel	<ul style="list-style-type: none"> enviro paint damage 	<ul style="list-style-type: none"> 12 inches 	

			 Nov 1 2024
Left Rear Tire	<ul style="list-style-type: none"> tread depth 	<ul style="list-style-type: none"> 5 mm 	
Right Bed Side	<ul style="list-style-type: none"> heavy scratch 	<ul style="list-style-type: none"> 12 inches 	 Nov 1 2024
Right Front Tire	<ul style="list-style-type: none"> tread depth 	<ul style="list-style-type: none"> 3 mm 	
Right Qtr Panel	<ul style="list-style-type: none"> enviro paint damage 	<ul style="list-style-type: none"> 12 inches 	 Nov 1 2024
Right Rear Tire	<ul style="list-style-type: none"> tread depth 	<ul style="list-style-type: none"> 4 mm 	
Tailgate	<ul style="list-style-type: none"> chipped 	<ul style="list-style-type: none"> 1 	 Nov 1 2024

Signature

Darrin B

Media

IMAGES

Please be advised that if there is a discrepancy between a picture location and the location of the report the image will show a message

