



1GAZGLFG8H1161302 [2025-03-24 - BY STEVEY HANEY]



**VEHICLE CATEGORY:** SUV/VAN  
**VIN:** 1GAZGLFG8H1161302  
**YEAR:** 2017  
**MAKE:** CHEVROLET  
**MODEL:** EXPRESS  
**TRIM:** LS 3500  
**BODY STYLE:** SPORTS VAN  
**DISTANCE TRAVELLED:** 187973  
**MILEAGE UNIT:** KILOMETERS



3.4

### Vehicle Details

#### GENERAL

<b>VEHICLE CATEGORY:</b>	SUV/Van	<b>VIN:</b>	1GAZGLFG8H1161302	<b>YEAR:</b>	2017
<b>MAKE:</b>	Chevrolet	<b>MODEL:</b>	Express	<b>TRIM:</b>	LS 3500
<b>BODY STYLE:</b>	SPORTS VAN	<b>DISTANCE TRAVELLED:</b>	187973	<b>MILEAGE UNIT:</b>	Kilometers

#### VEHICLE DETAILS

<b>TRANSMISSION-LONG:</b>	6-Speed Automatic	<b>DRIVELINE:</b>	RWD	<b>ANTI-BRAKE SYSTEM:</b>	4-Wheel ABS
<b>STEERING TYPE:</b>	Recirc	<b>OPTIONAL SEATING:</b>	NA	<b>POWER DOOR LOCKS:</b>	Yes
<b>VEHICLE ANTI-THEFT:</b>	NA	<b>4WD/AWD:</b>	2wd	<b>ABS BRAKES:</b>	Std.
<b>ELECTRONIC BRAKE ASSISTANCE:</b>	NA	<b>TRACTION CONTROL:</b>	Yes	<b>DRIVER AIRBAG:</b>	Std.

<b>FRONT SIDE AIRBAG:</b>	Std.	<b>FRONT SIDE AIRBAG WITH HEAD PROTECTION:</b>	NA	<b>PASSENGER AIRBAG:</b>	Std.
<b>SIDE HEAD CURTAIN AIRBAG:</b>	Std.	<b>SECOND ROW SIDE AIRBAG:</b>	NA	<b>SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION:</b>	NA
<b>ELECTRONIC PARKING AID:</b>	NA	<b>KEYLESS ENTRY:</b>	Yes	<b>REMOTE IGNITION:</b>	Yes
<b>CRUISE CONTROL:</b>	Yes	<b>POWER WINDOWS:</b>	Yes	<b>TOW HITCH RECEIVER:</b>	NA
<b>TOWING PREPARATION PACKAGE:</b>	NA	<b>VEHICLE LOCATION:</b>	NTA	<b>STOCK NUMBER:</b>	271108
<b>EXTERIOR COLOUR:</b>	Silver	<b>PAINT:</b>	Fair	<b>DOORS NUMBER:</b>	4
<b>PASSENGERS:</b>	12	<b>VEHICLE ADDITIONAL INFORMATION:</b>	Check engine and tps lights. Drivers seat torn.	<b>ROOF:</b>	Regular

INTERIOR DETAILS

<b>STANDARD SEATING:</b>	12	<b>AIR CONDITIONING:</b>	Yes	<b>SEPARATE DRIVER/FRONT PASSENGER CLIMATE CONTROLS:</b>	NA
<b>TILT STEERING:</b>	NA	<b>TILT STEERING COLUMN:</b>	NA	<b>HEATED STEERING WHEEL:</b>	NA
<b>LEATHER STEERING WHEEL:</b>	Yes	<b>STEERING WHEEL MOUNTED CONTROLS:</b>	Yes	<b>TIRE PRESSURE MONITOR:</b>	Yes
<b>TRIP COMPUTER:</b>	Yes	<b>AM/FM RADIO:</b>	Yes	<b>CASSETTE PLAYER:</b>	NA
<b>CD PLAYER:</b>	Yes	<b>CD CHANGER:</b>	NA	<b>DVD PLAYER:</b>	Yes
<b>VOICE ACTIVATED TELEPHONE:</b>	NA	<b>NAVIGATION AID:</b>	NA	<b>FRONT COOLED SEAT:</b>	NA
<b>FRONT HEATED SEAT:</b>	NA	<b>IS THERE A REVERSE CAMERA?:</b>	No	<b>INTERIOR COLOUR:</b>	Grey
<b>SAFETY DETECTION:</b>	N/A	<b>UPHOLSTERY:</b>	Cloth	<b>ODOMETER DISPLAY:</b>	Digital

**FULL-VIEW CAMERA:** No

MECHANICAL

**CYLINDERS:** 8                      **ENGINE SIZE:** 6.0                      **BRAKE CONDITION:** Average

**FUEL LEVEL:** Empty                      **ENGINE TUNE:** Average                      **TRANSMISSION CONDITION:** Average

**STEERING CONDITION:** Average                      **SUSPENSION CONDITION:** Average                      **EXHAUST:** Average

**FUEL TYPE:** Gas                      **DRIVABLE:** Yes                      **MECHANICAL ADDITIONAL INFORMATION:** Check engine and tps light

TIRES

**SPARE TIRE:** Yes                      **TIRE CONDITION:** Good                      **TIRE SIZE:** 245/75/16

**WINTER TIRES:** No                      **WHEEL COVERS:** Steel                      **EXTRA TIRE INCLUDED:** No

**TIRES ADDITIONAL INFORMATION:** None

DOCUMENTATION

**KEYS PRESENT:** Yes                      **NUMBER OF KEYS:** 1                      **KEY FOBS PRESENT:** No

**NUMBER OF KEY FOBS:** 1                      **LICENCE PLATES ON VEHICLE:** Yes                      **CIGARETTE SMOKE ODOUR:** No

**DECALS ON VEHICLE:** No                      **PET ODOUR/HAIR PRESENT :** No                      **OWNERSHIP PRESENT:** No

**OWNERSHIP REGION:** ON                      **MANUALS PRESENT:** No                      **NAV SOFTWARE:** N/A

**PERSONAL EFFECTS:** Yes                      **DOCUMENTATION ADDITIONAL INFORMATION:** None





# Map

Route distance:



# Condition Map







PLEASE CLICK ON MAP TO VIEW THE DAMAGES.









- Misaligned
- Chipped
- Multiple Dents/No Paint Damage
- Multiple Scratches Light
- Tread Depth
- Rust
- Dent(s) W/ Paint Dmg
- Heavy Scratch
- Multiple Scratches Heavy
- Multiple damages

## DAMAGE LIST

Part	Damage	Description	Images
Front Bumper	<ul style="list-style-type: none"> <li>• misaligned</li> </ul>	<ul style="list-style-type: none"> <li>• Repair Required</li> </ul>	 <p>Feb 21 2025</p>

Hood	<ul style="list-style-type: none"> <li>• chipped</li> <li>• multiple dents/no paint damage</li> </ul>	<ul style="list-style-type: none"> <li>• 10 or more</li> <li>• 5</li> </ul>	 <p>Feb 21 2025      Feb 21 2025</p>
Left Front Door	<ul style="list-style-type: none"> <li>• chipped</li> <li>• multiple scratches light</li> </ul>	<ul style="list-style-type: none"> <li>• 10 or more</li> </ul>	 <p>Feb 21 2025      Feb 21 2025</p>
Left Front Fender	<ul style="list-style-type: none"> <li>• chipped</li> </ul>	<ul style="list-style-type: none"> <li>• 10 or more</li> </ul>	 <p>Feb 21 2025</p>
Left Front Tire	<ul style="list-style-type: none"> <li>• tread depth</li> </ul>	<ul style="list-style-type: none"> <li>• 7 mm</li> </ul>	
Left Qtr Panel	<ul style="list-style-type: none"> <li>• multiple scratches light</li> </ul>	<ul style="list-style-type: none"> <li>• 10 or more</li> </ul>	 <p>Feb 21 2025</p>
Left Rear Tire	<ul style="list-style-type: none"> <li>• tread depth</li> </ul>	<ul style="list-style-type: none"> <li>• 4 mm</li> </ul>	
Rear Bumper	<ul style="list-style-type: none"> <li>• dent(s) w/ paint dmg</li> <li>• rust</li> </ul>	<ul style="list-style-type: none"> <li>• 12 inches</li> </ul>	 <p>Feb 21 2025      Feb 21 2025</p>
Right Front Door	<ul style="list-style-type: none"> <li>• heavy scratch</li> </ul>	<ul style="list-style-type: none"> <li>• 1 to 2 inches</li> </ul>	 <p>Feb 21 2025</p>
Right Front Fender	<ul style="list-style-type: none"> <li>• chipped</li> </ul>	<ul style="list-style-type: none"> <li>• 5</li> </ul>	

			 <p>Feb 21 2025</p>
Right Front Tire	<ul style="list-style-type: none"> <li>tread depth</li> </ul>	<ul style="list-style-type: none"> <li>7 mm</li> </ul>	
Right Qtr Panel	<ul style="list-style-type: none"> <li>multiple scratches light</li> </ul>	<ul style="list-style-type: none"> <li>10 or more</li> </ul>	 <p>Feb 21 2025</p>
Right Rear Door	<ul style="list-style-type: none"> <li>multiple scratches light</li> </ul>	<ul style="list-style-type: none"> <li>10 or more</li> </ul>	 <p>Feb 21 2025</p>
Right Rear Tire	<ul style="list-style-type: none"> <li>tread depth</li> </ul>	<ul style="list-style-type: none"> <li>4 mm</li> </ul>	
Right Rocker Panel	<ul style="list-style-type: none"> <li>chipped</li> </ul>	<ul style="list-style-type: none"> <li>10 or more</li> </ul>	 <p>Feb 21 2025</p>
Tailgate	<ul style="list-style-type: none"> <li>multiple scratches heavy</li> <li>rust</li> </ul>	<ul style="list-style-type: none"> <li>2 to 3 inches</li> <li>6</li> </ul>	 <p>Feb 21 2025</p>  <p>Feb 21 2025</p>





Signature





# Media

## IMAGES

Please be advised that if there is a discrepancy between a picture location and the location of the report the image will show a message




Feb 21 2025 07:48:43 PM




Feb 21 2025 07:52:35 PM



Feb 21 2025 07:49:52 PM



Feb 21 2025 07:52:00 PM



Feb 21 2025 07:52:00 PM



Feb 21 2025 07:52:00 PM



Feb 21 2025 07:55:18 PM



Feb 21 2025 07:55:18 PM




Feb 21 2025 07:55:19 PM



Feb 21 2025 07:55:19 PM




Feb 21 2025 07:55:19 PM



Feb 21 2025 08:01:14 PM



Feb 21 2025 08:13:32 PM





Feb 21 2025 08:22:15 PM