


Item info

2014 Chevrolet Express LS 1500 AWD

Sold For (CAD): \$5,700.00
Your bid (CAD): \$5,700.00 (Winning Bid)
Location : North York, ON
Sale / Lot : R5TO0017660 - 5TO015482-K4A20-CN
Closing date: 27-June-2025 @ 9:15 a.m. (ante meridiem) EDT (Eastern Daylight Time)

 [Show Bids](#)

Pictures



◀ Picture 1 of 51 ▶

▼ Details

Sold For (CAD): \$5,700.00
Your bid (CAD) : \$5,700.00 (Winning Bid)
Item: 2014 Chevrolet Express LS 1500 AWD
Minimum bid: \$ 4,600.00
Closing date: 27-June-2025 @ 9:15 a.m. (ante meridiem) EDT (Eastern Daylight Time)

Specifications:

Year:	2014
Make:	Chevrolet
Model:	Express
Body style:	SPORTS VAN
Engine type:	5.3L V8 OHV 16V
Transmission:	6-Speed Automatic
Drive line:	AWD
Brake type:	Disc
VIN/Serial number:	1GNSHBF44E1106581
Odometer:	316678 KM

Anti Theft Locks:

- Child Safety Door Locks
- Locking Pickup Truck Tailgate
- Vehicle Anti-Theft

Braking and traction:

- 4WD/AWD
- ABS Brakes
- Traction Control
- Vehicle Stability Control System

Safety:

- Driver Airbag
- Passenger Airbag
- Side Head Curtain Airbag

Wheels:

- Steel Wheels

Tires:

- Full Size Spare Tire

- Windows:**
 - Power Windows
 - Deep Tinted Glass
- Climate control:**
 - Air Conditioning
- Interior features:**
 - Tachometer
 - Tire Pressure Monitor
 - Trip Computer
- Entertainment:**
 - Telematics System
- Seat:**
 - Second Row Removable Seat
 - Third Row Removable Seat
- Exterior lighting:**
 - Automatic Headlights
 - Daytime Running Lights
- Observations :**
 - Tires:
 - Installed: Michelin LTX Winter LT245/70R17 119/116R
 - The rims are rusty.
 - Mechanical:
 - The vehicle runs and drives.
 - The vehicle requires a boost to start.
 - The vehicle does not hold the charge without hooked boosters.
 - The vehicle must be towed from the site.
 - The brakes may require servicing or repairs.
 - The pressure engine check is illuminated on the dashboard.
 - The service detergent system and the service airbag warning messages are illuminated on the dashboard.
 - The client department declares the car was involved in an accident in November 2017.
 - No repairs were required.
 - The claim exists solely for recording purposes.
 - Exterior:
 - There are scratches, rust, dents and paint chips throughout the vehicle.
 - The undercarriage is rusty.
 - The rear bumper is rusty.
 - There are glue residues on the doors.
 - The paint is peeling on passenger rear door edges.
 - The windshield is cracked.
 - Interior:
 - An interior cleaning is required.
 - The headliner, seats and trims are stained.
 - There is a metal divider installed at the back.
 - There is a metal cabinet installed at the back.
 - The rear seats are detached.
 - The rear flooring is on top of the rear seats.
 - There is no floor mat.
 - There is a metal storage installed in lieu of the centre console.
 - Additional information:
 - There are two keys included.

Additional comments:

Condition of Vehicle:

1. This vehicle is sold used without mechanical inspection and may require other unknown repairs.
2. GCSurplus has no additional information regarding the overall condition or history of this vehicle.
3. Any mention of a sale item's condition in the sales listing represents the best assessment of the divestment officer at the time of listing and is offered for guidance only and is not an enforceable condition of sale.


Viewing and Pick-up:

1. Appointments for viewing and pick-up are available Monday through Friday, excluding statutory holidays, from 8:00 a.m. to 3:00 p.m. (EST). To schedule an appointment please contact the divestment officer or GCSurplus Ontario Mailbox (information can be found in Location and Contacts tab).
2. Visitors without appointments may be turned away.
3. All pick-ups by a third party or transport company require written authorization from the buyer and are to be emailed to GCSurplus prior to sending the third party or transport.
 - GCSurplus cannot complete any shipping documents for the buyer, their representative, or shipper.

Registration:

1. This vehicle was owned and operated by the Government of Canada and was previously registered in Ontario.
2. Invoices and Bills of Sale cannot be modified for any reason. Bidders should ensure that the individual or business name on their account is the same information they wish to register the vehicle under before placing a bid.

▼ Location and Contacts

Location of asset(s): GCSurplus-Ontario
40 CARL HALL ROAD
Unit 40
Downsview Park
North York , ON M3K 2C1


Contact : Carine Ngior
416-807-8528
gcsurplusontario@pwgsc-tpsgc.gc.ca

Divestment Officer: Carine Ngior
416-807-8528
Carine.Ngior@tpsgc-pwgsc.gc.ca

Sale account: R5TO0017660

Lot number: 5TO015482-K4A20-CN

▼ Payment and Removal

Payment: The Purchaser agrees to make any payment requested ([see available payment options](#)) by the Minister within 3 business days from the date of such request and prior to removal of any of the property.

Removal: The Purchaser, upon acceptance of this offer by the Minister and after payment in full has been received by the Minister, shall at their expense, pack, load and remove the property by the date indicated on the bill of sale or, if no date is shown, within 5 business days after the date the bill of sale is issued.

▼ Sales Clauses

This sale is subject to all of the clauses outlined in the GCSurplus [General terms and conditions A](#) , unless [General terms and conditions B](#) are cited.

The Purchaser must also pay particular attention to the following clauses.

Clause No.	Description
832.1	All sales are final. No purchased Goods may be returned and no requests for reimbursement in whole or in part will be accepted.
844.1	With the exception of authorized dealers and registered recyclers, vehicle ownership transfer must occur prior to the vehicle being released to the owner. This transfer must be completed by the owner, who will also be responsible for any and all mandatory vehicle inspections.
875.1	It is the buyer's responsibility to contact the Canadian manufacturer and, if necessary, equipment manufacturer to find out whether any notices of defects or of non-compliance (more commonly known as "recalls") have been issued with regards to the vehicle.
915.1	1- Item descriptions: The description of the asset(s) is based on the best information available to GCSurplus. GCSurplus does not warrant the accuracy or the completeness of the information provided on the GCSurplus.ca website, or that GCSurplus.ca will function without error, failure or interruption; 2- Asset(s) sold "as-is/where-is"

All asset(s) are sold on an "as-is/where-is" basis. Canada/PWGSC/GCSurplus makes no warranty, expressed or implied, legal, contractual or verbal, as to the quantity, kind, character, quality, weight, size, condition or fitness for any use or purpose with respect to the asset(s) listed on GCSurplus.ca. Asset(s) are purchased at your own risk;

3- Inspection of goods

Inspection prior to submitting a bid is the responsibility of the user and may be arranged by appointment only during regular office hours with the custodian of the asset(s) at the location(s) indicated on the sale listing.

916.1

The vehicle sold is a used vehicle and is sold as is, without warranty of any kind, either expressed or implied. The buyer acknowledges that the vehicle may require repairs not indicated or visible at the time of sale. Such repairs may include, but are not limited to, repairs to the engine, transmission, brakes, suspension, electrical system, air conditioning, body, chassis and electronic components. The seller declines all responsibility for any mechanical, electrical or other defects or problems that may arise after the sale. The buyer agrees to assume all future repair and maintenance costs.
