

YEAR 2019 MAKE Land Rover MODEL Range Rover

UNIT/FLEET#
(Optional)

BODY STYLE Sport Utility Vehicle VIN SALGS2RK4KA547299

ODOMETER 72000 MI KM FUEL CODE G D

REASON FOR INSPECTION:

- FIRST TIME REGISTERED IN BC NOTICE & ORDER MOTORCYCLE REBUILT FROM SALVAGE OTHER

COLLISION REPAIR FACILITY NAME (FOR REBUILT FROM SALVAGE)

Phone No

HAS CUSTOMER BEEN NOTIFIED OF AIRBAG STATUS? YES NO

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASSES OF VEHICLES INSPECTED

MARK EACH ITEM AS: "F" Failed "R" Repaired (After a Fail) "P" Passed

DOCUMENTATION	F	R	P		F	R	P		F	R	P
Vehicle Identification			✓	Floors			✓	BRAKES			
				Bumpers			✓	Drum Brakes			✓
DRIVER'S CONTROLS				Trunk			✓	Disc Brakes			✓
Horn			✓	Trailer Hitch			✓	Proportioning Valve			✓
Mirrors			✓	Body Exterior/Protruding Metal			✓	Mechanical Components			✓
Windshield Wipers			✓	Motorcycle Kickstand			✓	Brake Lines, Hoses			✓
Windshield and Windows			✓	Frame			✓	Master Cylinder			✓
Windshield Dekoster			✓	Frame Structural Body			✓	ENGINE COMPARTMENT			
Visors			✓	Unibody			✓	Hood & Safety Catch			✓
Interior Heaters			✓	Unibody Structural Integrity			✓	Vacuum System			✓
Parking Brake			✓	Airbag - Driver (rebuilt & new to BC - fail)			✓	Power Train			✓
Power Brake Operation			✓	Airbag - Passenger (rebuilt & new to BC - fail)			✓	Fuel System			✓
Brake Pedal Reserve & Leakage Test			✓	UNDERCARRIAGE				PRESSURE FUEL			
Steering Lash and Travel			✓	Tires			✓	Liquid Propane Gas	N/A	✓	
Power Steering			✓	Tire Construction (Mixed)			✓	Compressed Natural Gas			✓
Handle Bars			✓	Wheels/Nuts/Studs			✓	LIGHTING/ELECTRICAL			
Accelerator Pedal			✓	Road Clearance			✓	Battery			✓
Transmission/Speed/Odom			✓	Steering Linkage			✓	Switches			✓
BODY INTEGRITY				Steering Column and Coupler			✓	Visible Wiring			✓
Driver's Seat			✓	Kingpins			✓	Indicator Lights			✓
Seat Belts			✓	Ball Joints			✓	Lamps			✓
Motorcycle Seat			✓	Springs and Attachments			✓	Headlight Aim			✓
Doors			✓	Shock Absorbers			✓				
Physically Disabled Passenger Vehicles			✓	Wheel Bearings			✓				
Reflex Reflectors			✓	Fuel System			✓				
				Exhaust System & Catalytic Converter			✓				

Where a pass is indicated in the inspection result box, the inspector's signature above is certification that this vehicle conforms to all the safety requirements of the Motor Vehicle Act and Regulations.