GARAGEONE

G 2076

12/4/2024

2015 BMW X6 X DRIVE	5UXKU2C50G0N79693

LOUGHEED MOTORS

94023 KMS

CHECKED AND OK

MAY NEED FUTURE ATTENTION

REQUIRES IMMEDIATE ATTENTION

BODY DAMAGE



NOTES:

INTERIOR / EXTERIOR

☑	Head Lights / Tail Lights / Turn Signals
☑	Brake Lights / Reverse Lights / Exterior Lamps
☑	Windshield: Washer/Wiper Blades
☑	Mirrors / Glass Cracks / Chips / Pitting
☑	Carpet / Upholstery / Floor Mats
☑	Fuel Tank Cap Gasket
☑	Clutch Operation (if equipped)
☑	Dash Warning Lights/Horn Operation

UNDER VEHICLE

☑	Shock Absorbers / Springs / Struts
☑	Ball joints / CV Joints
☑	Exhaust: Muffler, Pipes, Mounts, Cat. Converter
☑	Engine Oil and Fluid Leaks
☑	Brakes Lines, Hoses, Parking Brake Cable
☑	Inspect Nuts and Bolts on Body and Chassis

UNDER HOOD

☑	Engine Oil/Coolant/ Automatic Transmission
☑	Power Steering, Brake Fluid, Washer Fluid
☑	Engine Air Filter / Drive Belts
☑	Coolant Reservoir: Fluid Level / Condition
☑	Clutch Reservoir: Fluid Level (as equipped)
☑	Battery: Terminal / Cables / Mountings

TIRES AND BRAKES

PART	LEFT FRONT	RIGHT FRONT	LEFT REAR	RIGHT REAR
BRAKE PADS	☑ 12MM	☑ 12MM	☑ 10MM	☑ 10MM
TIRE DEPTH	☑ NEW	☑ NEW	☑ NEW	☑ NEW
WEAR PATTERN	☑ GOOD	☑ GOOD	☑ GOOD	☑ GOOD
ROTOR/DRUM	☑ GOOD	☑ GOOD	☑ GOOD	☑ GOOD