



VEHICLE INSPECTION

96011 KMS

OCT 30 25

LOUGHEED MOTORS

2017 MERCEDES C300 4M

55SWF4KBGHU208152

CHECKED AND OK

MAY NEED FUTURE ATTENTION

REQUIRES IMMEDIATE ATTENTION

CHECKED AND OK

MAY NEED FUTURE ATTENTION

REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

X			Head Lights & Turn Signals EXT Lamp
X			Brake Lights & Reverse Lights
X			Glass - Cracks / Chips / Pitting
X			Mirrors - Cracks
X			Carpet / Upholstery / Floor Mats
X			Horn Operation
X			Dash Warning Lights
X			Vehicle System Scanned

FLUID LEVELS

X			Engine Oil Level & Condition
X			Coolant Level & Condition
X			Transmission Fluid Level (Dipstick)
X			Power Steering Fluid Level
X			Brake Fluid Level
X			Washer Fluid Level
X			Fluid Leaks
			Clutch Fluid Level (as equipped)

VEHICLE FUNCTIONS

X			Power Windows Function
X			Power Lock Function
X			Heat & AC Function
X			Windshield Washer & Wiper Blades
X			Engine Air Filter
X			Cabin Air Filter
X			Drive Belts
X			Battery Terminal, Cables & Mounts
X			Fuel Tank Cap Gasket
X			Brakes Lines
X			Parking Brake Cable
			Clutch Operation (if equipped)
X			Road Test

EXHAUST

X			Manifold(s)
X			Muffler
X			Pipes
X			Hangers & Clamps
X			Catalytic Converter

SUSPENSION

X			Shocks & Struts
X			Springs
X			CV Axle
X			Ball joints
X			Tie Rod Ends

TIRES

LEFT FRONT			RIGHT FRONT		
X			8/32	X	
X			WEAR PATTERN	X	
LEFT REAR			RIGHT REAR		
X			5/32	X	
X			WEAR PATTERN	X	

BRAKES PADS AND ROTORS

LEFT FRONT			RIGHT FRONT		
X			10MM	X	
X			ROTORS	X	
LEFT REAR			RIGHT REAR		
X			8MM	X	
X			ROTORS	X	

Notes: