ATOZ AUTO REPAIR SERVICE

Technician: Billy **Date:** Jan 18th.202

Customer Name: Lougheed Auto sales

Yr/Make/Model: 2009/Lincoln/MKX

VIN: 2LMDU88C89BJ06274

Mileage: 223,673 Km **Repair Order #**

BRAKE AND TIRE

Left Front	Right Front
Brake Lining 8 mm	Brake Lining 8 mm
Tire Tread 8 32nds	Tire Tread 8 32nds
Wear Pattern OK	Wear Pattern OK
Tire Pressure PSI 36	Tire Pressure PSI 36

Left Rear	Right Rear
Brake Lining 10 mm	Brake Lining 10 mm
Tire Tread 9 32nds	Tire Tread 9 32nds
Wear Pattern OK	Wear Pattern OK
Tire Pressure PSI 36	Tire Pressure PSI 36

☐ Brake Inspection Not Performed This Visit

COMMENTS / ESTIMATES

CHECKED AND OKAY
MAY NEED FUTURE ATTENTION
REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

✔	☐	☐	Head Lights, Tail Lights, Turn Signals, Brake Lights Hazard Lights, Exterior Lamps, License Plate Lights
✔	☐	☐	Windshield Washer/Wiper Operation, Wiper Blades
✔	☐	☐	Emergency Brake Adjustment
✔	☐	☐	Horn Operation
☐	☐	☐	Clutch Operation (if equipped)

UNDER VEHICLE

✔	☐	☐	Shock Absorbers / Suspension / Struts
✔	☐	☐	Steering Box, Linkage, Ball Joints, Dust Covers
✔	☐	☐	Muffler, Exhaust Pipes/Mounts, Catalytic Converter
✔	☐	☐	Engine Oil and Fluid Leaks
✔	☐	☐	Brakes Lines, Hoses, Parking Brake Cable
✔	☐	☐	Drive Shaft Boots, Constant Velocity Boots, U-Joints, Transmission Linkage (if equipped)
✔	☐	☐	Transmission, Differential, Transfer Case, (Check Fluid Level, Fluid Condition, and Fluid Leaks)

UNDER HOOD

✔	☐	☐	Fluid Levels: Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Automatic Transmission
✔	☐	☐	Engine Air Filter
✔	☐	☐	Drive Belts (condition and adjustment)
✔	☐	☐	Cooling System Hoses, Heater Hoses, Air Condition, Hoses and Connections
✔	☐	☐	Radiator Core, Air Conditioner Condenser
✔	☐	☐	Coolant Recovery Reservoir Fluid Level / Condition
☐	☐	☐	Clutch Reservoir Fluid / Condition (as equipped)

BATTERY PERFORMANCE

✔	☐	☐	Battery Terminal / Cables / Mountings
✔	☐	☐	Condition of Battery / Cold Cranking Amps

BATTERY COLD CRANKING AMPS:

Factory Specs: **Actual:**

COMMENTS / ESTIMATES