



# VEHICLE INSPECTION

96622 KMS

MAR 13 26

LOUGHEED MOTORS

2019 JEEP COMPASS

3C4NJDDB0KT790251

CHECKED AND OK				CHECKED AND OK			
MAY NEED FUTURE ATTENTION				MAY NEED FUTURE ATTENTION			
REQUIRES IMMEDIATE ATTENTION				REQUIRES IMMEDIATE ATTENTION			
INTERIOR / EXTERIOR				EXHAUST			
X			Head Lights & Turn Signals EXT Lamp	X			Manifold(s)
X			Brake Lights & Reverse Lights	X			Muffler
X			Glass - Cracks / Chips / Pitting	X			Pipes
X			Mirrors - Cracks	X			Hangers & Clamps
X			Carpet / Upholstery / Floor Mats	X			Catalytic Converter
X			Horn Operation	SUSPENSION			
X			Dash Warning Lights	X			Shocks & Struts
X			Vehicle System Scanned	X			Springs
FLUID LEVELS				X			CV Axle
X			Engine Oil Level & Condition	X			Ball joints
X			Coolant Level & Condition	X			Tie Rod Ends
X			Transmission Fluid Level (Dipstick)	TIRES			
X			Power Steering Fluid Level	LEFT FRONT		RIGHT FRONT	
X			Brake Fluid Level	X			7/32
X			Washer Fluid Level	X			WEAR PATTERN
X			Fluid Leaks	X			WEAR PATTERN
			Clutch Fluid Level (as equipped)	LEFT REAR		RIGHT REAR	
				X			7/32
VEHICLE FUNCTIONS				X			WEAR PATTERN
X			Power Windows Function	BRAKES PADS AND ROTORS			
X			Power Lock Function	LEFT FRONT		RIGHT FRONT	
X			Heat & AC Function	X			7MM
X			Windshield Washer & Wiper Blades	X			ROTORS
X			Engine Air Filter	LEFT REAR		RIGHT REAR	
X			Cabin Air Filter	X			7MM
X			Drive Belts	X			ROTORS
X			Battery Terminal, Cables & Mounts	Notes:			
X			Fuel Tank Cap Gasket				
X			Brakes Lines				
X			Parking Brake Cable				
			Clutch Operation (if equipped)				
X			Road Test				