PULSE AUTO REPAIR

SINCE 2024

DONE RIGHT, THE FIRST TIME

Technician: Thomas Date: May 11

Customer Name: Loughead Motors

Yr/Make/Model: 2008 Chrysler 300

VIN: 2C3LK63H68H286914

Mileage: 90,483

BRAKE AND TYRE

	Left Front	Right Front	Left Rear	Right Rear
Brake Lining	6 mm	6 mm	6 mm	6 mm
Tyre Tread	7 mm	7 mm	6 mm	6 mm
Wear Pattern				

☐ Brake Inspection Not Performed This Visit

COMMENTS / ESTIMATES

CHECKED AND OKAY
MAY NEED FUTURE ATTENTION
REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

- ✓ Head Lights, Tail Lights, Turn Signals, Brake Lights Hazard Lights, Exterior Lamps, License Plate Lights
- ✓ Windshield Washer/Wiper Operation, Wiper Blades
- ✓ Hand Brake Adjustment
- ✓ Horn Operation
- ☐ Clutch Operation (if equipped) NA

UNDER VEHICLE

- ✓ Shock Absorbers / Suspension / Struts
- ✓ Steering Box, Linkage, Ball Joints, Dust Covers
- ✓ Exhaust System / Mountings
- ✓ Engine Oil and Fluid Leaks
- ✓ Brakes Pipes, Hoses, Hand Brake Cable
- ✓ Drive Shaft, Constant Velocity Boots, U-Joints, Transmission Linkage (if equipped)
- ✓ Transmission, Differential, Transfer Case, (Check Fluid Level, Fluid Condition, and Fluid Leaks)

UNDER HOOD

- ✓ Fluid Levels: Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Automatic Transmission
- ✓ Engine Air Filter
- ✓ Drive Belts (condition and adjustment)
- ✓ Cooling System Hoses, Heater Hoses, Air Condition, Hoses and Connections
- ✓ Radiator Core, Air Conditioner Condenser
- ✓ Coolant Recovery Reservoir Fluid Level / Condition
- ☐ Clutch Reservoir Fluid / Condition (as equipped) NA

BATTERY PERFORMANCE

- ✓ Battery Terminal / Cables / Mountings
- ✓ Condition of Battery / Cold Cranking Amps

BATTERY HEALTH: + 72

INSPECTED BY

THANK YOU FOR YOUR
BUSINESS | PULSE AUTO REPAIR