ATOZ AUTO REPAIR SERVICE

Technician: Billy **Date:** May 25.2026

Customer Name: Lougheed Motors LTD

Yr/Make/Model: 2011/Ford/F150

VIN: 1FTFW1ET9BFB67555

Mileage: 183,279 Km **Repair Order #**

BRAKE AND TIRE

Left Front	Right Front
Brake Lining 8 mm	Brake Lining 8 mm
Tire Tread 5 32nds	Tire Tread 5 32nds
Wear Pattern OK	Wear Pattern OK
Tire Pressure PSI 38	Tire Pressure PSI 38

Left Rear	Right Rear
Brake Lining 4 mm	Brake Lining 4 mm
Tire Tread 6 32nds	Tire Tread 6 32nds
Wear Pattern OK	Wear Pattern OK
Tire Pressure PSI 38	Tire Pressure PSI 38

☐ Brake Inspection Not Performed This Visit

COMMENTS / ESTIMATES

CHECKED AND OKAY
MAY NEED FUTURE ATTENTION
REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

✔	Head Lights, Tail Lights, Turn Signals, Brake Lights Hazard Lights, Exterior Lamps, License Plate Lights
✔	Windshield Washer/Wiper Operation, Wiper Blades
✔	Emergency Brake Adjustment
✔	Horn Operation
	Clutch Operation (if equipped)

UNDER VEHICLE

✔	Shock Absorbers / Suspension / Struts
✔	Steering Box, Linkage, Ball Joints, Dust Covers
✔	Muffler, Exhaust Pipes/Mounts, Catalytic Converter
✔	Engine Oil and Fluid Leaks
✔	Brakes Lines, Hoses, Parking Brake Cable
✔	Drive Shaft Boots, Constant Velocity Boots, U-Joints, Transmission Linkage (if equipped)
✔	Transmission, Differential, Transfer Case, (Check Fluid Level, Fluid Condition, and Fluid Leaks)

UNDER HOOD

✔	Fluid Levels: Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Automatic Transmission
✔	Engine Air Filter
✔	Drive Belts (condition and adjustment)
✔	Cooling System Hoses, Heater Hoses, Air Condition, Hoses and Connections
✔	Radiator Core, Air Conditioner Condenser
✔	Coolant Recovery Reservoir Fluid Level / Condition
	Clutch Reservoir Fluid / Condition (as equipped)

BATTERY PERFORMANCE

✔	Battery Terminal / Cables / Mountings
✔	Condition of Battery / Cold Cranking Amps

BATTERY COLD CRANKING AMPS:

Factory Specs: Actual:

COMMENTS / ESTIMATES