PULSE AUTO REPAIR

SINCE 2024

DONE RIGHT, THE FIRST TIME

Technician: Thomas Date: June 29

Customer Name: Lougheed Motors

Yr/Make/Model: 2019 Honda Fit

VIN: 3HGGK5H64KM103258

Mileage: 24,271

BRAKE AND TYRE

	Left Front	Right Front	Left Rear	Right Rear
Brake Lining	8 mm	8 mm	4 mm	4 mm
Tyre Tread	7 mm	7 mm	7 mm	7 mm
Wear Pattern				

☐ Brake Inspection Not Performed This Visit

COMMENTS / ESTIMATES

CHECKED AND OKAY
MAY NEED FUTURE ATTENTION
REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

✓			Head Lights, Tail Lights, Turn Signals, Brake Lights Hazard Lights, Exterior Lamps, License Plate Lights
✓			Windshield Washer/Wiper Operation, Wiper Blades
✓			Hand Brake Adjustment
✓			Horn Operation
			Clutch Operation (if equipped) NA

UNDER VEHICLE

✓			Shock Absorbers / Suspension / Struts
✓			Steering Box, Linkage, Ball Joints, Dust Covers
✓			Exhaust System / Mountings
✓			Engine Oil and Fluid Leaks
✓			Brakes Pipes, Hoses, Hand Brake Cable
✓			Drive Shaft, Constant Velocity Boots, U-Joints, Transmission Linkage (if equipped)
✓			Transmission, Differential, Transfer Case, (Check Fluid Level, Fluid Condition, and Fluid Leaks)

UNDER HOOD

✓			Fluid Levels: Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Automatic Transmission
✓			Engine Air Filter
✓			Drive Belts (condition and adjustment)
✓			Cooling System Hoses, Heater Hoses, Air Condition, Hoses and Connections
✓			Radiator Core, Air Conditioner Condenser
✓			Coolant Recovery Reservoir Fluid Level / Condition
			Clutch Reservoir Fluid / Condition (as equipped)

BATTERY PERFORMANCE

✓			Battery Terminal / Cables / Mountings
✓			Condition of Battery / Cold Cranking Amps

BATTERY HEALTH: 600

INSPECTED BY

THANK YOU FOR YOUR
BUSINESS | PULSE AUTO REPAIR