GARAGEONE

VEHICLE INSPECTION

69483 KMS | JUL 7 26

LOUGHEED MOTORS | 2019 KIA SPORTAGE | KNDPM3AC3L7711197

CHECKED AND OK
MAY NEED FUTURE ATTENTION
REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR			
X			Head Lights & Turn Signals EXT Lamp
X			Brake Lights & Reverse Lights
X			Glass - Cracks / Chips / Pitting
X			Mirrors - Cracks
X			Carpet / Upholstery / Floor Mats
X			Horn Operation
X			Dash Warning Lights
X			Vehicle System Scanned
FLUID LEVELS			
X			Engine Oil Level & Condition
X			Coolant Level & Condition
X			Transmission Fluid Level (Dipstick)
X			Power Steering Fluid Level
X			Brake Fluid Level
X			Washer Fluid Level
X			Fluid Leaks
			Clutch Fluid Level (as equipped)
VEHICLE FUNCTIONS			
X			Power Windows Function
X			Power Lock Function
X			Heat & AC Function
X			Windshield Washer & Wiper Blades
X			Engine Air Filter
X			Cabin Air Filter
X			Drive Belts
X			Battery Terminal, Cables & Mounts
X			Fuel Tank Cap Gasket
X			Brakes Lines
X			Parking Brake Cable
			Clutch Operation (if equipped)
X			Road Test

EXHAUST			
X			Manifold(s)
X			Muffler
X			Pipes
X			Hangers & Clamps
X			Catalytic Converter
SUSPENSION			
X			Shocks & Struts
X			Springs
X			CV Axle
X			Ball joints
X			Tie Rod Ends

TIRES

LEFT FRONT				RIGHT FRONT			
X			8/32	X			8/32
X			WEAR PATTERN	X			WEAR PATTERN
LEFT REAR				**RIGHT REAR**			
X			8/32	X			8/32
X			WEAR PATTERN	X			WEAR PATTERN

BRAKES PADS AND ROTORS

LEFT FRONT				RIGHT FRONT			
X			6MM	X			6MM
X			ROTORS	X			ROTORS
LEFT REAR				**RIGHT REAR**			
X			7MM	X			7MM
X			ROTORS	X			ROTORS

Notes: