PULSE AUTO REPAIR

SINCE 2024

DONE RIGHT. THE FIRST TIME

Technician: Thomas Date: Oct 6

Customer Name: Lougheed Motors

Yr/Make/Model: 2017 Nissan Pathfinder

VIN: 5N1DR2MM4HC677624

Mileage: 32,264

BRAKE AND TYRE

Left Front		Right Front	
Brake Lining	7 mm	Brake Lining	7 mm
Tyre Tread	7 mm	Tyre Tread	7 mm
Wear Pattern		Wear Pattern	

Left Rear		Right Rear	
Brake Lining	6 mm	Brake Lining	6 mm
Tyre Tread	7 mm	Tyre Tread	7 mm
Wear Pattern		Wear Pattern	

☐ Brake Inspection Not Performed This Visit

COMMENTS / ESTIMATES

CHECKED AND OKAY
MAY NEED FUTURE ATTENTION
REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

✓	Head Lights, Tail Lights, Turn Signals, Brake Lights Hazard Lights, Exterior Lamps, License Plate Lights
✓	Windshield Washer/Wiper Operation, Wiper Blades
✓	Hand Brake Adjustment
✓	Horn Operation
	Clutch Operation (if equipped) NA

UNDER VEHICLE

✓	Shock Absorbers / Suspension / Struts
✓	Steering Box, Linkage, Ball Joints, Dust Covers
✓	Exhaust System / Mountings
✓	Engine Oil and Fluid Leaks
✓	Brakes Pipes, Hoses, Hand Brake Cable
✓	Drive Shaft, Constant Velocity Boots, U-Joints, Transmission Linkage (if equipped)
✓	Transmission, Differential, Transfer Case, (Check Fluid Level, Fluid Condition, and Fluid Leaks)

UNDER HOOD

✓	Fluid Levels: Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Automatic Transmission
✓	Engine Air Filter
✓	Drive Belts (condition and adjustment)
✓	Cooling System Hoses, Heater Hoses, Air Condition, Hoses and Connections
✓	Radiator Core, Air Conditioner Condenser
✓	Coolant Recovery Reservoir Fluid Level / Condition
	Clutch Reservoir Fluid / Condition (as equipped) NA

BATTERY PERFORMANCE

✓	Battery Terminal / Cables / Mountings
✓	Condition of Battery / Cold Cranking Amps

BATTERY HEALTH: $100

INSPECTED BY

THANK YOU FOR YOUR
BUSINESS | PULSE AUTO REPAIR