PULSE AUTO REPAIR

SINCE 2024

DONE RIGHT, THE FIRST TIME

Technician: Thomas Date: Oct 6

Customer Name: Lougheed Motors

Yr/Make/Model: 2018 Audi S4

VIN: WAUC4AFH0JA041691

Mileage: 84,142 Km

BRAKE AND TYRE

	Left Front	Right Front	Left Rear	Right Rear
Brake Lining	9 mm	9 mm	5 mm	5 mm
Tyre Tread	8 mm	8 mm	8 mm	8 mm
Wear Pattern				

☐ Brake Inspection Not Performed This Visit

COMMENTS / ESTIMATES

CHECKED AND OKAY

MAY NEED FUTURE ATTENTION

REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR			
✓			Head Lights, Tail Lights, Turn Signals, Brake Lights Hazard Lights, Exterior Lamps, License Plate Lights
✓			Windshield Washer/Wiper Operation, Wiper Blades
✓			Hand Brake Adjustment
✓			Horn Operation
			Clutch Operation (if equipped) NA
UNDER VEHICLE			
✓			Shock Absorbers / Suspension / Struts
✓			Steering Box, Linkage, Ball Joints, Dust Covers
✓			Exhaust System / Mountings
✓			Engine Oil and Fluid Leaks
✓			Brakes Pipes, Hoses, Hand Brake Cable
✓			Drive Shaft, Constant Velocity Boots, U-Joints, Transmission Linkage (if equipped)
✓			Transmission, Differential, Transfer Case, (Check Fluid Level, Fluid Condition, and Fluid Leaks)
UNDER HOOD			
✓			Fluid Levels: Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Automatic Transmission
✓			Engine Air Filter
✓			Drive Belts (condition and adjustment)
✓			Cooling System Hoses, Heater Hoses, Air Condition, Hoses and Connections
✓			Radiator Core, Air Conditioner Condenser
✓			Coolant Recovery Reservoir Fluid Level / Condition
			Clutch Reservoir Fluid / Condition (as equipped) NA
BATTERY PERFORMANCE			
✓			Battery Terminal / Cables / Mountings
✓			Condition of Battery / Cold Cranking Amps

BATTERY HEALTH: ok WO

INSPECTED BY

THANK YOU FOR YOUR BUSINESS | PULSE AUTO REPAIR