PULSE AUTO REPAIR

SINCE 2024

DONE RIGHT. THE FIRST TIME

Technician: Thomas Date: Oct 8

Customer Name: Lougheed Motors

Yr/Make/Model: 2024 Mazda CX 5

VIN: JM3KFBCL0R0516369

Mileage: 78,359 Km

BRAKE AND TYRE

Left Front		Right Front	
Brake Lining	6 mm	Brake Lining	6 mm
Tyre Tread	8 mm	Tyre Tread	8 mm
Wear Pattern		Wear Pattern	

Left Rear		Right Rear	
Brake Lining	5 mm	Brake Lining	5 mm
Tyre Tread	8 mm	Tyre Tread	8 mm
Wear Pattern		Wear Pattern	

☐ Brake Inspection Not Performed This Visit

COMMENTS / ESTIMATES

CHECKED AND OKAY

MAY NEED FUTURE ATTENTION

REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

✓			Head Lights, Tail Lights, Turn Signals, Brake Lights Hazard Lights, Exterior Lamps, License Plate Lights
✓			Windshield Washer/Wiper Operation, Wiper Blades
✓			Hand Brake Adjustment
✓			Horn Operation
			Clutch Operation (if equipped) NP

UNDER VEHICLE

✓			Shock Absorbers / Suspension / Struts
✓			Steering Box, Linkage, Ball Joints, Dust Covers
✓			Exhaust System / Mountings
✓			Engine Oil and Fluid Leaks
✓			Brakes Pipes, Hoses, Hand Brake Cable
✓			Drive Shaft, Constant Velocity Boots, U-Joints, Transmission Linkage (if equipped)
✓			Transmission, Differential, Transfer Case, (Check Fluid Level, Fluid Condition, and Fluid Leaks)

UNDER HOOD

✓			Fluid Levels: Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Automatic Transmission
✓			Engine Air Filter
✓			Drive Belts (condition and adjustment)
✓			Cooling System Hoses, Heater Hoses, Air Condition, Hoses and Connections
✓			Radiator Core, Air Conditioner Condenser
✓			Coolant Recovery Reservoir Fluid Level / Condition
			Clutch Reservoir Fluid / Condition (as equipped) NP

BATTERY PERFORMANCE

✓			Battery Terminal / Cables / Mountings
✓			Condition of Battery / Cold Cranking Amps

BATTERY HEALTH: 100

INSPECTED BY

THANK YOU FOR YOUR BUSINESS | PULSE AUTO REPAIR