ATOZ AUTO REPAIR SERVICE

Technician: Billy **Date:** Oct 7th.2026

Customer Name: Lougheed Auto sales

Yr/Make/Model: 2010/Toyota/Matrix

VIN: 2T1KU4EE6AC204754

Mileage: 158,210 Km **Repair Order #**

BRAKE AND TIRE

Left Front	Right Front
Brake Lining 6 mm	Brake Lining 6 mm
Tire Tread 6 32nds	Tire Tread 6 32nds
Wear Pattern OK	Wear Pattern OK
Tire Pressure PSI 38	Tire Pressure PSI 38

Left Rear	Right Rear
Brake Lining 4 mm	Brake Lining 4 mm
Tire Tread 5 32nds	Tire Tread 5 32nds
Wear Pattern OK	Wear Pattern OK
Tire Pressure PSI 38	Tire Pressure PSI 38

☐ Brake Inspection Not Performed This Visit

COMMENTS / ESTIMATES

CHECKED AND OKAY
MAY NEED FUTURE ATTENTION
REQUIRES IMMEDIATE ATTENTION

INTERIOR / EXTERIOR

✔			Head Lights, Tail Lights, Turn Signals, Brake Lights Hazard Lights, Exterior Lamps, License Plate Lights
✔			Windshield Washer/Wiper Operation, Wiper Blades
✔			Emergency Brake Adjustment
✔			Horn Operation
			Clutch Operation (if equipped)

UNDER VEHICLE

✔			Shock Absorbers / Suspension / Struts
✔			Steering Box, Linkage, Ball Joints, Dust Covers
✔			Muffler, Exhaust Pipes/Mounts, Catalytic Converter
✔			Engine Oil and Fluid Leaks
✔			Brakes Lines, Hoses, Parking Brake Cable
✔			Drive Shaft Boots, Constant Velocity Boots, U-Joints, Transmission Linkage (if equipped)
✔			Transmission, Differential, Transfer Case, (Check Fluid Level, Fluid Condition, and Fluid Leaks)

UNDER HOOD

✔			Fluid Levels: Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Automatic Transmission
✔			Engine Air Filter
✔			Drive Belts (condition and adjustment)
✔			Cooling System Hoses, Heater Hoses, Air Condition, Hoses and Connections
✔			Radiator Core, Air Conditioner Condenser
✔			Coolant Recovery Reservoir Fluid Level / Condition
			Clutch Reservoir Fluid / Condition (as equipped)

BATTERY PERFORMANCE

✔			Battery Terminal / Cables / Mountings
✔			Condition of Battery / Cold Cranking Amps

BATTERY COLD CRANKING AMPS:

Factory Specs: Actual:

COMMENTS / ESTIMATES