



Vehicle History Report #: 45997508  
Report Date: May 13, 2023 | 7:19 PM EDT  
Report Status: Complete

## 2011 HYUNDAI SONATA SE

Sedan | 4 Cylinders | Gas  
5NPEC4AC1BH066785  
Country of Assembly: United States  
Last Reported Odometer: 91,300 KM



Accident/Damage Records  
Found



Last Registered In:  
Ontario (Normal)



19 Service Records Found



No U.S. History Found



5 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.  
Visit us at [support.carfax.ca](https://support.carfax.ca)




This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of May 13, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

## Vehicle History Report



Accident/Damage

5NPEC4AC1BH066785

INCIDENT DATE	DETAILS	AMOUNT
 2023 Mar 16	Ontario, Canada	
	<b>Police Reported Accident:</b> Accident reported: minor damage Vehicle involved in a sideswipe collision with another motor vehicle Damage to front Damage to left front	



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.  
**We checked for:** *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2012 Aug 25	28,263 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b>
2012 Nov 17	31,207 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b>
2013 Mar 23		Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Tire repaired</li></ul>
2013 Jun 15	38,330 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Brakes checked</li><li>Cabin air filter replaced/cleaned</li><li>Air filter replaced</li></ul>
2013 Jun 29	38,425 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Engine/powertrain computer/module checked</li></ul>
2013 Jul 8	39,434 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Engine/powertrain computer/module checked</li></ul>
2013 Oct 5	42,372 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b>
2014 Feb 1	47,600 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b>
2014 May 23	52,350 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Recommended maintenance performed</li><li>Alignment performed</li><li>Steering/suspension checked</li></ul>
2014 Jun 7	53,161 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b>
2014 Aug 23	56,168 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b>

5NPEC4AC1BH066785

	ODOMETER	SOURCE	DETAILS
2015 Jan 10	61,358 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b>
2015 Feb 7	62,163 KM	Active Green & Ross Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Rear brake rotor(s) replaced</li> <li>• Brakes serviced</li> <li>• Tire condition and pressure checked</li> <li>• Tire(s) balanced</li> <li>• Brake pads replaced</li> <li>• Cabin air filter replaced/cleaned</li> <li>• Rear brake pads replaced</li> <li>• Four tires balanced</li> <li>• Four tires mounted</li> <li>• Four wheel alignment performed</li> </ul>
2015 Apr 18	64,203 KM	Active Green & Ross Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Tire(s) balanced</li> <li>• Tire condition and pressure checked</li> <li>• Tire(s) replaced</li> <li>• Lights checked</li> <li>• Light bulb(s) replaced</li> <li>• Oil and filter changed</li> <li>• Four tires balanced</li> <li>• Four tires mounted</li> </ul>
2015 Jul 4	66,978 KM	Active Green & Ross Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Oil and filter changed</li> <li>• Brakes serviced</li> </ul>
2015 Aug 29	69,182 KM	Active Green & Ross Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Brake pads replaced</li> <li>• Brake fluid flushed/changed</li> <li>• Brake rotor(s) replaced</li> <li>• Brakes serviced</li> <li>• Front brake pads replaced</li> </ul>
2015 Nov 7	71,653 KM	Active Green & Ross Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Oil and filter changed</li> <li>• Tire(s) changed</li> </ul>
2015 Nov 24	73,000 KM	Service Facility Thornhill, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Recommended maintenance performed</li> </ul>
2018 Mar 24	91,300 KM	Midas Auto Service Experts Toronto, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Oil and filter changed</li> <li>• Fluids checked</li> </ul>



## Open Recalls

Recall #: R0101 | ENGINE INSPECTION/REPLACEMENT Recall Date: 2015 Dec 07

### Recall Description

On certain vehicles, the engine crankshaft may have not have been properly machined to remove metallic debris during manufacturing. If the debris is not completely removed from the crankshaft's oil passages, it can be forced into the connecting rod oiling passages restricting oil flow to the bearings, increasing the potential of premature bearing wear. If the vehicle continues to be driven with a worn connecting rod bearing, the bearing could fail, which could cause an engine stall while the vehicle is in motion, resulting in loss of motive power which could increase the risk of a crash causing injury and/or property damage. A worn connecting rod bearing could also result in the

5NPEC4AC1BH066785

illumination of the oil pressure lamp in the instrument cluster. Correction: Dealers will inspect, and if necessary, replace the engine assembly. Hyundai will also increase the warranty for the engine sub-assembly (short block) to 10 years/200,000 kilometers for both original and subsequent owners of 2011 and 2012 Sonatas.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](#).

Recall #: R0111 | Sonata Motor Driven Power Steering (MDPS) Assembly or ECU Replacement

Recall Date: 2016 Jul 11

#### Recall Description

On certain vehicles, the electric power steering (EPS) control circuit board could become damaged and fail. If this occurs, a red "EPS" warning lamp will illuminate in the instrument cluster to inform the driver that steering assist is no longer provided. Steering control can be maintained, as the vehicle will revert to a manual steering mode, but will require greater driver effort. The sudden change in steering effort may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the EPS control unit.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](#).

Recall #: R0128 | SONATA ANCHOR PRETENSIONER INSPECTION Recall Date: 2017 Apr 01

#### Recall Description

On certain vehicles, the connections between the front seat belts and the floor mounted seat belt anchor pretensioners may not have been attached properly during assembly. This could result in a front seat belt possibly detaching from the anchor pretensioner. If the vehicle were to be involved in a collision, and the seat belt were to detach, it could increase the risk of injury to the seat occupant. Correction: Dealers will verify the connection between the seat belt linkage and the anchor pretensioner's cable connector for both front seat belts and repair as necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](#).

Recall #: R0153 | Product Improvement Campaign - KSDS Update Recall Date: 2018 Sep 01

#### Recall Description

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of an accident. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: The Transport Canada Campaign number was changed to 2019-640. Vehicles previously repaired under Transport Canada Campaign number 2019-130 do not require this software update. Additional information at [www.hyundaiengineinfo.ca](http://www.hyundaiengineinfo.ca)

This recall was open as of the date/time that this report was generated. For more information, or to find out if the

recall has been closed, please contact HYUNDAI or visit [Hyundai's website](#).

Recall #: R0144 | Airbag Control Unit - Wiring Repair    Recall Date: 2018 Sep 30

**Recall Description**  
On certain gasoline and hybrid engine vehicles, the circuits within the airbag control unit may become damaged. This could cause the airbags and seat belt pretensioners to not deploy in certain collisions where deployment is warranted, which could increase the risk of injury to vehicle occupants. Correction: dealers will install an external wire filter kit that will prevent electrical overstress in the airbag control unit.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](#).



### Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



### Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2010 Jun 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal
2010 Oct 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2011 Sep 17	15,241 KM	Hyundai Canada	Service Record	
2012 Aug 25	28,263 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2012 Oct 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2012 Nov 17	31,207 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2013 Mar 23		Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced

5NPEC4AC1BH066785

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Jun 15	38,330 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2013 Jun 29	38,425 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2013 Jul 8	39,434 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2013 Oct 5	42,372 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 Feb 1	47,600 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 May 23	52,350 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 Jun 7	53,161 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 Aug 23	56,168 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 Oct 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Jan 10	61,358 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Feb 7	62,163 KM	Active Green & Ross Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Apr 18	64,203 KM	Active Green & Ross Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Jul 4	66,978 KM	Active Green & Ross Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Aug 29	69,182 KM	Active Green & Ross Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Nov 7	71,653 KM	Active Green & Ross Thornhill, Ontario,	Service Record	Vehicle serviced

5NPEC4AC1BH066785

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Canada		
2015 Nov 24	73,000 KM	Service Facility Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2015 Dec 7		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0101
2016 Apr 21	75,820 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2016 Jul 11		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0111
2016 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2017 Apr 1		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0128
2017 Sep 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Mar 24	91,300 KM	Midas Auto Service Experts Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Sep 1		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0153
2018 Sep 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Sep 30		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0144
2019 Sep 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2023 Mar 16		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> <li>• minor damage</li> <li>• Vehicle involved in a sideswipe collision</li> <li>• with another motor vehicle</li> <li>• Damage to front</li> <li>• Damage to left front</li> </ul>

5NPEC4AC1BH066785

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Mar 23	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)