



Vehicle History Report #: 48208497
Report Date: August 31, 2023 | 3:57 PM EDT
Report Status: Complete

2013 CHEVROLET EQUINOX LT

Sport utility vehicle | 4 Cylinders | Gas
2GNALDEK1D6100965
Country of Assembly: Canada
Last Reported Odometer: 178,219 KM

LOW
KILOMETRES™



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



8 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of August 31, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

2GNALDEK1D6100965

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2017 Jan 28	Ontario, Canada	
	Claim: Collision	\$1,918.00
2019 Apr 12	Ontario, Canada	
	Claim: Collision	\$1,808.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2015 May 13	Ontario, Canada	
	Glass Record	\$596.00
2019 Apr 23	n/a	
	Damage Event: Damage reported: minor damage Damage to rear	



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Oct 31	5,419 KM	Active Green & Ross Oshawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2014 May 20	11,504 KM	Active Green & Ross Oshawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2014 Sep 15	17,484 KM	Active Green & Ross Oshawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed

2GNALDEK1D6100965

DATE	ODOMETER	SOURCE	DETAILS
2016 Oct 21	55,139 KM	Jiffy Lube King St. Oshawa	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Fluids checked Air filter checked
2017 Dec 30	77,997 KM	Jiffy Lube King St. Oshawa	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Fluids checked
2018 May 19	84,899 KM	Jiffy Lube King St. Oshawa	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Fluids checked Wiper(s) replaced
2021 Dec 20	157,626 KM	Jiffy Lube King St. Oshawa	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Cabin air filter replaced/cleaned Fluids checked Oil and filter changed Headlight bulb(s) replaced
2022 May 2	161,099 KM	Jiffy Lube King St. Oshawa	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed



Open Recalls

Recall #: 2025300 | Front Wiper Transmission Corrosion Failure (Canada Vehicles Only) Recall Date: 2016 Jul 11

Recall Description

"Certain 2010-2017 model year Chevrolet Equinox and GMC Terrain vehicles located in the provinces of British Columbia, Ontario, Quebec, New Brunswick, Prince Edward Island, Nova Scotia and Newfoundland/Labrador may experience high wiper module transmission ball joint corrosion and/or wear which could result in the separation of one or more ball joints from its corresponding socket during operation. If a ball joint were to separate, one or both of the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. The predominant failure mode is water draining through the Air Inlet Panel (AIP) onto the wiper transmission ball joints, leading to grease washout of the link ball sockets. As the grease washes out of the transmission ball joint sockets, contaminants are able to enter the joints causing corrosion and wear of the link ball and socket, resulting in a reduced retention force of the joint. "

Remedy

Dealers will replace the front wiper module with a new module with improved ball joints and a water deflector. In addition, dealers will fill the water management hole near the passenger side wiper pivot and drill a small hole on the adjacent wall of AIP to direct water away from the wiper transmission joints.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](#).

Recall #: N192268180 | Tailpipe Emissions - Oxygen Sensor Recall Date: 2019 Nov 08

2GNALDEK1D6100965

Recall Description

General Motors has decided to conduct a voluntary emissions recall involving certain 2012-2013 Chevrolet Equinox and GMC Terrain vehicles equipped with a 2.4L engine and certified to the EPA Bin 4 emission standard and the California Cleaner Federal Vehicle option of Bin 4 emission standard. The vehicle's post-catalyst oxygen sensor may provide inaccurate information to the engine control module, which manages engine combustion air-fuel ratios. If this condition occurs, tail pipe emissions may exceed allowed limits, without providing any notification to the driver. The malfunction indicator lamp (check engine light) will not illuminate.

Remedy

Dealers are to replace the post-catalyst oxygen sensor.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](#).



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 May 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal
2013 Aug 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2013 Oct 31	5,419 KM	Active Green & Ross Oshawa, Ontario, Canada	Service Record	Vehicle serviced
2014 May 20	11,504 KM	Active Green & Ross Oshawa, Ontario, Canada	Service Record	Vehicle serviced
2014 Aug 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2014 Sep 15	17,484 KM	Active Green & Ross Oshawa, Ontario, Canada	Service Record	Vehicle serviced
2015 May 13		Insurance Records Ontario, Canada	Glass Record	\$596.00
2015 Aug 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Jul 11		CHEVROLET	Recall	Manufacturer Recall Issued Recall # 2025300
2016 Aug 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

2GNALDEK1D6100965

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Oct 21	55,139 KM	Jiffy Lube King St. Oshawa	Service Record	Vehicle serviced
2017 Jan 28		Insurance Records Ontario, Canada		
2017 Aug 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Dec 30	77,997 KM	Jiffy Lube King St. Oshawa	Service Record	Vehicle serviced
2018 May 19	84,899 KM	Jiffy Lube King St. Oshawa	Service Record	Vehicle serviced
2018 Aug 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Apr 12		Insurance Records Ontario, Canada		
2019 Apr 23			Damage Event	Damage reported: minor damage Damage to rear
2019 Nov 8		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192268180
2020 Aug 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Sep 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Dec 20	157,626 KM	Jiffy Lube King St. Oshawa	Service Record	Vehicle serviced
2022 May 2	161,099 KM	Jiffy Lube King St. Oshawa	Service Record	Vehicle serviced
2022 Aug 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2023 Jul 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2023 Aug 3	178,219 KM	Independent Source Oshawa, Ontario, Canada	Odometer reading	



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report,

including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.

