



Vehicle History Report #: 58751337
Report Date: January 17, 2025 | 2:15 p.m. EST
Report Status: Complete


2010 VOLKSWAGEN NEW BEETLE

Convertible | 5 Cylinders | Gas
3VWRW2AL3AM009250
Country of Assembly: Mexico
Last Reported Odometer: 243,602 KM

Low
Kilometres



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



18 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of January 17, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2011 Aug 16	Orangeville, Ontario, Canada	
	Estimate: Non-Collision Estimate Date: 2011 Aug 19	\$3,397.45
	Claim: Miscellaneous	\$3,997.00
2018 Aug 12	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage Vehicle involved in a sideswipe collision with another motor vehicle Damage to left side	

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2016 May 2	Ontario, Canada	
	Glass Record	\$102.00



Registration

- This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.
We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2012 Jul 25	54,198 KM	Service Facility Orangeville, Ontario, Canada	Vehicle serviced
2015 Sep 23		Orangeville Nissan Mono, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Safety inspection performed Emissions or safety inspection performed
2015 Nov 6		Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Vehicle serviced
2016 Jan 13		Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Vehicle serviced
2016 Jan 27	133,465 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Crankshaft position sensor replaced Engine/powertrain computer/module checked
2016 Apr 28	140,985 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Vehicle serviced
2016 Aug 31	144,785 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Headlight bulb(s) replaced Front brake rotor(s) replaced Vibration checked Front brake pads replaced Lights checked

	ODOMETER	SOURCE	DETAILS
		Oakville, Ontario, Canada	<ul style="list-style-type: none"> Battery replaced
2017 May 31	150,673 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> A/C system checked
2017 Oct 31	179,120 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Electrical system checked Rear brake pads replaced Rear brake rotor(s) replaced
2018 May 31	189,098 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2019 Aug 27	214,431 KM	Speedy Auto Service Burlington, Ontario, Canada	Vehicle serviced
2020 Jun 12	223,169 KM	Fitzsimmons & Sons Motor Sales Inc Peterborough, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Noise checked Oil and filter changed
2020 Sep 21	226,747 KM	Cross Avenue Auto Oakville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Fog light assembly replaced Fog light bulb(s) replaced
2021 Feb 18	230,265 KM	Cross Avenue Auto Oakville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brakes checked Trunk release switch/cable/handle replaced Front brake rotor(s) replaced Brake calipers cleaned/serviced Idler pulley replaced Serpentine tensioner replaced Drive belt(s) replaced Serpentine belt replaced Drive belts checked A/C system serviced Cooling system bled Radiator replaced Cooling system checked Antifreeze/coolant flushed/changed Front brake pads replaced Rear brake pads replaced Rear brake rotor(s) replaced
2021 Jun 11	232,264 KM	Cross Avenue Auto Oakville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> A/C system checked Oil and filter changed Oil pan replaced/repared Fluids checked Engine oil/fluid leak checked Tire(s) balanced Four tires balanced Four tires mounted Four tires replaced
2024 Dec 15	243,373 KM	Kal Tire Waterloo, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire(s) changed
2024 Dec 18	243,602 KM	Master Mechanic Collingwood Collingwood, Ontario, Canada	Vehicle serviced

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact VOLKSWAGEN or visit Volkswagen's website. (<https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html>)

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
------	----------	--------	-------------	---------

IRW2AL3AM009250

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
				Previous Use: Personal Vehicle colour noted as beige
2011 Feb 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2011 Aug 16		Insurance Records Ontario, Canada		
2011 Aug 19	30,797 KM	Insurance Records Orangeville, Ontario, Canada	Estimate Repair	Incident Date: 2011-08-16 Non-Collision
2012 Jul 25	54,198 KM	Service Facility Orangeville, Ontario, Canada	Service Record	Vehicle serviced
2013 Feb 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2014 Feb 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Feb 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Sep 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as beige
2015 Sep 23		Orangeville Nissan Mono, Ontario, Canada	Service Record	Vehicle serviced
2015 Nov 6		Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Service Record	Vehicle serviced
2016 Jan 13		Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Service Record	Vehicle serviced
2016 Jan 27	133,465 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 28	140,985 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Service Record	Vehicle serviced
2016 May 2		Insurance Records Ontario, Canada	Glass Record	\$102.00
2016 Aug 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Aug 31	144,785 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Service Record	Vehicle serviced
2016 Oct 27		Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Service Record	Vehicle serviced
2017 May 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 May 31	150,673 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Service Record	Vehicle serviced
2017 Jun 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Oct 31	179,120 KM	Good Neighbour Garage Signature Tire Oakville, Ontario, Canada	Service Record	Vehicle serviced
2018 May 31	189,098 KM	Good Neighbour Garage	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Aug 12		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • minor damage • Vehicle involved in a sideswipe collision • with another motor vehicle • Damage to left side
2019 Jul 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Aug 27	214,431 KM	Speedy Auto Service Burlington, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 12	223,169 KM	Fitzsimmons & Sons Motor Sales Inc Peterborough, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 21	226,747 KM	Cross Avenue Auto Oakville, Ontario, Canada	Service Record	Vehicle serviced
2021 Feb 18	230,265 KM	Cross Avenue Auto Oakville, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 11	232,264 KM	Cross Avenue Auto Oakville, Ontario, Canada	Service Record	Vehicle serviced
2024 Jul 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Dec 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2024 Dec 15	243,373 KM	Kal Tire Waterloo, Ontario, Canada	Service Record	Vehicle serviced
2024 Dec 18	243,602 KM	Master Mechanic Collingwood Collingwood, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>