



Vehicle History Report #: 32443390  
Report Date: March 17, 2021 | 03:21 PM EST  
Report Status: Complete

# 2009 NISSAN MURANO S

Sport utility vehicle | 6 Cylinders | Gas  
JN8AZ18W19W149931  
Country of Assembly: Japan  
Last Reported Odometer: 235,336 KM



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



13 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.  
1.866.835.8612 | [support.carfax.ca](https://support.carfax.ca)

JN8AZ18W19W149931

# Vehicle History Report



## Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



## Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

**We checked for:** *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2009 Oct 22		Krown Concord Vaughan, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Undercoating/rustproofing applied</li> </ul>
2017 Dec 14	187,316 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> </ul>
2018 Apr 26		Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> </ul>
2018 Jul 20	199,163 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Light bulb(s) replaced</li> <li>Oil and filter changed</li> <li>Air filter replaced</li> <li>License plate light bulb(s) replaced</li> </ul>
2018 Aug 10	200,061 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Steering/suspension checked</li> </ul>
2018 Oct 22	204,607 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> </ul>
2019 Jan 19	209,791 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Light bulb(s) replaced</li> <li>Oil and filter changed</li> </ul>
2020 Jan 21	225,046 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>

JN8AZ18W19W149931

DATE	ODOMETER	SOURCE	DETAILS
2020 Apr 21	227,861 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Brakes serviced</li> <li>• Brake fluid flushed/changed</li> <li>• Rear brake pads replaced</li> <li>• Rear brake rotor(s) replaced</li> <li>• Front brake rotor(s) replaced</li> <li>• Front brake pads replaced</li> </ul>
2020 May 14	229,249 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Oil and filter changed</li> </ul>
2020 Jul 8	231,453 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• A/C refrigerant recharged</li> <li>• Brakes checked</li> </ul>
2020 Aug 26	233,619 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Cooling system checked</li> <li>• Cooling system serviced</li> </ul>
2020 Oct 23	235,336 KM	Active Green & Ross Woodbridge, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Oil and filter changed</li> </ul>

## Open Recalls

Recall #: R1814 | MURANO BRAKE FLUSH NTB18-087 Recall Date: 2018 Jan 02

### Recall Description

The preventative zinc coating used on the normally closed (NC) valve armatures within ABS Hydraulic Control Units (HCU) may react with brake fluids containing specific corrosion preventative additives. This reaction can cause the formation of a gelatinous material, which may cause the NC valves to close slowly. Over time, the gel can solidify to an extent such that the spring used to return the valve to the closed position may not be able to overcome the gel buildup, allowing the NC valve to remain open.

### Remedy

Nissan will notify all owners of potentially affected vehicles within 60 days. For owners of vehicles previously subject to a Service Campaign that have not yet remedied their vehicles, Nissan will also issue a Part 577 letter to re-notify them. The remedy remains unchanged. Dealers will flush the brake system with DOT 4 fluid. The HCU will then be tested to detect a possible stuck valve condition. If necessary, HCU will be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).

## Stolen Vehicle Check

 This vehicle is not actively declared stolen.

## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2008 Nov 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	First Owner Reported
2008 Nov 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2008 Nov 20		Motor Vehicle Dept. Ontario, Canada	Previous use	Commercial
2009 Apr 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2009 Apr 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Apr 15		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2009 Oct 22		Krown Concord Vaughan, Ontario, Canada	Service Record	Vehicle serviced
2011 Apr 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2011 Apr 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Apr 15		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2012 Apr 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Apr 15		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2014 Apr 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Apr 15		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2015 Aug 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Aug 19		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2015 Oct 7	142,000 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2015 Oct 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2016 Aug 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed

JN8AZ18W19W149931

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Aug 30		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2017 Aug 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Aug 19		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2017 Dec 14	187,316 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 2		NISSAN	Recall	Manufacturer Recall Issued Recall # R1814
2018 Apr 26		Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2018 Jul 20	199,163 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2018 Aug 10	200,061 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2018 Aug 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Aug 19		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2018 Oct 22	204,607 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 19	209,791 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Aug 19		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2020 Jan 21	225,046 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2020 Apr 21	227,861 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced

JN8AZ18W19W149931

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 May 14	229,249 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2020 Jul 8	231,453 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2020 Aug 26	233,619 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 23	235,336 KM	Active Green & Ross Woodbridge, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

1.866.835.8612 | [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.

