



Vehicle History Report #: 32757039
Report Date: April 6, 2021 | 12:26 PM EST
Report Status: Complete

2012 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas
3VW2K7AJXCM420849
Country of Assembly: Mexico
Last Reported Odometer: 111,103 KM

NO REPORTED ACCIDENTS*



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)




8 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
1.866.835.8612 | support.carfax.ca

3VW2K7AJXCM420849

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Jul 14	20,822 KM	Belleville Volkswagen Belleville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Lights checked
2015 Apr 22	28,035 KM	Belleville Volkswagen Belleville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Engine/powertrain computer/module checked
2015 Jul 9	30,436 KM	Belleville Volkswagen Belleville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Lights checked
2016 Jan 26	35,158 KM	Ralph Ruffo Service CTR - Autopro Peterborough, Ontario, Canada	Vehicle serviced
2018 Apr 11	86,703 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Rear brake pads replaced
2018 Apr 23	86,903 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced
2018 Dec 14	97,570 KM	Steve`s Auto Repair Lakefield, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Emissions inspection performed
2019 Aug 8	111,103 KM	Humberview Volkswagen Toronto, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tires rotated Tire condition and pressure checked



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](#).

**Stolen Vehicle Check**

✔ This vehicle is not actively declared stolen.

**Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Aug 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	First Owner Reported
2012 Aug 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2014 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Jul 14	20,822 KM	Belleville Volkswagen Belleville, Ontario, Canada	Service Record	Vehicle serviced
2015 Apr 22	28,035 KM	Belleville Volkswagen Belleville, Ontario, Canada	Service Record	Vehicle serviced
2015 Jul 9	30,436 KM	Belleville Volkswagen Belleville, Ontario, Canada	Service Record	Vehicle serviced
2016 Jan 26	35,158 KM	Ralph Ruffo Service CTR - Autopro Peterborough, Ontario, Canada	Service Record	Vehicle serviced
2016 Jan 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported

3WV2K7AJXCM420849

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jan 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jan 27		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2017 Jan 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jan 11		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2018 Apr 11	86,703 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 23	86,903 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Dec 14	97,570 KM	Steve`s Auto Repair Lakefield, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 8	111,103 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2021 Jan 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jan 14		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2021 Mar 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported



Questions? We're here to help.

1.866.835.8612 | support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

3WV2K7AJXCM420849

