



Vehicle History Report #: 36314980
Report Date: November 5, 2021 | 11:59 AM EST
Report Status: Complete

2010 MITSUBISHI OUTLANDER XLS

Sport utility vehicle | 6 Cylinders | Gas
JA4JT3AX9AZ608390
Country of Assembly: Japan
Last Reported Odometer: 213,567 KM

LOW
KILOMETRES™



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



7 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of November 5, 2021 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

JA4JT3AX9AZ608390

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
 2019 Dec 7	London, Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage with another motor vehicle Damage to rear	
	Estimate: Rear Center Estimate Date: 2019 Dec 10	\$4,207.85
	Claim: Other Damage	\$4,208.00



Registration

 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Jul 25	70,697 KM	Service Facility London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Brakes checked
2015 Aug 7		Service Facility London, Ontario, Canada	Vehicle serviced
2016 Jun 20	79,188 KM	Service Facility London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Four tires balanced Four tires mounted Vehicle washed/detailed Emissions inspection performed
2016 Jul 25	79,204 KM	Service Facility London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed Emissions inspection performed
2016 Jul 28		Service Facility London, Ontario, Canada	Vehicle serviced

JA4JT3AX9AZ608390

DATE	ODOMETER	SOURCE	DETAILS
2020 Jun 4	166,162 KM	Napa AutoPro Wellington London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Radiator hose clamp replaced Power steering checked Brake line(s) replaced/repared Exhaust system checked Exhaust pipe seal replaced Power steering hose(s)/line(s) replaced
2021 Apr 1	192,824 KM	Napa AutoPro Wellington London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Sway bar link(s) replaced Rear brakes serviced/adjusted Front strut(s) replaced



Open Recalls

Recall #: SR-16-003 | FRONT CROSS MEMBER CORROSION - INSPECT & REPLACE IF NECESSARY. C Recall Date: 2016 Jun 20

Recall Description

THE INSIDE AND OUTSIDE SURFACES OF THE FRONT CROSS MEMBERS USED ON CERTAIN VEHICLES, IF EXPOSED LONG TERM TO SNOW MELT WATER AND ANTI-FREEZING AGENTS, MAY CORRODE DUE TO INSUFFICIENT PERFORMANCE OF THE RUST PROTECTION. SHOULD SIGNIFICANT CORROSION OCCUR OVER TIME, A LOWER CONTROL ARM COULD EVENTUALLY BECOME DETACHED RESULTING IN LOSS OF VEHICLE CONTROL AND A POTENTIAL COLLISION.

Remedy

THE CROSS MEMBER WILL BE INSPECTED AND THE FOLLOWING ACTION WILL BE TAKEN AT NO CHARGE TO THE CUSTOMER: 1) IF NO SIGNIFICANT CORROSION IS IDENTIFIED, A SEALING/ANTICORROSION AGENT WILL BE SPRAYED INSIDE/OUTSIDE THE CROSS MEMBER; 2) IN THE EVENT THAT SIGNIFICANT CORROSION IS IDENTIFIED, THE CROSS MEMBER WILL BE REPLACED WITH A NEW ONE THAT HAS A SEALING/ANTICORROSION AGENT SPRAYED INSIDE/OUTSIDE THE CROSS MEMBER.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).

Recall #: SR-16-009 | 2007-2013 OUTLANDER -REPLACE WIPER LINK (PERFORM AT SAME TIME AS Recall Date: 2016 Oct 26

Recall Description

IN THE EVENT THAT WATER DROPS DOWN THROUGH THE BACK SIDE OF THE FRONT DECK GARNISH (THE BODY PIECE BETWEEN THE HOOD AND WINDSHIELD), THE FRONT WIPER LINK BALL JOINT MAY EXPERIENCE EXCESSIVE MOISTURE AND CORRODE. IF THIS OCCURS, THE RESIN CASE OF THE BALL JOINT WILL WEAR PREMATURELY DUE TO THE BALL JOINT CORROSION AND THE WIPER LINK MAY ULTIMATELY SEPARATE CAUSING THE WINDSHIELD WIPERS TO STOP OPERATING.

Remedy

OWNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING IN THEIR VEHICLES FOR THE REPAIR. AT NO CHARGE TO THE CUSTOMER, THE RUBBER BOOT WHICH COVERS THE BALL JOINT WILL BE REPLACED WITH A COUNTERMEASURE ONE TO PREVENT WATER INTRUSION. THE WIPER MOTOR CRANK ARM WILL ALSO BE INSPECTED AND REPLACED AS NECESSARY IN CASE OF EXCESSIVE FREE PLAY ON THE LINK.

JA4JT3AX9AZ608390

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).

Recall #: SR-17-003 | 2007-2013MY OUTLANDER -REPLACE WIPER MOTOR (PERFORM AT SAME TIME Recall Date: 2017 Jul 20

Recall Description

WATER CAN POTENTIALLY DROP DOWN ONTO THE FRONT WIPER MOTOR THROUGH A GAP BETWEEN THE FRONT DECK GARNISH (THE BODY PIECE BETWEEN THE HOOD AND WINDSHIELD) AND THE FRONT WINDSHIELD. IF THIS OCCURS, WATER COULD POTENTIALLY COLLECT IN THE AREA OF THE WIPER MOTOR BREATHING HOLE. IF THE WIPER MOTOR IS NOT OPERATING, THIS WATER CAN THEN POTENTIALLY ENTER THE WIPER MOTOR THROUGH THE BREATHING HOLE. IF THIS OCCURS, SUCH WATER INTRUSION OVER TIME MAY CAUSE INTERNAL CORROSION AND/OR ELECTRICAL CONDUCTION FAILURE RESULTING IN NON-OPERATION OF THE WINDSHIELD WIPER MOTOR.

Remedy

OWNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING IN THEIR VEHICLES FOR REPAIR. AT NO CHARGE TO THE CUSTOMER, THE WIPER MOTOR WILL BE REPLACED WITH AN UPGRADED WIPER MOTOR THAT WILL PREVENT WATER INTRUSION.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2010 Dec 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	First Owner Reported
2010 Dec 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Apr 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Apr 10		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2012 May 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2012 May 1		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2012 Nov 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported

JA4JT3AX9AZ608390

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Nov 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Nov 30		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2013 Oct 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Oct 26		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2014 Oct 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Oct 26		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2015 Jul 25	70,697 KM	Service Facility London, Ontario, Canada	Service Record	Vehicle serviced
2015 Aug 7		Service Facility London, Ontario, Canada	Service Record	Vehicle serviced
2015 Oct 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Oct 26		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2015 Dec 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Dec 17		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2016 Jun 20	79,188 KM	Service Facility London, Ontario, Canada	Service Record	Vehicle serviced
2016 Jun 20		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-16-003
2016 Jul 25	79,204 KM	Service Facility London, Ontario, Canada	Service Record	Vehicle serviced
2016 Jul 28		Service Facility London, Ontario, Canada	Service Record	Vehicle serviced
2016 Oct 26		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-16-009
2016 Nov 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Nov 2		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal

JA4JT3AX9AZ608390

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Jul 20		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-17-003
2017 Nov 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Nov 2		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2018 Dec 15	138,250 KM	Independent Source London, Ontario, Canada	Odometer reading	
2019 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2019 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Feb 23		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2019 May 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2019 Dec 7		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • minor damage • with another motor vehicle • Damage to rear
2019 Dec 7		Insurance Records Ontario, Canada		
2019 Dec 7	158,856 KM	Insurance Records London, Ontario, Canada	Estimate Repair	Estimate Date: 12/10/2019 Rear Center
2020 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Feb 23		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2020 Jun 4	166,162 KM	Napa AutoPro Wellington London, Ontario, Canada	Service Record	Vehicle serviced
2021 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Feb 23		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2021 Apr 1	192,824 KM	Napa AutoPro Wellington London, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 31	213,567 KM	Independent Source London, Ontario, Canada	Odometer reading	

JA4JT3AX9AZ608390



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.

