


# 2006 NISSAN FRONTIER KING CAB LE

Pickup | 6 Cylinders | Gas  
1N6AD06U16C447136  
Country of Assembly: United States  
Last Reported Odometer: 118,053 KM




Accident/Damage Records Found



Last Registered In:  
**British Columbia (Normal)**



4 Service Records Found



U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



Import Record Found

Questions? We're here to help.

1.866.835.8612 | [support.carfax.ca](mailto:support.carfax.ca)



**This vehicle history report is based on information that was reported and available to CARFAX Canada as of August 17, 2021** (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report (BC)



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2010 May 20	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> LEFT SIDE   Estimate Date: n/a	\$0.00
	<b>Claim:</b> COLLISION LEFT SIDE	\$0.00
2010 Jul 7	<b>British Columbia, Canada</b>	
	<b>Claim:</b> THEFT FROM AUTO	\$0.00
2019 Feb 13	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> RIGHT FRONT CORNER   Estimate Date: n/a	\$2,314.21
	<b>Claim:</b> COLLISION RIGHT FRONT CORNER	\$2,314.21



## Registration

- This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

- This vehicle has been registered in the state of **Washington** in the **United States**. No major title problems were reported.

**We checked for:** Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2006 Apr 29		Puyallup Nissan Puyallup, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Pre-delivery inspection completed</li></ul>
2006 Nov 1		King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b>
2007 Oct 30		King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b>
2021 Mar 25	118,053 KM	Service Facility	<b>Vehicle serviced</b>





## Open Recalls

Recall #: PC068 | NISSAN ECM RELAY NTB10-137 Recall Date: 2010 Dec 02

### Recall Description

THE INTELLIGENT POWER DISTRIBUTION MODULE (IPDM) ASSEMBLY CONTAINS AN ENGINE CONTROL MODULE (ECM) RELAY THAT HAS A DIODE FOR ELECTRICAL CURRENT NOISE REDUCTION. THE ECM RELAY MAY ALLOW SILICON VAPOR TO FORM AND, OVER TIME, THE SILICON EVAPORATES FROM THE DIODE MOLDING WHICH CAUSES SILICON OXIDE TO DEVELOP ON THE ECM RELAY CONTACT DUE TO ARCING.

### Remedy

DEALERS WILL REPLACE THE ECM RELAY INSIDE THE IPDM ASSEMBLY.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).









## Stolen Vehicle Check

This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2006 Apr 29		Puyallup Nissan Puyallup, Washington, United States	Service Record	Vehicle serviced
 2006 Sep 13		Motor Vehicle Dept. Washington, United States	DMV Record Adjustment	First Owner Reported
 2006 Sep 13		Motor Vehicle Dept. Washington, United States	DMV Record Adjustment	Loan or lien reported
 2006 Sep 13		Motor Vehicle Dept. Washington, United States	DMV Record Adjustment	Title issued or updated
 2006 Sep 13		Motor Vehicle Dept. Washington, United States	Previous use	Personal
 2006 Nov 1		King Nissan SERVICE	Service Record	Vehicle serviced

Bellingham, Washington,  
United States

 2007 Aug 7	Motor Vehicle Dept. Washington, United States	DMV Record Adjustment	Registration Issued or Renewed
 2007 Oct 30	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
 2007 Nov 27	Motor Vehicle Dept. Canada	Import Record	<b>From:</b> United States <b>To:</b> Canada  This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV ( <a href="http://www.riv.ca">www.riv.ca</a> ).  Imported Into Canada As: Case/Dossier: <b>J332877</b> Import Date: <b>11/27/2007</b> Entered Customs: <b>11/27/2007</b> Inspection Date: <b>12/7/2007</b>
2007 Dec 6	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2008 Dec 13	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Dec 12	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 May 20	Insurance Records British Columbia, Canada	COLLISION	LEFT SIDE
2010 May 20	Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT SIDE
2010 Jul 7	Insurance Records British Columbia, Canada	THEFT FROM AUTO	
2010 Dec 2	NISSAN	Recall	Manufacturer Recall Issued Recall # PC068
2010 Dec 11	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Dec 10	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Dec 8	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



2013 Dec 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Dec 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Nov 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Dec 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Dec 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Oct 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Feb 13		Insurance Records British Columbia, Canada	COLLISION	RIGHT FRONT CORNER
2019 Feb 13		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT FRONT CORNER
2019 Oct 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Feb 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Feb 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Mar 25	118,053 KM	Service Facility Langley, British Columbia, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

1.866.835.8612 | [support.carfax.ca](https://support.carfax.ca)

#### ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.



1N6AD06U16C447136





UNIT #8 - 20071 113B AVENUE  
 MAPLE RIDGE, BC V2X 0Z2  
 O: 604 460 7142  
 C: 604 721 1432  
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

*Cyross* MULTI-POINT INSPECTION

Name: AUTO BROKER Year/Make/Model: 2006 NISSAN FRONTIER KMs: 167949

RO#: 2601 VIN: 1N6AD07U56C434596 License: \_\_\_\_\_

■ CHECKED AND OK      ■ FUTURE ATTENTION      ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR			
NOTE ANY EXISTING BODY DAMAGE			
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

TIRES			
TREAD DEPTH			
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32"	<input type="checkbox"/> 2/32" or less	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"		
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"		
	Wear Pattern/Damage	Air Pressure	Based on Mileage and Wear:
	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Alignment
	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE SHOULD BE	<input type="checkbox"/> Balance
	LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LF 25 35	<input type="checkbox"/> Rotation
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF 25 35	<input type="checkbox"/> New Tire	
		LR 25 35	
		RR 25 35	

BATTERY			

BRAKES			
BRAKE PADS / SHOES			
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)			
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)			
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)			
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			

UNDERHOOD			
Oil Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

UNDER VEHICLE			
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

COMMENTS
<i>BRAKE PADS</i>
<i>FRONT 9mm</i>
<i>REAR 8mm</i>

INSPECTOR: JIM DATE: 4/24/2021



# Invoice

Ridge Motors Auto Repair and Tires  
 Unit 8 - 20071 113B Avenue  
 Maple Ridge, BC V2X 0Z2  
 (604) 460-7142

Date	Invoice #
11/24/2021	2601

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

Vehicle Description
2006 Nissan Frontier

ODO IN	ODO OUT	Plate	VIN
167949			1n6ad07u56c434596

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...		80.00	80.00	G
		GST on sales	5.00%	4.00	
			<b>Sales Tax Total</b>	\$4.00	
			<b>Total</b>	\$84.00	

I herby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I herby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized herby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature \_\_\_\_\_





**JIFFY LUBE #1087**

20284 Dewdney Trunk Rd  
 Maple Ridge, BC V2X 3E1  
 (604) 465-0181

DATE	9/16/2021 11:57 AM
TRANSACTION NO	21091600016374
INVOICE NO	01087-16374
VEHICLE ID	BC-CYP

Customer Information	Service History
Cypress Auto Brokers 11919 Maple Meadows Way MAPLE RIDGE, BC V2X 3M7 (604) 465-3313	<b>DATE KILOMETERS SERVICES</b> 9/16/21 121238 CYP OF RAD AFC

Vehicle Information
2006 NISSAN/DATSUN FRONTIER 6cyl 4.0L FI <b>VIN 0</b> <b>KILOMETERS 121238</b> <b>ALT ID</b>

Employees								
<table border="0"> <tr> <td><b>UPPER</b></td> <td><b>LOWER</b></td> <td><b>COURTESY</b></td> <td><b>CASHIER</b></td> </tr> <tr> <td>PARI</td> <td>GURP</td> <td>ISHAN</td> <td></td> </tr> </table>	<b>UPPER</b>	<b>LOWER</b>	<b>COURTESY</b>	<b>CASHIER</b>	PARI	GURP	ISHAN	
<b>UPPER</b>	<b>LOWER</b>	<b>COURTESY</b>	<b>CASHIER</b>					
PARI	GURP	ISHAN						

Service Comments
THANK YOU FOR YOUR BUSINESS!!!

Service Checklist	Description	Qty.	Price
1. CHASSIS LUBRICATION	SEALED	CYP OIL PACKAGE	1.00 39.99
2. REAR DIFFERENTIAL	FULL	OF4622 OIL FILTER	1.00 0.00
3. TRANS/TRANSAXLE FLUID	FULL	PENNZOIL 5W30 OIL	5.10 0.00
4. LIGHT CHECK	CHECKED OK	RADIATOR COOLANT FLUSH	1.00 99.99
5. WIPER BLADES	CUST. OK'D	ECO (GREEN) ANTIFREEZE	10.0 0.00
6. AIR FILTER	CHECKED		
7. CABIN AIR FILTER	NO CHECK	<b>SUBTOTAL</b>	<b>\$139.98</b>
8. FUEL FILTER	NA	(AIR)	-0.00
9. POWER STEERING FLUID	FULL	\$10 OFF COUPON (10)	-10.00
10. BRAKE FLUID	LEVEL OK	<b>SALE</b>	<b>\$129.98</b>
11. BATTERY	CHECKED OK		
12. RADIATOR FLUID	ADDED		
13. WINDSHIELD WASH FLUID	ADDED		
14. TRANSFER CASE FLUID	N/A	GST TAX	6.50
15. FRT DIFFERENTIAL FLUID	N/A	PST TAX (Exempt 10144575)	0.00
16. CV BOOTS	CHECKED OK	<b>TOTAL</b>	<b>\$136.48</b>
17. SHOCKS/STRUTS	APPEARS O.K	VISA 7313 AUTH: 090871	136.48
18. TIRES	F__R__		
19. U JOINTS	N/A	<b>CHANGE</b>	<b>\$0.00</b>
20. BELTS AND HOSES	CHECK OK		

**Warranty Statement**

This Jiffy Lube centre warrants all workmanship against failure for 7 days from the date of service. This warranty does not apply when the customer tampers with or alters the centre's products or alters the manufacturer's original equipment or when corrective action is taken without prior written approval from this Jiffy Lube service centre. The customer must have the limited warranty certificate and must retain a sample of the product(s) involved. \_\_ Oil Level Shown \_\_ Oil Filter Tight \_\_ Drain Plug Tight \_\_ Rear Diff Chk Plug \_\_ Front Diff Chk Plug \_\_ Transfer Case Chk Plug \_\_ Transmission Chk Plug

\*OPEN SUN - SAT 9-6. ANY QUESTIONS CALL +04-465-0181  
 APPROPRIATE, WARRANTY-APPROVED PRODUCT MAY HAVE BEEN SUBSTITUTED.  
  
**Recommend next service on 03/15/2022 or 124738 km.**

**X**

Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.