

2006 NISSAN FRONTIER KING CAB LE

Pickup | 6 Cylinders | Gas


1N6AD06U16C447136

Country of Assembly: United States

Last Reported Odometer: 118,053 KM




Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



4 Service Records Found



U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



Import Record Found

Questions? We're here to help.

1.866.835.8612 | support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of August 17, 2021 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2010 May 20	British Columbia, Canada	
	Estimate: LEFT SIDE Estimate Date: n/a	\$0.00
	Claim: COLLISION LEFT SIDE	\$0.00
2010 Jul 7	British Columbia, Canada	
	Claim: THEFT FROM AUTO	\$0.00
2019 Feb 13	British Columbia, Canada	
	Estimate: RIGHT FRONT CORNER Estimate Date: n/a	\$2,314.21
	Claim: COLLISION RIGHT FRONT CORNER	\$2,314.21



Registration

- This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

- This vehicle has been registered in the state of **Washington** in the **United States**. No major title problems were reported.

We checked for: Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2006 Apr 29		Puyallup Nissan Puyallup, Washington, United States	Vehicle serviced <ul style="list-style-type: none">Pre-delivery inspection completed
2006 Nov 1		King Nissan SERVICE Bellingham, Washington, United States	Vehicle serviced
2007 Oct 30		King Nissan SERVICE Bellingham, Washington, United States	Vehicle serviced
2021 Mar 25	118,053 KM	Service Facility	Vehicle serviced



Open Recalls

Recall #: PC068 | NISSAN ECM RELAY NTB10-137 Recall Date: 2010 Dec 02

Recall Description

THE INTELLIGENT POWER DISTRIBUTION MODULE (IPDM) ASSEMBLY CONTAINS AN ENGINE CONTROL MODULE (ECM) RELAY THAT HAS A DIODE FOR ELECTRICAL CURRENT NOISE REDUCTION. THE ECM RELAY MAY ALLOW SILICON VAPOR TO FORM AND, OVER TIME, THE SILICON EVAPORATES FROM THE DIODE MOLDING WHICH CAUSES SILICON OXIDE TO DEVELOP ON THE ECM RELAY CONTACT DUE TO ARCING.

Remedy

DEALERS WILL REPLACE THE ECM RELAY INSIDE THE IPDM ASSEMBLY.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).









Stolen Vehicle Check




This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2006 Apr 29		Puyallup Nissan Puyallup, Washington, United States	Service Record	Vehicle serviced
 2006 Sep 13		Motor Vehicle Dept. Washington, United States	DMV Record Adjustment	First Owner Reported
 2006 Sep 13		Motor Vehicle Dept. Washington, United States	DMV Record Adjustment	Loan or lien reported
 2006 Sep 13		Motor Vehicle Dept. Washington, United States	DMV Record Adjustment	Title issued or updated
 2006 Sep 13		Motor Vehicle Dept. Washington, United States	Previous use	Personal
 2006 Nov 1		King Nissan SERVICE	Service Record	Vehicle serviced

Bellingham, Washington,
United States

 2007 Aug 7	Motor Vehicle Dept. Washington, United States	DMV Record Adjustment	Registration Issued or Renewed
 2007 Oct 30	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
 2007 Nov 27	Motor Vehicle Dept. Canada	Import Record	From: United States To: Canada This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV (www.riv.ca). Imported Into Canada As: Case/Dossier: J332877 Import Date: 11/27/2007 Entered Customs: 11/27/2007 Inspection Date: 12/7/2007
2007 Dec 6	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2008 Dec 13	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Dec 12	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 May 20	Insurance Records British Columbia, Canada	COLLISION	LEFT SIDE
2010 May 20	Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT SIDE
2010 Jul 7	Insurance Records British Columbia, Canada	THEFT FROM AUTO	
2010 Dec 2	NISSAN	Recall	Manufacturer Recall Issued Recall # PC068
2010 Dec 11	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Dec 10	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Dec 8	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

2013 Dec 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Dec 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Nov 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Dec 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Dec 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Oct 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Feb 13		Insurance Records British Columbia, Canada	COLLISION	RIGHT FRONT CORNER
2019 Feb 13		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT FRONT CORNER
2019 Oct 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Feb 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Feb 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Mar 25	118,053 KM	Service Facility Langley, British Columbia, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

1.866.835.8612 | support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.



1N6AD06U16C447136



UNIT #8 - 20071 113B AVENUE
 MAPLE RIDGE, BC V2X 0Z2
 O: 604 460 7142
 C: 604 721 1432
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

Cyross MULTI-POINT INSPECTION

Name: AUTO BROKER Year/Make/Model: 2006 NISSAN FRONTIER KMs: 167949

RO#: 2601 VIN: 1N6AD07U56C434596 License: _____

■ CHECKED AND OK ■ FUTURE ATTENTION ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR			
NOTE ANY EXISTING BODY DAMAGE			
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

TIRES			
TREAD DEPTH			
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32"	<input type="checkbox"/> 2/32" or less	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"		
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"		
	Wear Pattern/Damage	Air Pressure	Based on Mileage and Wear:
	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Alignment
	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE SHOULD BE	<input type="checkbox"/> Balance
	LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LF 25 35	<input type="checkbox"/> Rotation
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF 25 35	<input type="checkbox"/> New Tire	
		LR 25 35	
		RR 25 35	

BATTERY			
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

BRAKES			
BRAKE PADS / SHOES			
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)			
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)			
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)			
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			

UNDERHOOD			
Oil Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

UNDER VEHICLE			
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

COMMENTS
<i>BRAKE PADS</i>
<i>FRONT 9mm</i>
<i>REAR 8mm</i>

INSPECTOR: JIM DATE: 4/24/2021

Invoice

Ridge Motors Auto Repair and Tires
 Unit 8 - 20071 113B Avenue
 Maple Ridge, BC V2X 0Z2
 (604) 460-7142

Date	Invoice #
11/24/2021	2601

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadow Way Maple Ridge BC V2X3M7

Vehicle Description
2006 Nissan Frontier

ODO IN	ODO OUT	Plate	VIN
167949			1n6ad07u56c434596

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...		80.00	80.00	G
		GST on sales	5.00%	4.00	
			Sales Tax Total	\$4.00	
			Total	\$84.00	

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature _____

