



# 2011 NISSAN JUKE S

Sport utility vehicle | 4 Cylinders | Gas

JN8AF5MV5BT010793

Country of Assembly: Japan

Last Reported Odometer: 49,859 MI

ONE OWNER

NO REPORTED ACCIDENTS

## LIEN CHECK



No Lien Records Found




Glass Records found



Last Registered In:  
**British Columbia (Normal)**



16 Service Records Found



U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on information that was reported and available to CARFAX Canada as of January 12, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report + Lien Check (BC)

## Lien Check

 No lien records found in **British Columbia**.

### How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

### CARFAX Canada Canadian Lien Guarantee





If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

## Accident/Damage

 There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

## Other Damage Records

RECORD DATE	DETAILS	AMOUNT
 2013 Oct 8	British Columbia, Canada	
	Glass Record	\$587.46
 2018 Mar 3	British Columbia, Canada	
	Glass Record	\$408.10

## Registration


 This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.





# Service Records

DATE	ODOMETER	SOURCE	DETAILS
 2010 Dec 15		King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Pre-delivery inspection completed</li></ul>
 2011 Jul 22	3,758 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Oil and filter changed</li></ul>
 2011 Dec 22	7,809 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Oil and filter changed</li><li>• Tire condition and pressure checked</li><li>• Tires rotated</li></ul>
 2012 Jan 24	8,102 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Electrical system checked</li></ul>
 2012 Jun 28	12,288 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Oil and filter changed</li></ul>
 2012 Jul 13	13,071 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b>
 2012 Nov 23	16,496 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• 15,000 mile service performed</li></ul>
 2013 Mar 19	21,178 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Electrical system checked</li><li>• Oil and filter changed</li></ul>
 2013 Jul 12	25,374 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Oil and filter changed</li><li>• Tire condition and pressure checked</li><li>• Tires rotated</li></ul>
 2013 Oct 25	29,777 MI	King Nissan SERVICE Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• 30,000 mile service performed</li></ul>
 2014 Mar 11	33,908 MI	Wilson Motors Nissan Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Oil and filter changed</li></ul>
 2014 Jul 1	38,157 MI	Wilson Motors Nissan Bellingham, Washington, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Maintenance inspection completed</li><li>• Oil and filter changed</li></ul>
 2014 Jul 14	38,536 MI	Wilson Motors Nissan	<b>Vehicle serviced</b>

Bellingham, Washington, United States

- Brakes checked



2014 Oct 13

42,602 MI

Wilson Motors Nissan  
Bellingham, Washington, United States

**Vehicle serviced**

- Maintenance inspection completed
- Brakes checked
- Oil and filter changed
- Air filter replaced
- Cabin air filter replaced/cleaned



2014 Dec 31

45,588 MI

Wilson Motors Nissan  
Bellingham, Washington, United States

**Vehicle serviced**

- Oil and filter changed
- Cabin air filter replaced/cleaned
- Battery/charging system checked



2015 Apr 22

49,859 MI

Wilson Motors Nissan  
Bellingham, Washington, United States

**Vehicle serviced**

- Electrical system checked
- Oil and filter changed



## Open Recalls

- No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact NISSAN or visit [Nissan's website](#).



## Stolen Vehicle Check

- This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2010 Dec 15		King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
2011 Jan 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	First Owner Reported
2011 Jan 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Jul 22	3,758 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
2011 Jul 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



	2011 Dec 22	7,809 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
	2012 Jan 24	8,102 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
	2012 Jun 28	12,288 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
	2012 Jul 13	13,071 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
	2012 Aug 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2012 Nov 23	16,496 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
	2013 Mar 19	21,178 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
	2013 Jul 12	25,374 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
	2013 Aug 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
	2013 Oct 8		Insurance Records British Columbia, Canada	Glass Record	\$587.46
	2013 Oct 25	29,777 MI	King Nissan SERVICE Bellingham, Washington, United States	Service Record	Vehicle serviced
	2014 Mar 11	33,908 MI	Wilson Motors Nissan Bellingham, Washington, United States	Service Record	Vehicle serviced
	2014 Jul 1	38,157 MI	Wilson Motors Nissan Bellingham, Washington, United States	Service Record	Vehicle serviced
	2014 Jul 14	38,536 MI	Wilson Motors Nissan Bellingham, Washington, United States	Service Record	Vehicle serviced
	2014 Aug 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

 2014 Oct 13	42,602 MI	Wilson Motors Nissan Bellingham, Washington, United States	Service Record	Vehicle serviced
 2014 Dec 31	45,588 MI	Wilson Motors Nissan Bellingham, Washington, United States	Service Record	Vehicle serviced
 2015 Apr 22	49,859 MI	Wilson Motors Nissan Bellingham, Washington, United States	Service Record	Vehicle serviced
2015 Aug 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jul 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jul 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Mar 3		Insurance Records British Columbia, Canada	Glass Record	\$408.10
2018 Jul 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jul 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Aug 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at [support.carfax.ca](http://support.carfax.ca)

**ICBC Disclaimer**

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.



The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

**CARFAX Canada No Reported Accidents™ Badge**

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

[Conditions of Use](#)

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



JN8AF5MV5BT010793





UNIT #8 - 20071 113B AVENUE  
 MAPLE RIDGE, BC V2X 0Z2  
 O: 604 460 7142  
 C: 604 721 1432  
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

**MULTI-POINT INSPECTION**

Name: CYPRESS AUTO BREAKER Year/Make/Model: 2011 NISSAN JUKE KMs: 112331  
 RO#: 2696 VIN: JNB0AF5MV5B1010793 License: \_\_\_\_\_

CHECKED AND OK       FUTURE ATTENTION       IMMEDIATE ATTENTION

INTERIOR/EXTERIOR			
NOTE ANY EXISTING BODY DAMAGE			
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD			
Oil Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

UNDER VEHICLE			
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

TIRES			
TREAD DEPTH			
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32"	<input type="checkbox"/> 2/32" or less	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"		
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 6/32"		
	Wear Pattern/ Damage	Air Pressure	Based on Mileage and Wear:
	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Alignment
	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE SHOULD BE	<input type="checkbox"/> Balance
	LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LF 28 35	<input type="checkbox"/> Rotation
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF 28 35	<input type="checkbox"/> New Tire	
		LR 28 35	
		RR 28 35	

BRAKES	
BRAKE PADS / SHOES	
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)	
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

COMMENTS
FRONT PADS 8mm
REAR PADS 9mm

INSPECTOR: JIM DATE: 1/14/2012



# Invoice

Ridge Motors Auto Repair and Tires  
 Unit 8 - 20071 113B Avenue  
 Maple Ridge, BC V2X 0Z2  
 (604) 460-7142

Date	Invoice #
1/14/2022	2696

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

Vehicle Description
2011 Nissan Juke

ODO IN	ODO OUT	Plate	VIN
112331			jn8af5mv5b1010793

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...		80.00	80.00	G
	P_Filter	air filter	15.00	15.00	G
		GST on sales	5.00%	4.75	
<b>Sales Tax Total</b>				\$4.75	
<b>Total</b>				\$99.75	

I herby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I herby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized herby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature \_\_\_\_\_





**JIFFY LUBE #1087**

20284 Dewdney Trunk Rd  
Maple Ridge, BC V2X 3E1  
(604) 465-0181

DATE 1/18/2022 12:56 PM  
TRANSACTION NO 22011800018439  
INVOICE NO 01087-18439  
VEHICLE ID BC-CYP

Customer Information		Service History		
Cypress Auto Brokers 11919 Maple Meadows Way MAPLE RIDGE, BC V2X 3M7 (604) 465-3313		<b>DATE</b>	<b>KILOMETERS</b>	<b>SERVICES</b>
		1/18/22	112345	CYP OF ATF
Vehicle Information				
2011 NISSAN/DATSUN JUKE 4cyl 1.6L FI Turbo VIN JN8AF5MV5BT010793 ALT ID		KILOMETERS 112345		
Employees		Service Comments		
<b>UPPER</b> PARI	<b>LOWER</b> PRAV	<b>COURTESY</b> PARI	<b>CASHIER</b> THANK YOU FOR YOUR BUSINESS!!!	
Service Checklist		Description	Qty.	Price
1. CHASSIS LUBRICATION	SEALED	CYP OIL PACKAGE	1.00	39.99
2. REAR DIFFERENTIAL	FULL	OF4622 OIL FILTER	1.00	0.00
3. TRANS/TRANSAXLE FLUID	REPLACED	PENNZOIL 5W30 OIL	4.50	0.00
4. LIGHT CHECK	CHECKED OK	FREE WASHER FLUID TOP UP	2.00	0.00
5. WIPER BLADES	CUST. OK'D	CVT TRANS. SERVICE	1.00	279.99
6. AIR FILTER	CHECKED	CVT TRANSMISSION FLUID	5.00	0.00
7. CABIN AIR FILTER	NO CHECK			
8. FUEL FILTER	NA	<b>SUBTOTAL</b>		<b>\$319.98</b>
9. POWER STEERING FLUID	N/A	(AIR)		-0.00
10. BRAKE FLUID	LEVEL OK	12.5% (125FLT)		-40.00
11. BATTERY	CHECKED OK	5% (5FLT)		-16.00
12. RADIATOR FLUID	FULL	<b>SALE</b>		<b>\$263.98</b>
13. WINDSHIELD WASH FLUID	ADDED			
14. TRANSFER CASE FLUID	N/A	GST TAX		13.20
15. FRT DIFFERENTIAL FLUID	N/A	PST TAX (Exempt 10144575)		0.00
16. CV BOOTS	CHECKED OK	<b>TOTAL</b>		<b>\$277.18</b>
17. SHOCKS/STRUTS	APPEARS O.K	VISA 7159 AUTH: 067851		277.18
18. TIRES	F__R__			
19. U JOINTS	N/A	<b>CHANGE</b>		<b>\$0.00</b>
20. BELTS AND HOSES	CHECK OK			
Warranty Statement				
This Jiffy Lube centre warrants all workmanship against failure for 7 days from the date of service. This warranty does not apply when the customer tampers with or alters the centre's products or alters the manufacturer's original equipment or when corrective action is taken without prior written approval from this Jiffy Lube service centre. The customer must have the limited warranty certificate and must retain a sample of the product(s) involved. <input type="checkbox"/> Oil Level Shown <input type="checkbox"/> Oil Filter Tight <input type="checkbox"/> Drain Plug Tight <input type="checkbox"/> Rear Diff Chk Plug <input type="checkbox"/> Front Diff Chk Plug <input type="checkbox"/> Transfer Case Chk Plug <input type="checkbox"/> Transmission Chk Plug				
y*OPEN SUN - SAT 9-6. ANY QUESTIONS CALL 604-465-0181 APPROPRIATE, WARRANTY-APPROVED PRODUCT MAY HAVE BEEN SUBSTITUTED.		<p><b>X</b></p> <p>Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.</p>		
<b>Recommend next service on 06/17/2022 or 115845 km.</b>				