


2009 FORD ECONOLINE E250 VAN

Van cargo | 8 Cylinders | Gas
1FTNE24L09DA23890
Country of Assembly: United States
Last Reported Odometer: 178,658 KM



Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



30 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of December 9, 2021 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2011 Apr 2	n/a	
	Police Reported Accident: Accident reported Damage to rear	
2014 Feb 14	Winnipeg, Manitoba, Canada	
	Estimate: Right Rear Estimate Date: n/a	\$11,639.69
	Claim: Collision Right Rear	Not Reported
	Damage Detail: Damage reported: severe damage Damage to right rear Damage to right side Damage to right front	
2015 Jun 2	Manitoba, Canada	
	Estimate: Front Estimate Date: n/a	\$113.00
	Claim: Non-collision Front	Not Reported



Registration

This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Alberta** with **Normal** branding.
- In the province of **Saskatchewan** with **Normal** branding.
- In the province of **Manitoba** with **Normal** branding.
- In the province of **British Columbia** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2010 Nov 30		Lakeview Shell Service Calgary, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tires rotated
2011 Mar 8		Lakeview Shell Service	Vehicle serviced <ul style="list-style-type: none"> Battery/charging system checked

		Calgary, Alberta, Canada	<ul style="list-style-type: none"> • Oil and filter changed • Tire condition and pressure checked • Air filter checked • Cooling system checked • Drivability/performance checked • Tires rotated
2014 May 6		Service Facility	Vehicle serviced <ul style="list-style-type: none"> • Air filter replaced • Oil and filter changed
2014 Jul 29		Service Facility	Vehicle serviced <ul style="list-style-type: none"> • Tire repaired
2014 Sep 10		Service Facility	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Exterior light bulb(s) replaced • Differential fluid flushed/changed • Rear differential fluid flushed/changed • Rear differential serviced
2014 Nov 12		Service Facility	Vehicle serviced <ul style="list-style-type: none"> • Tires rotated • Brakes serviced • Thermostat replaced • Rear brake pads replaced • Four wheel alignment performed • Oil and filter changed
2014 Dec 17		Service Facility	Vehicle serviced <ul style="list-style-type: none"> • Antifreeze/coolant flushed/changed
2015 Apr 14		Service Facility	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Tire repaired
2015 Apr 27		Service Facility	Vehicle serviced
2015 Jun 1		Service Facility	Vehicle serviced
2015 Oct 23	101,878 KM	Service Facility Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Air filter replaced
2015 Nov 14	103,349 KM	Service Facility Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Blower motor replaced/repared
2015 Dec 17		Service Facility Cambridge, Ontario, Canada	Vehicle serviced
2016 Jan 15		Service Facility Cambridge, Ontario, Canada	Vehicle serviced
2016 Jun 7	111,288 KM	Service Facility Calgary, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Front brake rotor(s) replaced • Front brake pads replaced • Wheel bearing seal replaced • Rear brake pads replaced

- Tire condition and pressure checked
- Parking brake shoes/pads replaced
- Brakes replaced
- Rear differential serviced

2016 Nov 24	122,086 KM	Kal Tire 85 Kelowna, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Maintenance reminder reset • Four wheel alignment performed • Brakes serviced • Safety inspection performed • Tire(s) replaced • Tire(s) balanced • Brakes checked • Front brake pads replaced • Front brake rotor(s) replaced • Air filter replaced • Ball joint(s) replaced • Alignment performed • Drive belt(s) replaced • Parking brake shoes/pads replaced • Emissions or safety inspection performed
2017 Jan 24	126,853 KM	Service Facility Kelowna, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Wiper(s) replaced • Tires rotated
2017 Feb 28	132,087 KM	Service Facility Vernon, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Tires rotated
2017 Mar 1		Sanderson Service Vernon, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tires rotated • Oil and filter changed
2017 Apr 13	139,722 KM	Sanderson Service Vernon, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Starter replaced • Air filter replaced • Oil and filter changed • Drive belt(s) replaced
2017 Jun 8	150,340 KM	Sanderson Service Vernon, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed
2017 Aug 22		Service Facility Cambridge, Ontario, Canada	Vehicle serviced
2017 Sep 19	155,603 KM	Service Facility Kelowna, British Columbia, Canada	Vehicle serviced
2017 Nov 24	156,744 KM	Service Facility Kelowna, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed
2018 Jun 27	159,990 KM	Service Facility Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed
2018 Nov 13	161,605 KM	Service Facility Delta, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Spark plug(s) replaced • Headlight bulb(s) replaced • Air filter replaced

- Wiper(s) replaced

2019 Apr 16	164,345 KM	Service Facility Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Brake fluid flushed/changed • Brakes checked • Tires rotated • Alignment performed • Wheel bearings repacked • Steering/suspension checked
2019 Oct 24	170,806 KM	Service Facility Victoria, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed
2020 Feb 1	173,239 KM	Service Facility Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Windshield washer checked • Antifreeze/coolant checked • Exterior light bulb(s) replaced • Headlight bulb(s) replaced • Blower motor resistor replaced • Oil and filter changed
2020 Jun 30	178,658 KM	Service Facility Abbotsford, British Columbia, Canada	Vehicle serviced



Open Recalls

- No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit [Ford's website](#).



Stolen Vehicle Check

- This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2009 Sep 24		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	First Owner Reported
2009 Sep 24		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Nov 2		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Nov 30		Lakeview Shell Service Calgary, Alberta, Canada	Service Record	Vehicle serviced

2010 Dec 16		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Mar 8		Lakeview Shell Service Calgary, Alberta, Canada	Service Record	Vehicle serviced
2011 Apr 2		Police Reported Accident	Police Report	Accident Reported: • Damage to rear
2011 Dec 8		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Aug 27		Motor Vehicle Dept. Saskatchewan, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Apr 9		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Apr 9		Motor Vehicle Dept. Manitoba, Canada	Previous use	Commercial
2013 Nov 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Nov 1		Motor Vehicle Dept. Manitoba, Canada	Previous use	Commercial
2014 Feb 14	58,764 KM	Winnipeg, Manitoba, Canada	Collision	Right Rear
2014 Feb 14			Damage Event	Damage reported: severe damage Damage to right rear Damage to right side Damage to right front
2014 Feb 14		Insurance Records Winnipeg, Manitoba, Canada	Collision	Estimate Date: n/a Right Rear
2014 May 6		Service Facility	Service Record	Vehicle serviced
2014 Jul 29		Service Facility	Service Record	Vehicle serviced
2014 Sep 10		Service Facility	Service Record	Vehicle serviced
2014 Nov 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Nov 1		Motor Vehicle Dept. Manitoba, Canada	Previous use	Commercial
2014 Nov 12		Service Facility	Service Record	Vehicle serviced
2014 Dec 17		Service Facility	Service Record	Vehicle serviced

2015 Apr 14		Service Facility	Service Record	Vehicle serviced
2015 Apr 27		Service Facility	Service Record	Vehicle serviced
2015 Jun 1		Service Facility	Service Record	Vehicle serviced
2015 Jun 2		Manitoba, Canada	Non-collision	Front
2015 Jun 2		Insurance Records Manitoba, Canada	Non-collision	Estimate Date: n/a Front
2015 Oct 23	101,878 KM	Service Facility Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Nov 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Nov 1		Motor Vehicle Dept. Manitoba, Canada	Previous use	Commercial
2015 Nov 14	103,349 KM	Service Facility Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Dec 17		Service Facility Cambridge, Ontario, Canada	Service Record	Vehicle serviced
2016 Jan 15		Service Facility Cambridge, Ontario, Canada	Service Record	Vehicle serviced
2016 May 3		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	New Owner Reported
2016 May 3		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2016 May 3		Motor Vehicle Dept. Manitoba, Canada	Previous use	Commercial
2016 Jun 7	111,288 KM	Service Facility Calgary, Alberta, Canada	Service Record	Vehicle serviced
2016 Nov 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Nov 1		Motor Vehicle Dept. Manitoba, Canada	Previous use	Commercial
2016 Nov 24	122,086 KM	Kal Tire 85 Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2016 Dec 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jan 24	126,853 KM	Service Facility	Service Record	Vehicle serviced

		Kelowna, British Columbia, Canada		
2017 Feb 28	132,087 KM	Service Facility Vernon, British Columbia, Canada	Service Record	Vehicle serviced
2017 Mar 1		Sanderson Service Vernon, British Columbia, Canada	Service Record	Vehicle serviced
2017 Apr 13	139,722 KM	Sanderson Service Vernon, British Columbia, Canada	Service Record	Vehicle serviced
2017 Jun 8	150,340 KM	Sanderson Service Vernon, British Columbia, Canada	Service Record	Vehicle serviced
2017 Jul 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Aug 22		Service Facility Cambridge, Ontario, Canada	Service Record	Vehicle serviced
2017 Sep 19	155,603 KM	Service Facility Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2017 Nov 24	156,744 KM	Service Facility Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2018 Jun 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jun 27	159,990 KM	Service Facility Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2018 Nov 13	161,605 KM	Service Facility Delta, British Columbia, Canada	Service Record	Vehicle serviced
2019 Apr 16	164,345 KM	Service Facility Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2019 Jun 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Oct 24	170,806 KM	Service Facility Victoria, British Columbia, Canada	Service Record	Vehicle serviced
2020 Feb 1	173,239 KM	Service Facility	Service Record	Vehicle serviced

		Abbotsford, British Columbia, Canada		
2020 Jun 30	178,658 KM	Service Facility Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2020 Jul 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jun 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.



1FTNE24L09DA23890



UNIT #8 - 20071 113B AVENUE
 MAPLE RIDGE, BC V2X 0Z2
 O: 604 460 7142
 C: 604 721 1432
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

express **MULTI-POINT INSPECTION**

Name: Auto Broker Year/Make/Model: 2009 E250 KMs: 178 714

RO#: 2694 VIN: 1FTNE24109DA23890 License: _____

■ CHECKED AND OK ■ FUTURE ATTENTION ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR			
NOTE ANY EXISTING BODY DAMAGE			
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

TIRES			
TREAD DEPTH			
■ 7/32" or greater	■ 3/32" to 6/32"	■ 2/32" or less	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<u>8</u> /32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<u>8</u> /32"
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<u>9</u> /32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<u>9</u> /32"
	Wear Pattern / Damage	Air Pressure	Based on Mileage and Wear:
	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Alignment
	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE SHOULD BE	<input type="checkbox"/> Balance
	LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LF <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Rotation
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> New Tire	
		LR <input type="checkbox"/> <input type="checkbox"/>	
		RR <input type="checkbox"/> <input type="checkbox"/>	

BATTERY			
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			

BRAKES			
BRAKE PADS / SHOES			
■ Over 5 mm (Disk) or 2 mm (Drum)			
■ 3-5 mm (Disk) or 1.01-2 mm (Drum)			
■ Less than 3 mm (Disk) or 1 mm (Drum)			
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			

UNDERHOOD			
Oil Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

UNDER VEHICLE			
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

COMMENTS
<u>FRONT PADS 12mm</u>
<u>REAR PADS 9mm</u>

INSPECTOR: JTM DATE: 1/12/2022

Ridge Motors Auto Repair and Tires
 Unit 8 - 20071 113B Avenue
 Maple Ridge, BC V2X 0Z2
 (604) 460-7142

Invoice

Date	Invoice #
1/12/2022	2694

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

Vehicle Description
2008 E250

ODO IN	ODO OUT	Plate	VIN
178714			1ftne24l09da23890

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...	GST on sales	80.00 5.00%	80.00 4.00	G
Sales Tax Total				\$4.00	
Total				\$84.00	

I herby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I herby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized herby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature _____