

Vehicle History Report + Lien Check (BC) #: 36599985  
Report Date: November 23, 2021 | 12:40 PM EST  
Report Status: Complete  
Reference:



# 2011 FORD RANGER SUPER CAB

Pickup | 6 Cylinders | Gas  
1FTKR4EE3BPA09702  
Country of Assembly: United States  
Last Reported Odometer: 948,464 KM

LIEN CHECK



No Lien Records Found



Accident/Damage Records Found



Last Registered In:  
British Columbia (Normal)



3 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



**This vehicle history report is based on information that was reported and available to CARFAX Canada as of November 23, 2021** (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report + Lien Check (BC)

## Lien Check

 No lien records found in **British Columbia**.

### How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

### CARFAX Canada Canadian Lien Guarantee




If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
 2012 Sep 14	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> REAR CENTER   Estimate Date: n/a	\$812.10
	<b>Claim:</b> COLLISION REAR CENTER	\$667.81
 2014 Oct 16	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> LEFT SIDE   Estimate Date: n/a	\$3,945.40
	<b>Claim:</b> COLLISION LEFT SIDE	\$3,621.68
 2017 May 25	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> FRONT CENTER   Estimate Date: n/a	\$2,950.85
	<b>Claim:</b> COLLISION FRONT CENTER	\$2,950.85

## Registration

 This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

1FTKR4EE3BPA09702



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 May 15	66,863 KM	Max Tire Centre And Auto Vancouver, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2015 Feb 3	62,237 KM	Service Facility Vancouver, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Alignment performed</li> <li>Oil and filter changed</li> <li>Tires rotated</li> </ul>
2017 Nov 8	948,464 KM	Big O Tire & Auto Service Langley, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Tire(s) balanced</li> </ul>



## Open Recalls

Recall #: 21S12 | DRIVER AIRBAG INFLATOR REPLACEMENT Recall Date: 2021 Mar 25

### Recall Description

DRIVER AIRBAG INFLATOR REPLACEMENT

### Remedy

FORD MOTOR COMPANY IS WORKING CLOSELY WITH ITS SUPPLIERS TO PRODUCE PARTS FOR THIS REPAIR. WHEN PARTS BECOME AVAILABLE IN SUFFICIENT QUANTITIES, OWNERS WILL BE NOTIFIED BY MAIL AND INSTRUCTED TO TAKE THEIR VEHICLE TO A FORD OR LINCOLN DEALER TO HAVE THE DRIVER AIRBAG INFLATOR REPLACED. THERE WILL BE NO CHARGE FOR THIS SERVICE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit [Ford's website](#).



## Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2011 Jan 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	First Owner Reported
2011 Jan 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

1FTKR4EE3BPA09702

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2011 Apr 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Oct 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Jul 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner Reported
2012 Jul 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Aug 1	39,574 KM	Auto Auction Vancouver, British Columbia, Canada	Auction Announcement	Rental
2012 Sep 14		Insurance Records British Columbia, Canada	COLLISION	REAR CENTER
2012 Sep 14		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a REAR CENTER
2012 Nov 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 May 15	66,863 KM	Max Tire Centre And Auto Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2013 Jul 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner Reported
2013 Jul 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Feb 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Jul 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Oct 16		Insurance Records British Columbia, Canada	COLLISION	LEFT SIDE
2014 Oct 16		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT SIDE
2015 Feb 3	62,237 KM	Service Facility Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2015 Aug 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Dec 18	73,800 KM	Independent Source Vancouver, British Columbia, Canada	Odometer reading	

1FTKR4EE3BPA09702

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Dec 19		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jun 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner Reported
2016 Jun 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jul 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner Reported
2016 Jul 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 May 25		Insurance Records British Columbia, Canada	COLLISION	FRONT CENTER
2017 May 25		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a FRONT CENTER
2017 Jul 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Nov 8	948,464 KM	Big O Tire & Auto Service Langley, British Columbia, Canada	Service Record	Vehicle serviced
2018 Jul 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jun 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Mar 25		FORD	Recall	Manufacturer Recall Issued Recall # 21512
2021 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner Reported
2021 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.





UNIT #8 - 20071 113B AVENUE  
 MAPLE RIDGE, BC V2X 0Z2  
 O: 604 460 7142  
 C: 604 721 1432  
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

**MULTI-POINT INSPECTION**

Name: CYPRESS AUTO BROKER Year/Make/Model: 2011 FORD RANGER KMs: 145465  
 RO#: 2631 VIN: 1FTRKEE2BPA09702 License: \_\_\_\_\_

■ CHECKED AND OK      ■ FUTURE ATTENTION      ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES																						
TREAD DEPTH																						
<span style="color: green;">■</span> 7/32" or greater	<span style="color: yellow;">■</span> 3/32" to 6/32" <span style="color: red;">■</span> 2/32" or less																					
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 10/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 10/32"																					
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"																					
	<table border="1"> <tr> <th colspan="2">Wear Pattern / Damage</th> <th colspan="2">Air Pressure</th> <th rowspan="5">Based on Mileage and Wear:</th> </tr> <tr> <td>LF</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> <td>BEFORE</td> <td>SHOULD BE</td> </tr> <tr> <td>RF</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> <td>27</td> <td>35</td> </tr> <tr> <td>LR</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> <td>27</td> <td>35</td> </tr> <tr> <td>RR</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> <td>27</td> <td>35</td> </tr> </table>	Wear Pattern / Damage		Air Pressure		Based on Mileage and Wear:	LF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE	SHOULD BE	RF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	27	35	LR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	27	35	RR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	27	35
	Wear Pattern / Damage		Air Pressure		Based on Mileage and Wear:																	
	LF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE	SHOULD BE																		
	RF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	27	35																		
	LR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	27	35																		
RR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	27	35																			
<input type="checkbox"/> Alignment <input type="checkbox"/> Balance <input type="checkbox"/> Rotation <input type="checkbox"/> New Tire																						

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

BRAKES	
BRAKE PADS / SHOES	
<span style="color: green;">■</span> Over 5 mm (Disk) or 2 mm (Drum)	
<span style="color: yellow;">■</span> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<span style="color: red;">■</span> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

COMMENTS
FRONT PADS 10mm
REAR 6mm

INSPECTOR: Jim      DATE: 12/7/2021

